

# Part 573 Safety Recall Report

# 25V-158

**Manufacturer Name :** Ford Motor Company**Submission Date :** MAR 14, 2025**NHTSA Recall No. :** 25V-158**Manufacturer Recall No. :** 25S26**Manufacturer Information :**

Manufacturer Name : Ford Motor Company

Address : 330 Town Center Drive

Suite 500 Dearborn MI 48126-2738

Company phone : 1-866-436-7332

**Population :**

Number of potentially involved : 12,833

Estimated percentage with defect : 100 %

**Vehicle Information :**

Vehicle 1 : 2021-2024 Ford Bronco Sport

Vehicle Type : LIGHT VEHICLES

Body Style :

Power Train : NR

**Descriptive Information :** The Ford process is capable of determining which software part numbers have been installed in production and service. Affected vehicles may not contain the remedy Powertrain Control Module and/or Body Control Module software for recall 24S24. These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service Information System (OASIS) database.

11,620 Bronco Sport vehicles are affected

Production Dates : JUL 08, 2020 - MAR 14, 2024

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 2 : 2022-2023 Ford Maverick

Vehicle Type : LIGHT VEHICLES

Body Style :

Power Train : NR

**Descriptive Information :** The Ford process is capable of determining which software part numbers have been installed in production and service. Affected vehicles may not contain the remedy Powertrain Control Module and/or Body Control Module software for recall 24S24. These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service Information System (OASIS) database. 1,213 Maverick vehicles are affected.

**Production Dates :** AUG 02, 2021 - AUG 22, 2022

**VIN Range 1 : Begin :**

NR

**End :** NR

Not sequential

## Description of Defect :

**Description of the Defect :** According to Ford's records, certain 2021 – 2024 model year Bronco Sport and 2022 – 2023 model year Maverick vehicles did not have the remedy for Safety Recall 24S24 / 24V267 installed correctly but were recorded as having the repair successfully completed. Because the correct software update remedy may not be installed on the vehicle, the underlying condition specified in Safety Recall 24S24 / 24V267 may still exist, and an insufficient calibration strategy for detecting sudden battery degradations during a drive cycle may lead to (a) a vehicle that is unable to restart after an auto start/stop event or (b) experience a stall while coming to a stop at low speed. Either may be accompanied by a loss of 12-volt accessories, including hazard lights.

FMVSS 1 : NR

FMVSS 2 : NR

**Description of the Safety Risk :** The underlying safety risk specified in Safety Recall 24S24 / 24V267 still exists on these specified vehicles. Ford described that safety risk as, "an insufficient calibration strategy for detecting sudden battery degradations during a drive cycle can lead to (a) a vehicle that is unable to restart after an auto start/stop event or (b) experience a stall while coming to a stop at low speed. Either may be accompanied by a loss of 12-volt accessories, including hazard lights. A loss of motive power can increase the risk of a crash."

**Description of the Cause :** The dealer instructions to complete the recall instruct the technician to upload the latest software using the service tool, which downloads the latest software from Ford for installation on the vehicle. For these vehicles, the software tool did not upload the correct software to the vehicle.

**Identification of Any Warning that can Occur :** None

## Involved Components :

Component Name 1 : Body Control Module

Component Description : Body Control Module Calibration - Bronco Sport

Component Part Number : M1PT-14F390-AC\*

Component Name 2 : Body Control Module

Component Description : Body Control Module Calibration – Maverick Gas

Component Part Number : NZ6T-14F390-AD\*

Component Name 3 : Body Control Module

Component Description : Body Control Module Calibration – Maverick HEV

Component Part Number : NZ6T-14F390-BD\*

Component Name 4 : Powertrain Control Module

Component Description : Powertrain Control Module Calibration – MY2021

Component Part Number : M1PA-12A650-\*

Component Name 5 : Powertrain Control Module

Component Description : Powertrain Control Module Calibration – MY2022

Component Part Number : N1PA-12A650-\*

Component Name 6 : Powertrain Control Module

Component Description : Powertrain Control Module Calibration – MY2023

Component Part Number : P1PA-12A650-\*

Component Name 7 : Powertrain Control Module

Component Description : Powertrain Control Module Calibration – MY2024

Component Part Number : R1PA-12A650-\*

## Supplier Identification :

### Component Manufacturer

Name : Ford Motor Company  
Address : 1 American Road  
Dearborn Michigan 48126  
Country : United States

## Chronology :

On November 26, 2024, an issue pertaining to incomplete software recall remedies was brought to Ford's Critical Concern Group (CCRG) for review. This issue was initially identified in a Quality Office forum, where an audit was requested for software part numbers applied to vehicles remedied under a sample of field service actions (FSAs). Initial review of three FSAs revealed insufficient data to confirm correct software application across all FSAs using the FDRS service tool. Further investigation was deemed necessary. In December 2024, a cross-functional team was formed to audit all software FSAs that used the FDRS service tool, with its first focus being on safety and compliance FSAs. Templates were created to track software lineage part numbers.

On December 19, 2024, Ford informed NHTSA of this concern -- the service tool data confirmed that the software state on the service tool at the time of installation matches the FSA software release for most vehicles. However, there are vehicles that do not have a match between the software state on the service tool and the FSA software release. Ford discussed with NHTSA its plan to address the mismatched vehicles. In January 2025, the cross-functional team created database records to store all software lineage part numbers for previously launched FSAs. The team then began auditing the current software level for every VIN repaired under several previously launched FSAs. On February 27, 2025, the cross-functional team completed the audit of 24S24 and brought the results to Ford's CCRG for review, concluding that 96% of the repairs conducted under 24S24 had the correct software installed. The team identified the specific vehicles that were recorded as receiving the remedy but have software that does not remedy the safety defect. On March 7, 2025, Ford's Field Review Committee reviewed the concern and approved a field action Ford is not aware of any reports of accident or injury related to this condition.

## Description of Remedy :

Description of Remedy Program : Owners will be notified by mail and instructed to take their vehicle to a Ford or Lincoln dealer to have the BCM and PCM calibrations updated. Then, the software part numbers will be validated using the Software Validation Form in the Professional Technician System before the FSA is closed. There will be no charge for this service. Ford provided the general reimbursement plan for the cost of remedies paid for by vehicle owners prior to notification of a safety recall in May 2023. Owners who have paid to have these repairs completed at their own expense may be eligible for reimbursement, in accordance with the recall reimbursement plan on file with NHTSA.

**How Remedy Component Differs from Recalled Component :** The software service package SRV0002082, SRV0002320, SRV0002321, SRV0002725, SRV0002727, SRV0003152, SRV0003153, SRV0002379, or SRV0002671 will have the intended remedy for 24S24 / 24V267.

**Identify How/When Recall Condition was Corrected in Production :** Not required per 49 Part 573.

### Recall Schedule :

**Description of Recall Schedule :** Notification to dealers is expected to occur on April 24, 2025. Mailing of owner notification letters is expected to begin April 24, 2025, and is expected to be completed by May 1, 2025.

**Planned Dealer Notification Date :** APR 24, 2025 - APR 24, 2025

**Planned Owner Notification Date :** APR 24, 2025 - MAY 01, 2025

\* NR - Not Reported