#### OMB Control No.: 2127-0004

# **Part 573 Safety Recall Report**

Manufacturer Name: Ford Motor Company Submission Date : MAR 14, 2025 NHTSA Recall No.: 25V-161 Manufacturer Recall No.: 25C08

### **Manufacturer Information :**

Manufacturer Name: Ford Motor Company Address: 330 Town Center Drive Suite 500 Dearborn MI 48126-2738 Company phone : 1-866-436-7332

### **Vehicle Information :**

Vehicle 1:	2025-2025 Ford Escape		
Vehicle Type :	LIGHT VEHICLES		
Body Style :			
Power Train :	2		
-	Ford's team reviewed supplier process and shipping records to determine the population of affected parts. These records indicate 27 affected rear-view cameras were introduced into production between $12/10/2024$ and $01/17/2025$ .		
	Affected vehicles are equipped with rear-view camera only systems. Vehicles equipped with 360-degree camera systems are not affected.		
	These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service Information System (OASIS) database		
	4,721 Ford Escape Units are affected.		
Production Dates : DEC 10, 2024 - JAN 17, 2025			
VIN Range 1 : Begin :NREnd :NRInterpretation			
Description of Noncompliance :			
Description of th Noncompliance	he The rear-view camera may display an inverted image when the vehicle is in e : reverse.		
<b>FMVSS</b>	1: 111 - Rear visibility		
FMVSS 2	2: NR		
Description of the Safety Risl	k: An inverted rear-view camera image will not provide the driver with a clear		
The information contained in this report was submitted pursuant to 49 CFR §573			

云 🔨 🔁

25V-161



Number of potentially involved : 4,721 Estimated percentage with defect : 1%

**Population :** 

### Part 573 Safety Recall Report

and accurate representation of the area behind the vehicle, increasing the risk of a crash.
Supplier produced a batch of rear-view cameras with Printed Circuit Board Assemblies (PCBAs) intended for a different model variant with incorrect image processing software.
g NA

#### **Involved Components :**

Component Name 1:	Rear View Camera (RVC)
Component Description :	Rear View Camera (RVC)
Component Part Number :	SV4T-19G490-DB

#### **Supplier Identification :**

#### **Component Manufacturer**

Name :Valeo Switches and Detection Systems, InAddress :Carr Matamoros Mazatlan KM 99<br/>Rio Bravo Foreign States 88920Country :Mexico

#### **Chronology** :

On February 13, 2025, an issue pertaining to inverted rear-view camera image was brought to Ford's Critical Concern Review Group (CCRG) for review by the Advanced Driver Assist Systems (ADAS) engineering team upon receipt of two warranty claims for this concern.

Ford's CCRG investigation reviewed actions taken at the supplier and Louisville Assembly Plant (LAP) in December 2024 – January 2025. During this period, LAP and the supplier identified rear-view camera parts for inspection and developed a sorting criteria. This investigation identified the population of affected cameras and the scope of potentially affected vehicles.

The CCRG reviewed the requirements of FMVSS No. 111 and also reviewed the sorting methodology at LAP to better understand the level of part traceability to determine the correct population scope. CCRG also conducted a read-across to ensure that no other vehicle lines were affected.

On March 7, 2025, Ford's Field Review Committee reviewed this concern and approved a field action.

The information contained in this report was submitted pursuant to 49 CFR §573

# Part 573 Safety Recall Report

Ford is not aware of any reports of accident or injury related to this condition.		
<b>Description of Remedy</b> :		
Description of Remedy Program :	Dealers will inspect the Rear View Camera (RVC) to determine if the image is inverted when the vehicle is in reverse. If the image is inverted, dealers will replace the RVC.	
How Remedy Component Differs from Recalled Component :	The remedy component (SV4T-19G490-DB) will display a properly oriented rear-view image.	
Identify How/When Recall Condition was Corrected in Production :	NR	
Recall Schedule :		
Description of Recall Schedule :	Notification to dealers is expected to occur on March 19, 2025. Mailing of owner notification letters is expected to begin April 28, 2025 and is expected to be completed by May 2, 2025.	
Planned Dealer Notification Date : Planned Owner Notification Date :	MAR 19, 2025 - MAR 19, 2025	

\* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573