OMB Control No.: 2127-0004

Part 573 Safety Recall Report

25V-178

Manufacturer Name: International Motors, LLC

Submission Date: MAR 20, 2025 NHTSA Recall No.: 25V-178 Manufacturer Recall No.: 25501



Manufacturer Information:

Manufacturer Name: International Motors, LLC

Address: 2701 Navistar Drive

Lisle IL 60532

Company phone: 331-332-1590

Population:

Number of potentially involved : 153 Estimated percentage with defect : 100%

Vehicle Information:

Vehicle 1: 2020-2025 International MV

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER Power Train : DIESEL

Descriptive Information: •

• The suspect population was identified by certain vehicles built 09/12/2018 thru 04/29/2024 with feature codes 0004JCC (Brake Rear Air Disc 18/24" sq Bk Chambers), 0004XCK (Rear Bendix Spicer ADB22X AB) and 0014UNA (Tandem RS

52" Intl).

The vehicles in the suspect population were identified by their build dates and feature codes: W/0004JCC (Brake Rear Air Disc 18/24" sq Bk Chambers), 0004XCK (Rear Bendix Spicer ADB22X AB), and W/0014UNA (Tandem RS 52" Intl). All other similar

vehicles, which are not subject to this recall, are excluded.

Production Dates: JUL 03, 2019 - OCT 28, 2024

VIN Range 1 : Begin : NR End : NR Not sequential

Identification of Any Warning NR

that can Occur:

	Vehicle 2:	2024-2024	International H	IV			
	Vehicle Type :	: BUSES, MEDIUM & HEAVY VEHICLES					
	Body Style :						
	Power Train:	NR					
	Descriptive Information:	• The	e suspect popula	ition was iden	ntified by	certain vehicles built 09/12/2018	
	•	thru 04/29/2024 with feature codes 0004JCC (Brake Rear Air Disc 18/24" sq Bk					
		Chambers), 0004XCK (Rear Bendix Spicer ADB22X AB) and 0014UNA (Tandem RS					
		52" Intl).					
		The vehicles in the suspect population were identified by their build dates and feature codes: W/0004JCC (Brake Rear Air Disc 18/24" sq Bk Chambers), 0004XCK (Rear					
		Bendix Spicer ADB22X AB), and W/0014UNA (Tandem RS 52" Intl). All other similar					
		vehicles, which are not subject to this recall, are excluded.					
	Production Dates :						
	VIN Range 1:	Begin :	NR	End:	NR	☐ Not sequential	
	Vohiclo 3:	2010-2010	International 7	400			
		nicle 3: 2019-2019 International 7400 e Type: BUSES, MEDIUM & HEAVY VEHICLES					
	V -	Body Style: OTHER					
	0 0	Power Train: DIESEL					
	Descriptive Information : • The suspect population was identified by certain vehicles built 09/12/2018						
	Descriptive information.	thru 04/29/2024 with feature codes 0004JCC (Brake Rear Air Disc 18/24" sq Bk					
		Chambers), 0004XCK (Rear Bendix Spicer ADB22X AB) and 0014UNA (Tandem RS					
		52" Intl).					
		The vehicles in the suspect population were identified by their build dates and feature					
		codes: W/0004JCC (Brake Rear Air Disc 18/24" sq Bk Chambers), 0004XCK (Rear Readily Spices ADR22V AR), and W/0014JNA (Tondom BS 52" Intl). All other cimiler					
		Bendix Spicer ADB22X AB), and W/0014UNA (Tandem RS 52" Intl). All other similar vehicles, which are not subject to this recall, are excluded.					
	Production Dates: SEP 12, 2018 - NOV 13, 2018						
	VIN Range 1:			End:	NR.	☐ Not sequential	
Description of Defect :							
Description of the Defect : • Within the normal maintenance intervals for air disc brake pad wear,							
	the caliper may contact a suspension spring or axle U-bolt.						
FMVSS 1: NR							
FMVSS 2: NR							
Ι	Description of the Safety Risk : • The contact may hinder caliper movement, causing only the inner pad						
	to deliver braking torque. Under certain braking conditions, this could extend						
			icle's stopping d	listance, poter	ntially ind	creasing the risk of a crash.	
	Description of the Caus	se: NR					

Involved Components:

Component Name 1: PLATE

Component Description: PLATE, TORQUE, REAR, BRAKE

Component Part Number: 3885192C91, 3885193C91

Supplier Identification:

Component Manufacturer

Name: NR Address: NR

NR

Country: NR

Chronology:

12/20/2024: International Field Service Team receives communication from a customer stating the rear calipers are contacting certain suspension components.

12/26/2024: International receives a Field Service Report indicating that a vehicle is experiencing contact between the brake caliper and suspension components causing uneven pad wear.

01/02/2025: International Field Service Team provides International Engineering the vehicle build configuration and photos of the brake caliper contacting suspension components.

1/10/2025: International Product Safety Office initiates investigation to review findings from the Field Service Report.

1/15/2025: International Engineering, Field Service, and Product Safety Office meet to review the failure mode and potential suspect population. International Engineering begins a CAD layout study to investigate the clearance between the rear caliper and the suspension components and its relation to pad wear.

01/16/2025 thru 3/3/2025: International Engineering performs CAD layout studies on multiple vehicle configurations and determined that an interference between the rear caliper and axle U-bolt/spring suspension can exist within the normal pad wear interval of the brake.

02/25/2025: International blocks the configuration from being a saleable option.

03/06/2025: International finalizes suspect population.

03/13/2025: International declares a safety recall.

Description of Remedy:

Description of Remedy Program: •

- Install new rear brake torque plates. Switch left and right rear air disc brake calipers on affected units and replace the brake pads.
- International's plan for reimbursement of pre-notification remedies, on file with NHTSA and dated 06/07/2024 applies and reimbursement instructions will be included in the customer notification.

How Remedy Component Differs • from Recalled Component :

• NA

Identify How/When Recall Condition • was Corrected in Production :

See chronology.

Recall Schedule:

Description of Recall Schedule: •

It is estimated that the dealer notification letter will be mailed by

5/12/2025.

It is estimated that the Customer notification letter will be mailed

by 5/19/2025.

Planned Dealer Notification Date : MAY 12, 2025 - MAY 12, 2025 Planned Owner Notification Date : MAY 19, 2025 - MAY 19, 2025

^{*} NR - Not Reported