The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety	<b>Recall Report</b>
-----------------	----------------------

Manufacturer Name : Altec Industries, Inc.

Submission Date : MAY 02, 2025

NHTSA Recall No.: 25V-288

Manufacturer Recall No.: CSN-3226

#### Manufacturer Information :

Manufacturer Name : Altec Industries, Inc. Address : 210 Inverness Center Drive Birmingham AL 35242 Company phone : 205 991 7733

## Vehicle Information :



Number of potentially involved : 2,461 Estimated percentage with defect : 25 %

**Population :** 

# 25V-288

# Part 573 Safety Recall Report

	22-2024 Altec TA	Series Aerial I	Device	
Vehicle Type :				
Body Style : Power Train : NI	,			
Descriptive Information : Th		on was determi	ned from a review	v of production records
Production Dates : JA				, or production records.
VIN Range 1: Beg			nd: NR	Not sequential
Vehicle 5: 20	22-2024 Altec AF	Series Forestr	y Body	
Vehicle Type :				
Body Style : Power Train : NI	)			
Descriptive Information : Th		n was dotormi	and from a ravia	w of production records
Production Dates : JA				w or production records.
VIN Range 1 : Beg			d: NR	☐ Not sequential
-	0			fuel line after it was moved allowing it to rub against
Description of the Defect : FMVSS 1 : FMVSS 2 :	during the PTO a other componen NR NR	and hydraulic p its.	ump installation,	allowing it to rub against
Description of the Defect : FMVSS 1 : FMVSS 2 : Description of the Safety Risk :	during the PTO a other component NR NR If a fuel line rubs cause a leak. A fu for a fire, which a to the operator of	and hydraulic p its. s against anothe iel leak could c could result in j	ump installation, er component, it o reate an environi property damage	allowing it to rub against
FMVSS 1 : FMVSS 2 : Description of the Safety Risk : Description of the Cause :	during the PTO a other componen NR NR If a fuel line rubs cause a leak. A fu for a fire, which to the operator of NR	and hydraulic p its. s against anothe iel leak could ci could result in pr others nearb	ump installation, er component, it e reate an environi property damage y.	, allowing it to rub against could damage the lines and nental risk and the potential e and serious injury or death
Description of the Defect : FMVSS 1 : FMVSS 2 : Description of the Safety Risk : Description of the Cause : Identification of Any Warning	during the PTO a other componen NR NR If a fuel line rubs cause a leak. A fu for a fire, which to the operator of NR	and hydraulic p its. s against anothe iel leak could c could result in or others nearb	ump installation, er component, it c reate an environi property damage y. d identify the cha	, allowing it to rub against could damage the lines and nental risk and the potential e and serious injury or death
Description of the Defect : FMVSS 1 : FMVSS 2 : Description of the Safety Risk : Description of the Cause : Identification of Any Warning	during the PTO a other componen NR NR If a fuel line rubs cause a leak. A fu for a fire, which a to the operator of NR A periodic DOT i	and hydraulic p its. s against anothe iel leak could c could result in or others nearb	ump installation, er component, it c reate an environi property damage y. d identify the cha	, allowing it to rub against could damage the lines and nental risk and the potential e and serious injury or death
Description of the Defect : FMVSS 1 : FMVSS 2 : Description of the Safety Risk : Description of the Cause : Identification of Any Warning that can Occur :	during the PTO a other componen NR NR If a fuel line rubs cause a leak. A fu for a fire, which to the operator of NR A periodic DOT i travel inspection	and hydraulic p its. s against anothe iel leak could cr could result in or others nearb inspection could in could identify	ump installation, er component, it c reate an environi property damage y. d identify the cha	, allowing it to rub against could damage the lines and nental risk and the potential e and serious injury or death
Description of the Defect : FMVSS 1 : FMVSS 2 : Description of the Safety Risk : Description of the Cause : Identification of Any Warning that can Occur : nvolved Components :	during the PTO a other componen NR NR If a fuel line rubs cause a leak. A fu for a fire, which to the operator of NR A periodic DOT i travel inspection	and hydraulic p its. s against anothe iel leak could ci could result in or others nearb inspection could n could identify	ump installation, er component, it c reate an environi property damage y. d identify the cha	, allowing it to rub against could damage the lines and nental risk and the potential e and serious injury or death

The information contained in this report was submitted pursuant to 49 CFR \$573

# **Supplier Identification :**

### **Component Manufacturer**

Name :Altec Industries Inc.Address :2106 S. Riverside Rd<br/>Saint Joseph Missouri 64507Country :United States

#### **Chronology** :

October 6, 2024, Altec received a report of a warranty claim from a customer that a fuel line was not secured and was rubbing on components and a root cause investigation was initiated. Altec found that a fuel line was not secured after the PTO and pump were installed on the specific unit.

October 22, 2024, Altec opened an investigation to determine the severity of the potential loose fuel lines, their detectability, and whether the issue could affect additional units in the field.

April 25, 2025, after reviewing the information collected in the investigation, Altec decided that certain units in the field could have a potential defect affecting vehicle safety.

No other warranty claims or field reports were identified in addition to the October warranty claim. There have been no accidents, injuries, or deaths related to this issue.

#### **Description of Remedy :**

Description of Remedy Program :	Altec will issue CSN 3226 to all affected owners requiring them to inspect the fuel line for proper securement. If the inspection finds that a fuel line is not secure, Altec will provide work instructions and a kit to secure the line properly. If damage is found at the inspection, the customer will be required to schedule service with the chassis OEM to have the damaged fuel line repaired. The recall remedy will be completed free of charge when presented for repair. The Altec Warranty Policy covers the recall remedy, including cases requiring reimbursement for the cost of obtaining a pre- notification or OEM remedy of the problem associated with this recall.
	The repair will secure the fuel lines, eliminating the potential for contact and rubbing against another component.
	Work instructions have been developed to instruct associates to secure the fuel lines when moving them for the installation of the PTO and pump. An inspection of the fuel lines has been added to the pre-delivery inspection checklinst and all units are inspected prior to shipment.

#### **Recall Schedule :**

Description of Recall Schedule :Altec will issue CSN-3226 to the owners of the affected units. Altec does<br/>not have a dealer network and issues letters to owners only.Planned Dealer Notification Date :JUN 30, 2025 - JUN 30, 2025Planned Owner Notification Date :JUN 30, 2025 - JUN 30, 2025

\* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573