



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

25V403

Manufacturer Name: Ford Motor Company

Submission Date: Dec 18, 2025

NHTSA Recall No.: 25V403

Manufacturer Recall No.: 25C28

Manufacturer Information

Population

Manufacturer Name: Ford Motor Company

Address: 20000 Rotunda Drive
Mezzanine
Dearborn MI, 48124

Total number of potentially involved: 48

Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2022-2022 LINCOLN NAVIGATOR

Product Category: Light Vehicles

Product Type: Multipurpose Passenger Vehicle

Fuel / Propulsion:

Production Dates: Jul 25, 2021 - Mar 17, 2022

Number of potentially involved: 48

Descriptive Information:

The Ford process is capable of determining which software part numbers have been installed in production and service. Affected vehicles do not contain the remedy the Headlamp Control Module software for recall 22C14.

These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service Information System (OASIS) database.

Defect / Noncompliance Description

Description of the defect or noncompliance:

According to Ford's records, certain 2022 MY Navigator vehicles did not have the remedy for Safety Recall 22C14 / 22V-455 installed correctly, but were recorded as having the repair successfully completed. Because the correct software update remedy may not be installed on the vehicle, the underlying condition specified in Safety Recall 22C14 / 22V-455 may still exist, the vehicles may exhibit a loss of side marker lamp function and daytime running lamps function (if equipped) which are regulated by FMVSS. Other nonregulated lighting features may also be affected; however, there is no loss of low beam, manual high beam, turn signal, hazard, or position functionality.

Part 573 Safety Recall Report

25V403

FMVSS1: 108 - Lamps, reflective devices, and assoc. Equipment

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

The underlying safety risk specified in Safety Recall 22C14 / 22V-455 still exists on these specified vehicles. Ford described that safety risk as, "A loss of function to the vehicle's side marker lamps and/or daytime running lamps (if equipped) that are regulated by FMVSS, could increase the risk of a crash."

Description of the cause:

The dealer instructions to complete the recall instruct the technician to upload the latest software using the service tool, which downloads the latest software from Ford for installation on the vehicle. For these vehicles, the software tool did not upload the correct software to the vehicle.

An audit dashboard bug, discovered in November 2025, incorrectly used engineering-entered values in the "fixed vehicle" calculation. This led to misidentifying certain vehicles as repaired that were not repaired.

Identification of any warning that can occur:

None

Component Manufacturer

Tier of Supplier:

Supplier Type: OEM

Name: Ford Motor Company

Address: 1 American Road
Dearborn MI, 48126

Country: United States

Involved Components

Component Name 1: Headlamp Control Module

Component Description: Headlamp Control Module

Component Part Number: NL1B-14D063-A

Chronology

Part 573 Safety Recall Report

25V403

On **November 26, 2024**, an issue pertaining to incomplete software recall remedies was brought to Ford's Critical Concern Group (CCRG) for review. This issue was initially identified in a Quality Office forum, where an audit was requested for software part numbers applied to vehicles remedied under a sample of field service actions (FSAs). Initial review of three FSAs revealed insufficient data to confirm correct software application across all FSAs using the FDRS service tool. Further investigation was deemed necessary.

In **December 2024**, a cross-functional team was formed to audit all software FSAs that used the FDRS service tool, with its first focus being on safety and compliance FSAs. Templates were created to track software lineage part numbers.

On **December 19, 2024**, Ford informed NHTSA of this concern -- the service tool data confirmed that the software state on the service tool at the time of installation matches the FSA software release for most vehicles. However, there are vehicles that do not have a match between the software state on the service tool and the FSA software release. Ford discussed with NHTSA its plan to address the mismatched vehicles.

In **January 2025**, the cross-functional team created database records to store all software lineage part numbers for previously launched FSAs. The team then began auditing the current software level for every VIN repaired under several previously launched FSAs.

On **June 2, 2025**, the cross-functional team completed the audit of 22C14 and brought the results to Ford's CCRG for review, concluding that 99.2% of the repairs conducted under 22C14 had the correct software installed. The team identified the specific vehicles that were recorded as receiving the remedy, but have software that does not remedy the noncompliance.

On **June 6, 2025**, Ford's Field Review Committee reviewed the concern and approved a field action

On **November 17, 2025**, a bug in the audit dashboard logic for FSA audits was discovered. This bug incorrectly utilized engineering-entered values in the "fixed vehicle" calculation, leading to the misidentification of vehicles as fixed that should not have been. This error resulted in an inflated "fixed" population. A review of the vehicles shown as repaired was conducted after this bug was identified resulting in the identification of VINs incorrectly closed as repaired without receiving the FSA remedy.

On **December 11, 2025**, Ford's Field Review Committee reviewed the concern and approved an amendment to this field action.

Ford is not aware of any reports of accident or injury related to this condition.

Related NHTSA Recall Number: 22V455

Description of Remedy

Remedy Type: Software

Consumer Advisories: Do Not Drive Park Outside

Description of remedy program:

Owners will be notified by mail and instructed to take their vehicle to a Ford or Lincoln dealer to have the Headlamp Control Module software updated. Then, the software part numbers will be validated using the Software Validation Form in the Professional Technician System before the FSA is closed. There will be no charge for this service.

Part 573 Safety Recall Report

25V403

Ford provided the general reimbursement plan for the cost of remedies paid for by vehicle owners prior to notification of a safety recall in May 2023. Owners who have paid to have these repairs completed at their own expense may be eligible for reimbursement, in accordance with the recall reimbursement plan on file with NHTSA.

How remedy component differs from recalled component:

The software service package will have the intended remedy for 22C14 / 22V-455

Identify how/when recall condition was corrected in production:

Not required per 49 Part 573.

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Recall Schedule

Description of recall schedule:

Notification to dealers is expected to occur on July 14, 2025. Mailing of remedy owner notification letters is expected to begin July 14, 2025 and is expected to be completed by July 21, 2025. The date VINs are planned to be searchable is July 14, 2025.

Planned Dealer Notification Date: Jul 14, 2025 - Jul 14, 2025

No Dealers

Planned Interim Owner Notification Date:

No Owners

Planned Remedy Owner Notification Date: Jul 14, 2025 - Jul 21, 2025

Phased Recall

Date when VIN will be searchable: Jul 14, 2025