



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

25V412

Manufacturer Name: Bontrager Outdoors

Submission Date: Jul 08, 2025

NHTSA Recall No.: 25V412

Manufacturer Recall No.:

Manufacturer Information

Population

Manufacturer Name: Bontrager Outdoors

Address: 0925 North State RD 5
Shipshewana IN, 46565

Total number of potentially involved: 24

Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2025-2025 Skinny Guy Campers Armor 7 LT

Product Category:

Product Type:

Fuel / Propulsion:

Production Dates: Aug 16, 2024 - May 16, 2025

Number of potentially involved: 9

Descriptive Information:

During the first production run of this product, it came to our attention that the proper carbon monoxide detector was not installed in the camper. We identified these units when our Quality Control personnel alerted management about the missing component. Any camper manufactured after May 16th, 2025, has the proper detector installed on the production line.

Vehicle 2: 2025-2025 Bontrager Outdoors 7 Rod

Product Category:

Product Type:

Fuel / Propulsion:

Production Dates: Jul 30, 2024 - May 16, 2025

Number of potentially involved: 15

Descriptive Information:

During the first production run of this product, it came to our attention that the proper carbon monoxide detector was not installed in the campers. We identified these units when our Quality Control personnel alerted management about the missing component. Any camper manufactured after May 16th, 2025, has the proper detector installed on the production line.

Part 573 Safety Recall Report

25V412

Defect / Noncompliance Description

Description of the defect or noncompliance:

Production failed to install carbon monoxide detectors in the camper. Their reasoning was there no LP gas source to generate the risk.

FMVSS1:

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

The owner could suffer possible side effects of inhaling carbon monoxide.

Description of the cause:

Identification of any warning that can occur:

Component Manufacturer

Tier of Supplier:

Supplier Type:

Name:

Address:

Country:

Involved Components

Component Name 1: BRK CO250RVA

Component Description: Carbon Monoxide detector

Component Part Number: 95-10000-A

Chronology

No real event preceding this decision, following RVIA Guideline is how we put this back into compliance. We had a change in the Quality Control department and the new QC person spotted the issue.

Part 573 Safety Recall Report

25V412

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Repair

Consumer Advisories: Do Not Drive Park Outside

Description of remedy program:

We are allotting time for each Dealer to install these detectors for the retail customers and their stock units.

How remedy component differs from recalled component:

There was no Carbon Monoxide detector, so we are supplying the detectors and the labor hours to remediate the issue.

Identify how/when recall condition was corrected in production:

Any unit produced after May 16th 2025 will have the detector installed by default.

Reimbursement Plan

Description of reimbursement program:

1. Repair time .2 hours
2. We are sending the detector to honor the warranty/nonconformance.

Period of reimbursement:

Until all units are completed.

Costs to be reimbursed:

Labor cost of .2 hours depending on individual shop rates.

Address for reimbursement claims:

925 State Road 5
Shipshewana IN, 46565

Recall Schedule

Description of recall schedule:

1. Affected Dealer get the first round of letters.

Part 573 Safety Recall Report**25V412**

2. Retail customers will get their letters one week after.

Planned Dealer Notification Date:

No Dealers

Planned Interim Owner Notification Date:

No Owners

Planned Remedy Owner Notification Date:

Phased Recall

Date when VIN will be searchable: