



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

25V442

Manufacturer Name: Ford Motor Company

Submission Date: Dec 18, 2025

NHTSA Recall No.: 25V442

Manufacturer Recall No.: 25S72

Manufacturer Information

Population

Manufacturer Name: Ford Motor Company

Address: 20000 Rotunda Drive
Mezzanine
Dearborn MI, 48124

Total number of potentially involved: 200,237

Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2019-2020 LINCOLN MKX

Product Category: Light Vehicles

Product Type: Multipurpose Passenger Vehicle

Fuel / Propulsion:

Production Dates: Sep 06, 2018 - Dec 21, 2020

Number of potentially involved:

Descriptive Information:

The Ford process is capable of determining which software part numbers have been installed in production and service. Affected vehicles contain SYNC 3.2 R10 RC1 infotainment software. These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service Information System (OASIS) database.

Vehicle 2: 2019-2023 FORD RANGER

Product Category: Light Vehicles

Product Type:

Fuel / Propulsion: Spark Ignition Fuel

Production Dates: Jul 13, 2018 - Jun 28, 2023

Number of potentially involved: 11,865

Descriptive Information:

The Ford process is capable of determining which software part numbers have been installed in production and service. Affected vehicles contain SYNC 3.2 R10 RC1 infotainment software.

Part 573 Safety Recall Report

25V442

These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service Information System (OASIS) database.

Vehicle 3: 2020-2021 FORD ECOSPORT**Product Category:** Light Vehicles**Product Type:****Fuel / Propulsion:** Spark Ignition Fuel**Production Dates:** Aug 12, 2019 - Dec 09, 2021**Number of potentially involved:** 12**Descriptive Information:**

The Ford process is capable of determining which software part numbers have been installed in production and service. Affected vehicles contain SYNC 3.2 R10 RC1 infotainment software.

These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service Information System (OASIS) database.

Vehicle 4: 2019-2020 LINCOLN MKZ**Product Category:** Light Vehicles**Product Type:****Fuel / Propulsion:** Spark Ignition Fuel**Production Dates:** Aug 21, 2018 - Jul 31, 2020**Number of potentially involved:** 479**Descriptive Information:**

The Ford process is capable of determining which software part numbers have been installed in production and service. Affected vehicles contain SYNC 3.2 R10 RC1 infotainment software.

These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service Information System (OASIS) database.

Vehicle 5: 2020-2021 LINCOLN NAVIGATOR**Product Category:** Light Vehicles**Product Type:****Fuel / Propulsion:** Spark Ignition Fuel

Part 573 Safety Recall Report

25V442**Production Dates:** Oct 14, 2019 - Dec 12, 2021**Number of potentially involved:** 512**Descriptive Information:**

The Ford process is capable of determining which software part numbers have been installed in production and service. Affected vehicles contain SYNC 3.2 R10 RC1 infotainment software.

These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service Information System (OASIS) database.

Vehicle 6: 2019-2023 FORD MUSTANG**Product Category:** Light Vehicles**Product Type:****Fuel / Propulsion:** Spark Ignition Fuel**Production Dates:** May 14, 2018 - Apr 05, 2023**Number of potentially involved:** 4,366**Descriptive Information:**

The Ford process is capable of determining which software part numbers have been installed in production and service. Affected vehicles contain SYNC 3.2 R10 RC1 infotainment software.

These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service Information System (OASIS) database.

Vehicle 7: 2019-2020 FORD FUSION**Product Category:** Light Vehicles**Product Type:****Fuel / Propulsion:** Spark Ignition Fuel**Production Dates:** Aug 21, 2018 - Jul 31, 2020**Number of potentially involved:** 5,738**Descriptive Information:**

The Ford process is capable of determining which software part numbers have been installed in production and service. Affected vehicles contain SYNC 3.2 R10 RC1 infotainment software.

These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service Information System (OASIS) database.

Part 573 Safety Recall Report**25V442****Vehicle 8:** 2021-2024 FORD BRONCO SPORT**Product Category:** Light Vehicles**Product Type:****Fuel / Propulsion:** Spark Ignition Fuel**Production Dates:** Mar 13, 2020 - Nov 04, 2024**Number of potentially involved:** 34,601**Descriptive Information:**

The Ford process is capable of determining which software part numbers have been installed in production and service. Affected vehicles contain SYNC 3.2 R10 RC1 infotainment software.

These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service Information System (OASIS) database.

Vehicle 9: 2020-2021 FORD EXPEDITION**Product Category:** Light Vehicles**Product Type:****Fuel / Propulsion:** Spark Ignition Fuel**Production Dates:** Jul 16, 2019 - Dec 23, 2021**Number of potentially involved:** 3,013**Descriptive Information:**

The Ford process is capable of determining which software part numbers have been installed in production and service. Affected vehicles contain SYNC 3.2 R10 RC1 infotainment software.

These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service Information System (OASIS) database.

Vehicle 10: 2020-2023 LINCOLN AVIATOR**Product Category:** Light Vehicles**Product Type:****Fuel / Propulsion:** Spark Ignition Fuel**Production Dates:** Apr 25, 2019 - Nov 08, 2023**Number of potentially involved:** 3,535**Descriptive Information:**

The Ford process is capable of determining which software part numbers have been installed in production and service. Affected vehicles contain SYNC 3.2 R10 RC1 infotainment software.

Part 573 Safety Recall Report

25V442

These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service Information System (OASIS) database.

Vehicle 11: 2020-2024 FORD EXPLORER

Product Category: Light Vehicles

Product Type:

Fuel / Propulsion: Spark Ignition Fuel

Production Dates: Feb 06, 2019 - Dec 22, 2023

Number of potentially involved: 57,782

Descriptive Information:

The Ford process is capable of determining which software part numbers have been installed in production and service. Affected vehicles contain SYNC 3.2 R10 RC1 infotainment software.

These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service Information System (OASIS) database.

Vehicle 12: 2018-2022 FORD TRANSIT CONNECT

Product Category: Buses, Medium & Heavy Vehicles

Product Type:

Fuel / Propulsion: Spark Ignition Fuel

Production Dates: Jul 25, 2018 - Jan 18, 2022

Number of potentially involved: 955

Descriptive Information:

The Ford process is capable of determining which software part numbers have been installed in production and service. Affected vehicles contain SYNC 3.2 R10 RC1 infotainment software.

These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service Information System (OASIS) database.

Vehicle 13: 2019-2020 FORD EDGE

Product Category: Light Vehicles

Product Type:

Fuel / Propulsion: Spark Ignition Fuel

Part 573 Safety Recall Report**25V442****Production Dates:** Aug 02, 2018 - Dec 21, 2020**Number of potentially involved:** 4,916**Descriptive Information:**

The Ford process is capable of determining which software part numbers have been installed in production and service. Affected vehicles contain SYNC 3.2 R10 RC1 infotainment software.

These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service Information System (OASIS) database.

Vehicle 14: 2020-2022 LINCOLN CORSAIR**Product Category:** Light Vehicles**Product Type:****Fuel / Propulsion:** Spark Ignition Fuel**Production Dates:** Feb 12, 2019 - Dec 08, 2022**Number of potentially involved:** 856**Descriptive Information:**

The Ford process is capable of determining which software part numbers have been installed in production and service. Affected vehicles contain SYNC 3.2 R10 RC1 infotainment software.

These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service Information System (OASIS) database.

Vehicle 15: 2020-2022 FORD ESCAPE**Product Category:** Light Vehicles**Product Type:****Fuel / Propulsion:** Spark Ignition Fuel**Production Dates:** May 17, 2019 - Dec 09, 2022**Number of potentially involved:** 6,812**Descriptive Information:**

The Ford process is capable of determining which software part numbers have been installed in production and service. Affected vehicles contain SYNC 3.2 R10 RC1 infotainment software.

These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service Information System (OASIS) database.

Part 573 Safety Recall Report**25V442****Vehicle 16:** 2019-2020 FORD F-150**Product Category:** Light Vehicles**Product Type:****Fuel / Propulsion:** Spark Ignition Fuel**Production Dates:** Jul 23, 2018 - Oct 11, 2020**Number of potentially involved:** 22,388**Descriptive Information:**

The Ford process is capable of determining which software part numbers have been installed in production and service. Affected vehicles contain SYNC 3.2 R10 RC1 infotainment software.

These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service Information System (OASIS) database.

Vehicle 17: 2022-2024 FORD MAVERICK**Product Category:** Light Vehicles**Product Type:****Fuel / Propulsion:** Spark Ignition Fuel**Production Dates:** Jul 29, 2021 - Jan 08, 2024**Number of potentially involved:** 5,122**Descriptive Information:**

The Ford process is capable of determining which software part numbers have been installed in production and service. Affected vehicles contain SYNC 3.2 R10 RC1 infotainment software.

These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service Information System (OASIS) database.

Vehicle 18: 2019-2020 LINCOLN NAUTILUS**Product Category:** Light Vehicles**Product Type:****Fuel / Propulsion:** Spark Ignition Fuel**Production Dates:** Sep 06, 2018 - Dec 21, 2020**Number of potentially involved:** 926**Descriptive Information:**

The Ford process is capable of determining which software part numbers have been installed in production and service. Affected vehicles contain SYNC 3.2 R10 RC1 infotainment software.

Part 573 Safety Recall Report

25V442

These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service Information System (OASIS) database.

Vehicle 19: 2020-2022 FORD F-250 SD

Product Category: Light Vehicles

Product Type:

Fuel / Propulsion: Spark Ignition Fuel

Production Dates: Aug 02, 2019 - Dec 22, 2022

Number of potentially involved: 8,137

Descriptive Information:

The Ford process is capable of determining which software part numbers have been installed in production and service. Affected vehicles contain SYNC 3.2 R10 RC1 infotainment software.

These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service Information System (OASIS) database.

Vehicle 20: 2019-2020 LINCOLN CONTINENTAL

Product Category: Light Vehicles

Product Type:

Fuel / Propulsion: Spark Ignition Fuel

Production Dates: Sep 18, 2018 - Nov 25, 2020

Number of potentially involved: 180

Descriptive Information:

The Ford process is capable of determining which software part numbers have been installed in production and service. Affected vehicles contain SYNC 3.2 R10 RC1 infotainment software.

These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service Information System (OASIS) database.

Vehicle 21: 2020-2023 FORD TRANSIT

Product Category: Buses, Medium & Heavy Vehicles

Product Type:

Fuel / Propulsion: Spark Ignition Fuel

Part 573 Safety Recall Report

25V442

Production Dates: Jul 25, 2019 - Jan 18, 2022

Number of potentially involved: 28,042

Descriptive Information:

The Ford process is capable of determining which software part numbers have been installed in production and service. Affected vehicles contain SYNC 3.2 R10 RC1 infotainment software.

These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service Information System (OASIS) database.

Defect / Noncompliance Description

Description of the defect or noncompliance:

An error in the SYNC software can cause system instability concerns and/or a failure to preserve certain settings across ignition cycles. This may result in an intermittent blank image while in reverse or rear-view image remaining on display after reverse driving has ended. Other non-safety related symptoms may be present such as a black infotainment screen, incorrect language setting, and/or potential inability to perform software updates.

FMVSS1:

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

A rear-view camera that intermittently displays a blank image while in reverse can reduce the driver's view of what is behind the vehicle, increasing the risk of a crash. A rear-view camera that remains on after the backing event has ended can distract the driver, increasing the risk of a crash.

Description of the cause:

Short ignition cycles may cause interference with SYNC software log file compression routines leading to potential consumption of all the free space on the SYNC APIM (Accessory Protocol Interface Module). Once the space is consumed, the system is no longer able to write new files to the APIM and will exhibit stability of image issues.

Some VINs that were shown to have been repaired under Customer Satisfaction Field Service Action 24B47 were found to have not received the remedy. These VINs were excluded from the original 25S72 population.

Identification of any warning that can occur:

Component Manufacturer

Tier of Supplier:

Part 573 Safety Recall Report

25V442

Supplier Type:

Name: Ford Motor Company

Address: 1 American Rd.
Dearborn MI, 48126

Country: United States

Involved Components

Component Name 1: SYNC 3 Software

Component Description: SYNC 3 software version R10 RC1

Component Part Number: NU5T-14G381-AB

Chronology

On **January 17, 2025**, the National Highway Traffic Safety Administration (NHTSA) Office of Defect Investigations (ODI) contacted Ford about a Vehicle Owner Questionnaire (VOQ) trend associated with rear-view camera image complaints on 2021-2023 Bronco Sport vehicles.

On **March 27, 2025**, this issue was brought to Ford's Critical Concern Review Group (CCRG) for review.

From **April 2025 to May 2025**, Ford's CCRG performed an analysis of the warranty data for all rear-view camera system components. This review identified an increase in Accessory Protocol Image Module (APIM) and rear-view image complaints for vehicles produced between March 2023 and November 2023. These production dates coincide with the introduction of SYNC3 software release R10 RC1. Ford's review of VOQs and other service records indicated most vehicles were repaired with a SYNC3 software update and believes that this R10 RC1 software is a causal factor to those concerns.

Ford's CCRG and In-Vehicle Infotainment (IVI) conducted additional software reviews to understand if the R10 RC1 issues can affect the rear-view camera image. IVI determined that once the system is out of space it is possible for a configuration file write to fail in a manner which causes the infotainment system to "lock up," preventing correct Rearview Camera (RVC) transitions in certain, rare instances. The IVI team conducted testing and was able to replicate the condition.

A software update was released to production in December 2023 and to the field in August 2024 as part of Customer Satisfaction Field Service Action (FSA) 24B47, which contained other software improvements, and appears to correct the "lock up" issue.

Ford is aware of 1326 warranty claims potentially related to this condition received between 6/13/2023 and 5/23/2025. This includes claims that were repaired under 24B47.

On **June 20, 2025**, Ford's Field Review Committee reviewed the concern and approved a field action.

In **August 2024**, the customer satisfaction program 24B47 was launched. Vehicles in this program were later migrated to safety FSA 25S72. Vehicles already repaired under 24B47 were not added to 25S72 as they had already received updated software. A review of the vehicles repaired as part of 24B47 found 5 VINs in Canada that had not received the remedy and had been excluded from the original 25S72 population.

On **December 11, 2025**, Ford's Field Review Committee reviewed the concern and approved an amendment to this field action.

Part 573 Safety Recall Report

25V442

Ford is not aware of any injuries associated with this condition. Ford is aware of three minor crashes that may be attributed to this concern

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Software

Consumer Advisories: Do Not Drive Park Outside

Description of remedy program:

Owners will be notified by mail and instructed to take their vehicle to a Ford or Lincoln dealer to have an updated version of SYNC 3 software flashed into their Accessory Protocol Interface Module (APIM). There will be no charge for this service.

How remedy component differs from recalled component:

All software files superseding R10 RC1 SYNC 3 level software (NU5T-14G381-AB) contain overrun containment-enabled software.

Identify how/when recall condition was corrected in production:

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Recall Schedule

Description of recall schedule:

Notification to dealers is expected to occur on July 1, 2025. Mailing of remedy owner notification letters is expected to begin July 28, 2025 and is expected to be completed by August 1, 2025. The date VINs are planned to be searchable is July 1, 2025.

Planned Dealer Notification Date: Jul 01, 2025 - Jul 01, 2025 No Dealers

Planned Interim Owner Notification Date: No Owners

Planned Remedy Owner Notification Date: Aug 25, 2025 - Aug 29, 2025 Phased Recall

Part 573 Safety Recall Report

25V442

Date when VIN will be searchable: Jul 01, 2025