

U.S. Department of Transportation

National Highway Traffic Safety Administration

## Part 573 Safety Recall Report

25V582

Manufacturer Name: Honda (American Honda Motor Co.)

Submission Date: Sep 05, 2025

NHTSA Recall No.: 25V582

Manufacturer Recall No.: GMS

#### **Manufacturer Information**

#### **Population**

Manufacturer Name: Honda (American Honda

Motor Co.)

Address: 1919 Torrance Blvd.

Torrance CA, 90501

Total number of potentially involved: 17,334

Estimated percentage with defect: 0.3%

#### Vehicle Information

Vehicle 1: 2025-2025 ACURA RDX

Product Category: Light Vehicles

**Product Type:** Multipurpose Passenger Vehicle

Fuel / Propulsion: Compression Ignition Fuel

**Production Dates:** Jan 23, 2024 - Aug 18, 2025

Number of potentially involved: 17,334

Descriptive Information:

The recall population was determined based on manufacturing records. The production range reflects all possible vehicles that could experience the problem.

### **Defect / Noncompliance Description**

#### Description of the defect or noncompliance:

An improper electronic power steering (EPS) software calibration may cause the EPS system to enter failsafe mode under certain vehicle operating conditions.

FMVSS1:

FMVSS2:

#### Description of the safety risk, including crash, fire, death, injury:

If the EPS system enters failsafe mode, power steering assist is disabled, and the EPS warning indicators illuminate in the instrument cluster. Without power assist, steering effort increases, which may reduce vehicle controllability, increasing the risk of a crash or injury.

## Part 573 Safety Recall Report

25V582

#### Description of the cause:

During development of the 2025 Acura RDX EPS software to comply with California Idle Stop OBD requirements, the Tier 2 supplier inadvertently set the EPS target returnability Integrated Dynamics System (IDS) gain to an incorrect value. Under certain driving conditions—specifically, when the driver applies a sharp steering input during a turn while the IDS is in Comfort mode and the Lane Keeping Assist System (LKAS) is active—this calibration can cause the EPS target returnability output to exceed the Safety Barrier threshold. When this occurs, the system may incorrectly detect a fault and enter failsafe mode.

#### Identification of any warning that can occur:

#### **Component Manufacturer**

**Tier of Supplier:** Tier 1 **Supplier Type:** OEM

Name: JTEKT North America Corporation

Address: 55 EXCELLENCE WAY

VONORE TN, 37885-9637

**Country:** United States

#### **Involved Components**

Component Name 1: MCU COMP, EPS
Component Description: MCU COMP, EPS
Component Part Number: 53660-TJB-A62

Component Name 2: MCU COMP, EPS
Component Description: MCU COMP, EPS
Component Part Number: 53660-TJB-A72

Component Name 3: MCU COMP, EPS
Component Description: MCU COMP, EPS
Component Part Number: 53660-TJB-A82

#### Chronology

# Part 573 Safety Recall Report

25V582

October 2024
Honda received the initial complaint of the issue and began to investigate.
March 2025
Honda continued to investigate and analyze the issue.
M 00 0005
May 29, 2025
Through an investigation at a dealership, the customer driving mode was identified as a potential variable of the issue.
July 21, 2025
Honda and the supplier continued to investigate and analyze the issue.
Themad and the cappilor continued to invoctigate and analyze the local.
August 19, 2025
After receiving additional information and completion of further investigation, Honda considered the issue may present a potential safety risk.
record may procent a potential carety from
August 28, 2025
Honda determined that a defect related to motor vehicle safety existed and decided to conduct a safety recall.
As of August 28, 2025, Honda has had 84 warranty claims and no reports of an injury or death related to
this issue from August 14, 2024, through August 28, 2025.
Related NHTSA Recall Number:
Related NHTSA Recall Nulliber.
Description of Remedy
Remedy Type: Repair
Consumer Advisories:   Do Not Drive Park Outside

### Description of remedy program:

Registered owners of all affected vehicles will be contacted by mail and asked to take their vehicle to an authorized Acura dealer. The dealer will reprogram the EPS memory layout with an improved software.

How remedy component differs from recalled component:

# Part 573 Safety Recall Report

25V582

The remedy software will not cause the failsafe to activate under the specified conditions.

### Identify how/when recall condition was corrected in production:

The supplier developed and implemented the improved EPS software into production on August 29, 2025

		rse			

Manufacturer used general reimbursement plan on file.

#### **Recall Schedule**

Description of recall schedule:					
Dealer notification is scheduled to begin and end on or about $9/6/2025$ . Owner notification is scheduled to begin and end on or about $10/20/2025$ .					
Planned Dealer Notification Date: Sep 06, 2025 - Sep 06, 2025	☐ No Dealers				
Planned Interim Owner Notification Date:	☐ No Owners				
Planned Remedy Owner Notification Date: Oct 20, 2025 - Oct 20, 2025	Phased Recall				
Date when VIN will be searchable: Sep 17, 2025					