



U.S. Department  
of Transportation

National Highway  
Traffic Safety  
Administration

## Part 573 Safety Recall Report

## 25V598

**Manufacturer Name:** KTM North America, Inc.

**Submission Date:** Nov 06, 2025

**NHTSA Recall No.:** 25V598

**Manufacturer Recall No.:**

### Manufacturer Information

### Population

**Manufacturer Name:** KTM North America, Inc.

**Address:** 1119 Milan Avenue  
Amherst OH, 44001

**Total number of potentially involved:** 9,070

**Estimated percentage with defect:** 1.6%

### Vehicle Information

**Vehicle 1:** 2023-2023 Husqvarna Vitpilen 401

**Product Category:**

**Product Type:**

**Fuel / Propulsion:** Spark Ignition Fuel

**Production Dates:** Nov 28, 2022 - Jun 26, 2023

**Number of potentially involved:**

**Descriptive Information:**

Only US vehicle article numbers: F5375V5, F5375V6, F5375W7, F5375X7, F1375V1, F1375V5, F1375W1, F1375W5. The production date visible on affected population wiring of the e-throttle or on the attached DMC label (0523). The replacement part has a production date of (2405).

### Defect / Noncompliance Description

**Description of the defect or noncompliance:**

Affected motorcycles may lose throttle response and will revert to idle while riding.

**FMVSS1:**

**FMVSS2:**

**Description of the safety risk, including crash, fire, death, injury:**

On affected models, during use, a reduction in motive power may lead to injury and/or property damage.

# Part 573 Safety Recall Report

# 25V598

## Description of the cause:

Moisture can migrate into the electronic component of the throttle e-throttle and erode the electrical connection. The ECU detects a deviation between the two voltage values delivered from the e-throttle. The vehicle fault reaction is to set the engine to idle speed. After the ignition change, the e-throttle resumes operation until the next fault detection.

## Identification of any warning that can occur:

None

## Component Manufacturer

**Tier of Supplier:** Tier 1

**Supplier Type:** Other

**Name:** Uno Minda Ltd.

**Address:** Plot No. B-1/4/2, Chakan Industrial  
Area Nighoje, Tal-Khed, Dist.  
Pune, Maharashtra Foreign States, 410501

**Country:** India

## Involved Components

**Component Name 1:** E-throttle assembly

**Component Description:** Complete throttle assembly - KTM Adventure

**Component Part Number:** 95802010044

**Component Name 2:** E-throttle assembly

**Component Description:** Complete throttle assembly - HQV Vitpilen

**Component Part Number:** 28611012044

**Component Name 3:** E-throttle assembly

**Component Description:** Complete throttle assembly - HQV Svartpilen

**Component Part Number:** 28111012044

## Chronology

Q3/Q4 2022: First Single Cases.

# Part 573 Safety Recall Report

## 25V598

20. Jan 2023: Start of KTM internal investigation. Coordination, root cause analysis & testing with manufacturer and supplier

01. Jan 2024: 100% camera base inspection to check PCBA after conformal coating

01. Feb 2024: Automatic Cleaning of circuit board after PCBA & wire terminal soldering

18. Sept 2024: First contact of Transport Canada regarding consumer report to TC

25. Sept 2024: Vehicle inspection of reported vehicle

03. Oct 2024: Transport Canada starts investigation

10. Feb 2025: Transport Canada informs KTM about two additional reports

11. Feb 2025: Transport Canada request warranty claim data.

13. Feb 2025: Meeting Transport Canada and KTM NA

06. Mar 2025: Data shared with Transport Canada

07. July 2025: Meeting request from Transport Canada

02. Sept 2025: Meeting KTM HQ with Transport Canada

03. Sept 2025: KTM HQ determination that a recall is needed

05. Sept 2025: Notice of Defect filed with Transport Canada

11. Sept 2025: 573 Report filed with NHTSA

There have been no accidents or injuries related to this defect.

**Related NHTSA Recall Number:**

### Description of Remedy

**Remedy Type:**

**Consumer Advisories:**  Do Not Drive  Park Outside

**Description of remedy program:**

KTM and Husqvarna are notifying all registered owners of affected motorcycles by mail to bring their units to an authorized dealer for repair. The dealer technicians will inspect units and replace the e-throttle control completely, with a new non-affected replacement part.

**How remedy component differs from recalled component:**

Replacement parts can be recognized with the production date after 2405 (May 2024)

**Identify how/when recall condition was corrected in production:**

Starting January 2024, the supplier implemented a 100% camera-based inspection to check printed

# Part 573 Safety Recall Report

# 25V598

circuit board assembly (PCBA) after conformal coating and automatic cleaning of PCBA after soldering.

## Reimbursement Plan

**Description of reimbursement program:**

Dealers must inspect affected motorcycles in their inventory before customer delivery. Affected units are locked and cannot be retail registered to customers until the recall has been performed. An Interim Consumer Notification will be sent out in conjunction with the Recall Bulletin when published.

**Period of reimbursement:****Costs to be reimbursed:**

KTM and Husqvarna owners who previously had this inspection and replacement made will be offered a refund upon providing evidence of the same.

**Address for reimbursement claims:**

1119 Milan Avenue  
Amherst OH, 44001

## Recall Schedule

**Description of recall schedule:**

Dealers will be notified via Dealernet, an online communication portal for dealers. Interim letters will be issued to consumers.

**Planned Dealer Notification Date:** Sep 16, 2025 - Sep 16, 2025  No Dealers

**Planned Interim Owner Notification Date:** Oct 20, 2025 - Oct 20, 2025  No Owners

**Planned Remedy Owner Notification Date:** Dec 31, 2025  Phased Recall

**Date when VIN will be searchable:** Dec 31, 2025