



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

25V600

Manufacturer Name: Corp. Micro Bird, Inc.

Submission Date: Nov 11, 2025

NHTSA Recall No.: 25V600

Manufacturer Recall No.: 25-116-RUS

Manufacturer Information

Population

Manufacturer Name: Corp. Micro Bird, Inc.

Address: 3000, Rue Girardin
Drumondville, Quebec FS,
J2E 0A1

Total number of potentially involved: 611

Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2024-2025 Micro Bird MBII

Product Category:

Product Type:

Fuel / Propulsion:

Production Dates: Oct 10, 2024 - Jul 05, 2025

Number of potentially involved: 429

Descriptive Information:

In certain school vehicles equipped with a power-assisted service door, the rod-eye ring of the rod attaching each door leaf to the opening gear may delaminate, causing the door leaf to disengage from the opening gear and become loose.

Vehicle 2: 2023-2025 Micro Bird T-Series

Product Category:

Product Type:

Fuel / Propulsion:

Production Dates: May 10, 2024 - Jul 10, 2025

Number of potentially involved: 182

Descriptive Information:

In certain school vehicles equipped with a power-assisted service door, the rod-eye ring of the rod attaching each door leaf to the opening gear may delaminate, causing the door leaf to disengage from the opening gear and become loose.

Part 573 Safety Recall Report

25V600**Vehicle 3:** 2023-2025 MICRO BIRD G5**Product Category:** Buses, Medium & Heavy Vehicles**Product Type:** School Bus**Fuel / Propulsion:****Production Dates:** Oct 26, 2023 - Jun 30, 2025**Number of potentially involved:****Descriptive Information:**

In certain school vehicles equipped with a power-assisted service door, the rod-eye ring of the rod attaching each door leaf to the opening gear may delaminate, causing the door leaf to disengage from the opening gear and become loose.

Defect / Noncompliance Description

Description of the defect or noncompliance:

In certain school vehicles equipped with a power-assisted service door, the rod-eye ring of the rod attaching each door leaf to the opening gear may delaminate, causing the door leaf to disengage from the opening gear and become loose

FMVSS1:**FMVSS2:****Description of the safety risk, including crash, fire, death, injury:**

If the door leaf disengage from the opening gear, the leaf is no longer operable from the driver's seat and if the affected door leaf is the affected leaf is the one overlapping the other, vibrations or strong wind can open it, increasing the risk of injury if someone falls off the door or if the door leaf hit something or someone outside the vehicle

Description of the cause:**Identification of any warning that can occur:**

Component Manufacturer

Tier of Supplier: Tier 1**Supplier Type:** Other

Part 573 Safety Recall Report

25V600

Name: LR-TEK Inc.

Address: 21 Rue de Lyon
Repentigny Foreign States, J5Z 4Z3

Country: Canada

Involved Components

Component Name 1: Service door mechanism

Component Description: Service door mechanism

Component Part Number:

Chronology

On December 17, we received report that the service door rear leaf had come loose. Since the front leaf overlaps the rear leaf, the door had not opened, but the rear leaf was no longer operable from the driver's seat.

The situation was presented to LR-TEK, the service door mechanism provider in December 2024. After analysis, they started to verify the rod to make sure that the rod-eye ring showed no sign of delamination and reported a reject rate of 0.6%. They determined that the door mechanism produced after February 2025 did not present the issue.

After new reports of loose rear leaf on June 23 and June 25, 2025, and a third on July 30, 2025, but this time affecting the front leaf, LR-TEK was contacted to evaluate the situation. The uninstalled service door mechanism, as well as those installed in undelivered vehicles, were inspected to determine when they had been manufactured and understand the source of the problem.

On September 4, 2025, it was decided to recall all vehicles in which LR-TEK service door mechanism has been installed.

Micro Bird is not aware of any other claim or complaints or any incidents regarding this defect.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type:

Consumer Advisories: ☐ Do Not Drive ☐ Park Outside

Description of remedy program:

Micro Bird Corporation will provide field inspection and, if necessary, modification instructions to mitigate this recall at no charge. It will be the responsibility of the bus owners to have their vehicle(s)

Part 573 Safety Recall Report

25V600

inspected and corrected by a Micro Bird dealer. The dealers will secure the attachment of each door leaf to the opening mechanism.

Owners who have incurred costs to obtain a remedy for the defect addressed by this recall campaign in advance of notification and have not already submitted a claim on warranty, may submit their claims to Micro Bird Corporation. Reimbursement, in part or in full, will be provided upon approval of the claim

How remedy component differs from recalled component:

Identify how/when recall condition was corrected in production:

Reimbursement Plan

Description of reimbursement program:

Micro Bird Corporation will reimburse labor to mitigate this recall, but it will be your responsibility as owner to contact a Micro Bird dealer to have the defect corrected

Period of reimbursement:

Costs to be reimbursed:

Address for reimbursement claims:

Recall Schedule

Description of recall schedule:

Micro Bird Corporation will notify dealers via emails and written notifications will be sent to recalled vehicles owners

Planned Dealer Notification Date: Oct 16, 2025 - Oct 17, 2025

☐ No Dealers

Planned Interim Owner Notification Date:

☐ No Owners

Planned Remedy Owner Notification Date: Nov 03, 2025 - Nov 07, 2025

☐ Phased Recall

Date when VIN will be searchable: