



U.S. Department  
of Transportation

National Highway  
Traffic Safety  
Administration

## Part 573 Safety Recall Report

## 25V900

**Manufacturer Name:** Volkswagen Group of America, Inc.

**Submission Date:** Feb 04, 2026

**NHTSA Recall No.:** 25V900

**Manufacturer Recall No.:** 90TV

### Manufacturer Information

### Population

**Manufacturer Name:** Volkswagen Group of  
America, Inc.  
**Address:** 3800 Hamlin Road  
Auburn Hills MI, 48326

**Total number of potentially involved:** 356,894  
**Estimated percentage with defect:** 0.7%

### Vehicle Information

**Vehicle 1:** 2019-2024 AUDI ETRON QUATTRO

**Product Category:** Light Vehicles

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Jan 03, 2019 - Mar 24, 2024

**Number of potentially involved:** 37,111

**Descriptive Information:**

The recall population was determined by production records.

The recalled products are equipped with certain parts and software versions that may lead to a malfunction. Vehicles not included do not meet these criteria.

Estimated percentage of involved non-compliant: 0.740%

**Vehicle 2:** 2019-2025 AUDI A7

**Product Category:** Light Vehicles

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Jul 07, 2018 - Mar 21, 2025

**Number of potentially involved:** 11,472

**Descriptive Information:**

The recall population was determined by production records.

The recalled products are equipped with certain parts and software versions that may lead to a malfunction. Vehicles not included do not meet these criteria.

**Part 573 Safety Recall Report****25V900**

Estimated percentage of involved non-compliant: 0.740%

**Vehicle 3:** 2020-2026 AUDI RS Q8

**Product Category:** Light Vehicles

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Mar 02, 2020 - Jul 10, 2025

**Number of potentially involved:** 7,681

**Descriptive Information:**

The recall population was determined by production records.

The recalled products are equipped with certain parts and software versions that may lead to a malfunction. Vehicles not included do not meet these criteria.

Estimated percentage of involved non-compliant: 0.740%

**Vehicle 4:** 2020-2025 AUDI S6

**Product Category:** Light Vehicles

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Oct 22, 2019 - Jul 10, 2025

**Number of potentially involved:** 2,911

**Descriptive Information:**

The recall population was determined by production records.

The recalled products are equipped with certain parts and software versions that may lead to a malfunction. Vehicles not included do not meet these criteria.

Estimated percentage of involved non-compliant: 0.740%

**Vehicle 5:** 2022-2026 AUDI E-TRON GT

**Product Category:** Light Vehicles

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Mar 26, 2021 - Sep 26, 2025

**Number of potentially involved:** 3,859

**Descriptive Information:**

The recall population was determined by production records.

**Part 573 Safety Recall Report****25V900**

The recalled products are equipped with certain parts and software versions that may lead to a malfunction. Vehicles not included do not meet these criteria.

Estimated percentage of involved non-compliant: 0.740%

**Vehicle 6:** 2020-2026 AUDI SQ7

**Product Category:** Light Vehicles

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Mar 04, 2020 - Jul 07, 2025

**Number of potentially involved:** 8,056

**Descriptive Information:**

The recall population was determined by production records.

The recalled products are equipped with certain parts and software versions that may lead to a malfunction. Vehicles not included do not meet these criteria.

Estimated percentage of involved non-compliant: 0.740%

**Vehicle 7:** 2020-2024 AUDI E-TRON SPORTBACK QUATTRO

**Product Category:** Light Vehicles

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** May 20, 2020 - Mar 26, 2025

**Number of potentially involved:** 10,191

**Descriptive Information:**

The recall population was determined by production records.

The recalled products are equipped with certain parts and software versions that may lead to a malfunction. Vehicles not included do not meet these criteria.

Estimated percentage of involved non-compliant: 0.740%

**Vehicle 8:** 2020-2026 AUDI SQ8

**Product Category:** Light Vehicles

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Mar 04, 2020 - Jul 10, 2025

**Number of potentially involved:** 11,590

**Part 573 Safety Recall Report****25V900****Descriptive Information:**

The recall population was determined by production records.

The recalled products are equipped with certain parts and software versions that may lead to a malfunction. Vehicles not included do not meet these criteria.

Estimated percentage of involved non-compliant: 0.740%

**Vehicle 9:** 2019-2026 AUDI A8

**Product Category:** Light Vehicles

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Aug 07, 2018 - Sep 08, 2025

**Number of potentially involved:** 12,246

**Descriptive Information:**

The recall population was determined by production records.

The recalled products are equipped with certain parts and software versions that may lead to a malfunction. Vehicles not included do not meet these criteria.

Estimated percentage of involved non-compliant: 0.740%

**Vehicle 10:** 2021-2026 AUDI RS 6 AVANT

**Product Category:** Light Vehicles

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Jul 24, 2020 - Sep 03, 2025

**Number of potentially involved:** 6,425

**Descriptive Information:**

The recall population was determined by production records.

The recalled products are equipped with certain parts and software versions that may lead to a malfunction. Vehicles not included do not meet these criteria.

Estimated percentage of involved non-compliant: 0.740%

**Vehicle 11:** 2019-2025 AUDI A6

**Product Category:** Light Vehicles

**Product Type:**

**Fuel / Propulsion:**

**Part 573 Safety Recall Report****25V900****Production Dates:** Aug 07, 2018 - Jun 23, 2025**Number of potentially involved:** 45,233**Descriptive Information:**

The recall population was determined by production records.

The recalled products are equipped with certain parts and software versions that may lead to a malfunction. Vehicles not included do not meet these criteria.

Estimated percentage of involved non-compliant: 0.740%

**Vehicle 12:** 2020-2026 AUDI A6 ALLROAD**Product Category:** Light Vehicles**Product Type:****Fuel / Propulsion:****Production Dates:** Nov 05, 2019 - Jul 16, 2025**Number of potentially involved:** 5,526**Descriptive Information:**

The recall population was determined by production records.

The recalled products are equipped with certain parts and software versions that may lead to a malfunction. Vehicles not included do not meet these criteria.

Estimated percentage of involved non-compliant: 0.740%

**Vehicle 13:** 2020-2025 AUDI S7**Product Category:** Light Vehicles**Product Type:****Fuel / Propulsion:****Production Dates:** Oct 22, 2019 - May 26, 2025**Number of potentially involved:** 2,572**Descriptive Information:**

The recall population was determined by production records.

The recalled products are equipped with certain parts and software versions that may lead to a malfunction. Vehicles not included do not meet these criteria.

Estimated percentage of involved non-compliant: 0.740%

**Vehicle 14:** 2020-2026 AUDI Q7**Product Category:** Light Vehicles

**Part 573 Safety Recall Report****25V900****Product Type:****Fuel / Propulsion:****Production Dates:** Oct 24, 2019 - Jul 10, 2025**Number of potentially involved:** 120,611**Descriptive Information:**

The recall population was determined by production records.

The recalled products are equipped with certain parts and software versions that may lead to a malfunction. Vehicles not included do not meet these criteria.

Estimated percentage of involved non-compliant: 0.740%

**Vehicle 15:** 2022-2026 AUDI RS E-TRON GT**Product Category:** Light Vehicles**Product Type:****Fuel / Propulsion:****Production Dates:** Mar 18, 2021 - Oct 01, 2025**Number of potentially involved:** 3,222**Descriptive Information:**

The recall population was determined by production records.

The recalled products are equipped with certain parts and software versions that may lead to a malfunction. Vehicles not included do not meet these criteria.

Estimated percentage of involved non-compliant: 0.740%

**Vehicle 16:** 2019-2026 AUDI Q8**Product Category:** Light Vehicles**Product Type:****Fuel / Propulsion:****Production Dates:** Aug 08, 2018 - Jul 10, 2025**Number of potentially involved:** 60,775**Descriptive Information:**

The recall population was determined by production records.

The recalled products are equipped with certain parts and software versions that may lead to a malfunction. Vehicles not included do not meet these criteria.

Estimated percentage of involved non-compliant: 0.740%

# Part 573 Safety Recall Report

# 25V900

**Vehicle 17:** 2021-2026 AUDI RS 7

**Product Category:** Light Vehicles

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Jul 24, 2020 - Sep 09, 2025

**Number of potentially involved:** 4,403

**Descriptive Information:**

The recall population was determined by production records.

The recalled products are equipped with certain parts and software versions that may lead to a malfunction. Vehicles not included do not meet these criteria.

Estimated percentage of involved non-compliant: 0.740%

**Vehicle 18:** 2020-2026 AUDI S8

**Product Category:** Light Vehicles

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Oct 22, 2019 - Aug 03, 2025

**Number of potentially involved:** 3,010

**Descriptive Information:**

The recall population was determined by production records.

The recalled products are equipped with certain parts and software versions that may lead to a malfunction. Vehicles not included do not meet these criteria.

Estimated percentage of involved non-compliant: 0.740%

## Defect / Noncompliance Description

**Description of the defect or noncompliance:**

In certain situations, a software issue may prevent the rearview camera image from displaying.

**FMVSS1:** 111 - Rear visibility

**FMVSS2:**

**Description of the safety risk, including crash, fire, death, injury:**

A rearview camera image that does not display decreases the driver's visibility when reversing,

# Part 573 Safety Recall Report

# 25V900

increasing the risk of a crash.

## Description of the cause:

The exact root cause could not be identified but the analysis suggests that electrical noise, diminished shielding integrity, and timing may adversely affect rearview camera operation.

## Identification of any warning that can occur:

If this occurs, the driver will notice the rearview camera image is not displayed. Owners who may experience this issue are advised to use extra caution when reversing, and they should contact an authorized Audi dealer without delay to have the vehicle diagnosed.

## Component Manufacturer

### Tier of Supplier:

### Supplier Type:

**Name:** Volkswagen Group of America, Inc.

**Address:** 3800 Hamlin Road  
Auburn Hills MI, 48326

**Country:** United States

## Involved Components

**Component Name 1:** Software for the control unit of driver assistance

**Component Description:** Software for the control unit of driver assistance systems

**Component Part Number:** n/a

## Chronology

December 2023: Based on field claims received, an investigation of the issue and potential influencing factors and consequences was initiated.

January 2024 - September 2024: Various reproduction attempts, component analyses, and complete vehicle analyses were carried out to identify the root cause. However, due to the highly sporadic occurrence of the issue, the cause could not be determined.

October 2024 - September 2025: Even though the root cause, failure mechanism and consequences had not been fully understood, potential technical measures for the field were evaluated. Through ongoing analyses, corrupted register entries were identified for the first time during tests in November 2024 in one of the cameras, which could lead to camera failure. However, the reason why these corrupted register entries occur remained unknown. Further testing confirmed for the first time that electrical noise between the control unit and the cameras can cause corrupted register data which could sporadically affect the performance of one or more individual cameras of the Top View Camera system if

# Part 573 Safety Recall Report

# 25V900

the system is being used during that driving cycle. It was found that the issue is highly sporadic and is resolved after vehicle restart/bus sleep. Analysis continued to further understand the influencing factors.

October - December 2025: While the topic was still being investigated, it was also discussed with NHTSA ODI during a regular meeting on October 8, 2025. Measurements at coaxial cables of the field revealed an increased shielding resistance, and with that, reduced protection from electromagnetic interference, potentially caused by variations at crimp connections. This factor, in conjunction with electrical noise at a specific time, may ultimately result in camera failures within the Top View System. An additional discussion with NHTSA ODI occurred on December 12, 2025 and the current status was presented and discussed.

December 15, 2025: The Audi Product Safety Committee determined the issue constitutes a noncompliance and decided a noncompliance recall.

Date of determination: December 15, 2025

January 2026: Audi identified 245 vehicles in the United States that were not captured by the recall selection logic following a report received by Audi from a foreign market. Audi performed additional plausibility and validation checks to confirm the newly identified vehicle population was correct and complete.

On January 28, 2026, the Audi Product Safety Committee decided to include these 245 vehicles in the ongoing recall campaign 90TV.

**Related NHTSA Recall Number:**

## Description of Remedy

**Remedy Type:** Software

**Consumer Advisories:**  Do Not Drive  Park Outside

**Description of remedy program:**

The analysis suggests the primary issue impacting camera operability is software that lacks sufficient robustness. To address this issue, a more robust software solution was developed concurrently during the analysis to prevent such failures. This software will be installed on the affected vehicles.

**How remedy component differs from recalled component:**

The software solution can perform a self-healing process of the cameras during the driving cycle, if necessary, thereby preventing the failure. This self-healing process typically occurs quickly and in the background, so it is generally not noticeable to the customer unless the Top View system is active on the MMI.

**Identify how/when recall condition was corrected in production:**

The new software was introduced for the various affected models between July and September 2025.

## Reimbursement Plan

**Part 573 Safety Recall Report****25V900**

Manufacturer used general reimbursement plan on file.

**Recall Schedule****Description of recall schedule:**

Planned Dealer Notification Begin Date: On or before 12/23/2025

Planned Dealer Notification End Date: On or before 12/23/2025

Planned Owner Notification Begin Date: On or before 02/17/2026

Planned Owner Notification End Date: On or before 02/17/2026

**Planned Dealer Notification Date:** Dec 23, 2025 - Dec 23, 2025 No Dealers**Planned Interim Owner Notification Date:** No Owners**Planned Remedy Owner Notification Date:** Feb 17, 2026 - Feb 17, 2026 Phased Recall**Date when VIN will be searchable:** Dec 23, 2025