



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

25V905

Manufacturer Name: Tiffin Motorhomes, Inc.

Submission Date: Dec 23, 2025

NHTSA Recall No.: 25V905

Manufacturer Recall No.: WAY-106

Manufacturer Information

Population

Manufacturer Name: Tiffin Motorhomes, Inc.

Address: 105 2nd Street NW
PO Box 596
Red Bay AL, 35582

Total number of potentially involved: 18

Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2025-2025 TIFFIN OPEN TRAIL

Product Category: Buses, Medium & Heavy Vehicles

Product Type: Recreational Vehicle

Fuel / Propulsion:

Production Dates: Mar 06, 2025 - May 16, 2025

Number of potentially involved: 1

Descriptive Information:

The recall involves all 2025 and 2026 Open Trail Motorhomes that were produced with an optional diesel or propane generator.

Vehicle 2: 2026-2026 TIFFIN OPEN TRAIL

Product Category: Buses, Medium & Heavy Vehicles

Product Type: Recreational Vehicle

Fuel / Propulsion:

Production Dates: May 05, 2025 - Nov 25, 2025

Number of potentially involved: 17

Descriptive Information:

The recall involves all 2025 and 2026 Open Trail Motorhomes that were produced with an optional diesel or propane generator.

Part 573 Safety Recall Report

25V905

Defect / Noncompliance Description

Description of the defect or noncompliance:

The wire between the battery and the inverter may become overheated.

FMVSS1:

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

If the wire becomes overheated, there is a risk of fire.

Description of the cause:

The wire harness used between the battery and the inverter contains a 2 gauge wire and the inverter installation instructions state the wire should be a 2/0 wire.

Identification of any warning that can occur:

There is no warning.

Component Manufacturer

Tier of Supplier:

Supplier Type:

Name:

Address:

Country:

Involved Components

Component Name 1: Wire harness between battery and inverter

Component Description: 2 gauge wire

Component Part Number: Will be provided later

Chronology

12/08/2025 Compliance was notified by the Open Trail product manager that a customer contacted him about an overheated wire. 12/09/2025 Investigation started 12/11/2025 Engineering confirmed the wire

Part 573 Safety Recall Report

25V905

harness in question had the incorrect wire gauge according to the inverter installation guide. The installation guide calls for a 2/0 wire and a 2 gauge had been used. Engineering also confirmed this would only involve Open Trails equipped with a optional generator because those units were the only one with this wiring/inverter set up. 12/18/2025 Safety committee meeting was held, safety committee voted to recall all Open Trails equipped with an optional generator to replace the wire harness between the inverter and the battery with the correct gauge of wire.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Replace

Consumer Advisories: Do Not Drive Park Outside

Description of remedy program:

Tiffin Motorhomes will replace the 2 gauge wire harness with a 2/0 wire harness.

How remedy component differs from recalled component:

The remedy component will contain the correct gauge of wire.

Identify how/when recall condition was corrected in production:

All units in production and the PDI/final finish area had the 2 gauge wire harness replaced with a 2/0 wire harness. An engineering change notification was issued to correct the wire size for all future units.

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Recall Schedule

Description of recall schedule:

Tiffin Motorhomes will mail letters to customers and dealers that are in possession of the involved motorhomes explaining the issue and asking them to take the motorhome to a dealer or a service center so the wiring can be corrected. This will be done at no cost to the owner.

Planned Dealer Notification Date: Feb 20, 2026 - Feb 20, 2026 No Dealers

Planned Interim Owner Notification Date: No Owners

Part 573 Safety Recall Report

25V905

Planned Remedy Owner Notification Date: Feb 20, 2026 - Feb 20, 2026 Phased Recall

Date when VIN will be searchable: Feb 20, 2026