



ADMINISTRATION BULLETIN - SAFETY RELATED RECALL

Global Recall Action
Number:
H535ADM2

Changes are highlighted in blue

| | |
|---|---------------------------------|
| Subject: Loss of Rear View Camera Image | Publication No.: H535ADM2 |
| | Model: XE (X760) |
| | Model Year: 2019 - 2020 |
| | Date of Issue: 06 November 2025 |

| | |
|-----------------------|--|
| To: | JLR North America, LLC and JLR Canada ULC. |
| For the Attention of: | The approved JLR retailer/authorized repairer. |

FOR THE ATTENTION OF NORTH AMERICAN TERRITORIES ONLY:

National Highway Traffic Safety Administration (NHTSA) reference number:25V-017

Transport Canada (TC) reference number:2025-016

Visit the British Brands Sales Suite (BBSS) website for a list of affected vehicles at your retailer/authorized repairer. Unsold vehicles must be repaired prior to handover of the vehicle for retail sale.

| | |
|--|---|
| | The following applies to: [NORTH AMERICA] |
|--|---|

REGULATORY INFORMATION

| | |
|--|---|
| | The following applies to: [NORTH AMERICA] |
|--|---|

JLR North America, LLC and JLR Canada ULC have informed the National Highway Traffic Safety Administration (NHTSA) and Transport Canada (TC) of their intent to perform a Safety Recall on certain 2019 and 2020 model year XE vehicles imported into the United States and Canada markets. Information relating to this Safety Recall will be posted on the NHTSA and TC websites.



The following applies to:
[NORTH AMERICA]

This Safety Recall Administration Bulletin serves as notification to all retailers in the United States and Canada markets that any new affected vehicles may not be sold and delivered for customer use until the Safety Recall repair is completed. Violation of this requirement by a retailer/authorized repairer, in the USA only, could result in a maximum civil penalty of up to the equivalent of \$27,874.00 USD per violation and the equivalent of \$139,356,994.00 USD for a related series of violations.

DESCRIPTION OF ISSUE AND THE EFFECT ON VEHICLE OPERATION

A concern has been identified on certain 19MY and 20MY Jaguar XE vehicles, where the rear view camera image display may become intermittent or permanently fail as a result of wiring damage in the trunk.

Lack of, or intermittent, display of the rear view camera image may result in the driver being unaware of objects or pedestrians behind the vehicle increasing the risk of a crash.

OWNER NOTIFICATION

Initial owner notification is expected to occur on or before 14th March 2025.

ACTION TO BE TAKEN

Check the JLR Warranty Portal to make sure affected vehicles are correctly identified prior to starting this campaign. The Warranty Portal will be updated to reflect only those vehicles affected.

Retailers/authorized repairers are required to Quarantine affected new vehicles that are within your control and refrain from releasing the vehicles for new vehicle sale pending completion of the rework action. Affected vehicles already with customers should be updated at the next available opportunity. JLR North America recommends that affected sales demonstrator and loaner vehicles are repaired before use and that used vehicles are repaired before sale. Retailers/authorized repairers who choose to proceed against this recommendation, where legally permitted, must clearly and conspicuously disclose the open recall to the applicable customers.

The Safety Recall repair procedures and any required parts and/or software are not currently available. A Safety Recall repair campaign will be published when all repair procedures and all required parts and/or software are available. This is expected to be completed by TBD.

Retailers/authorized repairers are reminded that they must not sell vehicles identified as affected by this campaign until such time as the repair has been successfully completed.

Yours faithfully

Steve Oldham

Global Customer Care Quality Director