

ASB2 Stop Delivery / Recall Campaign - Re-programming the control unit for driver assistance systems

Update 1/21/2026 - Recall Vehicles added

Please note that Recall vehicles have been added to ASB2. The full VIN list is below as well as the separate Stop Delivery list. The remedy can be carried out via the interim TI below, and the official TI will be released in the coming days.

Please note that currently the campaign cannot be carried out for scopes 5 and 6 due to the missing software package (individual repair Scopes are listed in the attached full VIN list). The TI will be updated when the repair for these vehicles becomes available. These scopes generally correspond to 992.1 and E3.1 vehicles, for which the repair is not yet available. PLEASE DO NOT attempt to submit Warranty claims for the completion of the campaign on vehicles with scopes 5 and 6. If this occurs, the campaign will pay 0TU and will be reset to open when the repair becomes available.

Some vehicles will be assigned to scopes 5 and 8 or 6 and 8. If a vehicle has already received an update of the control unit for assistance systems before the release of this campaign, Scope 8 must be invoiced.

ASB2 Stop Delivery / Recall Campaign - Re-programming the control unit for driver assistance systems

Important Information

PORSCHE CENTERS SHOULD NOT SELL, LEASE, RENT, OR LOAN ANY NEW OR USED VEHICLES IN DEALER INVENTORY AFFECTED BY THIS NOTIFICATION PRIOR TO REMEDY. PORSCHE CENTERS GROUNDING LEASE RETURNS SHOULD REMEDY ALL AFFECTED GROUNDED VEHICLES.

Any vehicles delivered to customers before this announcement may be released from Stop Delivery by sending a PRMS Warranty / Campaigns Ticket to PCNA_Warranty_Support in PRMS. The ticket must have proper documentation of the sale / delivery.

ID Number	ASB2
Affected Models	911 (992) Panamera (YAA) Taycan (Y1A, Y1B, Y1C)

ASB2 Stop Delivery / Recall Campaign - Re-programming the control unit for driver assistance systems

Affected Model Years	Cayenne (9YA, 9YB) 2019-2025
VIN List	Attached below
Number of affected vehicles	172,462 Total 1,175 Stop Delivery
Issue Description	Due to a software issue, one or more surround view cameras may not operate as designed and not display on the corresponding portion of the PCM display screen.
What should Porsche Centers do?	<p>PORSCHE CENTERS SHOULD NOT SELL, LEASE, RENT, OR LOAN ANY NEW OR USED VEHICLES IN DEALER INVENTORY AFFECTED BY THIS NOTIFICATION PRIOR TO REMEDY. PORSCHE CENTERS GROUNDING LEASE RETURNS SHOULD REMEDY ALL AFFECTED GROUNDED VEHICLES.</p> <p>The vehicles will be reprogrammed with an updated driver assistance systems control unit software when the remedy is available.</p> <p>The remedy is now available as of 12/17/25.</p>
What will Porsche do?	<p>Subject vehicles will be remedied as soon as the remedy is available.</p> <p>The remedy is now available as of 12/17/25.</p>
Technical Information	Interim TI Attached below. Please note that since this is an interim TI it will not be available in PCSS.
Parts Status	Status 0 - No parts needed.
Customer Letter	To be released at a later date, if applicable.
Customer Reactive Statement	The safety of our customers is of utmost importance. We've identified that, in specific circumstances, a software issue may prevent the reversing cameras on certain cars operating as they should. In this condition, the cars do not meet one of the applicable regulations - consequently, we are conducting a voluntary recall. Customers will be notified and new software will be installed free of charge.

Procedure in the event of a workshop visit before software availability (Vehicles with Repair Scopes 5 and 6)

For vehicles for which no software is available yet, please proceed as follows:

- Mark the campaign as **cannot be carried out/ Campaign Not Feasible** with the reason "no software" in PCSS. Do **not** activate the "Warranty relevance" indicator!
- **The campaign remains open until the final software is available and may not be invoiced/closed.**

Required software

Porsche Tester 4 test software release 43.800.030 (or higher)

Warranty processing

Please enter the campaign carried out in the Warranty and Maintenance booklet for the vehicle.

Scope 1 to Scope 6:

Damage Code	ASB2 99 000
Repair Code	1
Labor time	86 TU to 90 TU

Scope 7:

- Only valid for vehicles with the **open** WRX1 campaign (first update as part of WRX1)

Damage Code	ASB2 99 000
Repair Code	1
Labor time	16 TU

Scope 8:

- Only valid for vehicles for which the software is already at the target level

Damage Code	ASB2 99 000
Repair Code	1
Labor time	16 TU

Note:

If a vehicle has already received an update of the control unit for assistance systems before the release of this campaign, Scope 8 must be invoiced.

The procedure for checking is described in the Technical Information.

Old / Outdated Updates

Update 12/17/25 - Remedy now available!

Please be advised that the remedy for ASB2 Stop Delivery vehicles is now available ONLY via the attached interim TI below. Please note that since this is an interim TI it will not be available in PCSS.

The only vehicle where the remedy is not yet available is for MY24 Cayenne.

Attachments

1. [VIN_List_Report_ASB2_2025-12-16_V3.xlsx](#)
2. [ASB2 Stop Delivery Remedial Measures.pdf](#)
3. [VIN_List_Report_ASB2_2026-01-21_V4.xlsx](#)