

# Quality Bulletin

TITLE:

**Recall RP1061 - PS2 BCM2 Software, Certain Model Year 2021-2025 Polestar 2**

<b>GROUP:</b> 30	<b>NO:</b> RP1061	<b>ISSUING DEPARTMENT:</b> Product, Safety and Compliance	<b>CAR MARKET:</b> United States and Canada	
<b>REVISIONS:</b>			<b>ISSUE DATE:</b> 2025-06-17	<b>STATUS DATE:</b> 2025-06-17
<b>Page 1 of 3</b>				

## BULLETIN REFERENCE

- A. RECALL RP1061 DESCRIPTION
- B. VEHICLES INVOLVED
- C. PORT VEHICLES
- D. PARTS INFORMATION/PARTS RETURN
- E. OWNER NOTIFICATION
- F. VEHICLES IN INVENTORY
- G. SERVICE POINT RESPONSIBILITY
- H. TECHNICIAN COMPETENCY REQUIREMENT
- I. REIMBURSEMENT PROCEDURES & ALLOWANCE

### A. RECALL RP1061 DESCRIPTION

Polestar Automotive USA, on behalf of Polestar Performance AB, have decided to launch Recall RP1061 on certain model year 2021 to 2025 Polestar 2 vehicles.

Polestar has identified that a loss of brake functionality may occur while in “One Pedal Drive” mode after an extended coast down period. Affected customers may experience a loss of braking.

As a result, loss of brake functionality will increase the risk of a crash.

To remedy the affected vehicles, Polestar will release a software update. This software is currently available in VIDA and will be made available via over-the-air (OTA) later this week. If the vehicle has **P3.6.4 or later** then this recall has been satisfied.

A total of 2 U.S. and 113 Canadian vehicles are affected by this recall.

# Quality Bulletin RP1061

## WHAT SHOULD YOUR CUSTOMERS DO NOW?

We have no reports of incidents related to the issue; however, we encourage customers to contact their Service Point and have this repair completed as soon as possible. **We are advising customers to not drive their vehicles in “One Pedal Drive” mode until the recall remedy has been performed.**

## B. VEHICLES INVOLVED

**NOTE: SERVICE POINT MUST CONFIRM VEHICLE ELIGIBILITY PRIOR TO BEGINNING THE REPAIR FOR THIS RECALL.**

Vehicle eligibility must be confirmed:

- Vehicle Inquiry – Warranty Vehicle Inquiry where the message “Recall RP1061 PS2 BCM2 Software” will appear for eligible vehicles, F4=History from the main Inquiry menu must be selected to confirm Recall RP1061 has not been completed. Eligibility can also be confirmed in VIDA.

All vehicles must be checked for any incomplete Recalls, Service Campaigns, or Service Upgrades. All open Recall, Service Campaigns or Service Action repairs must be completed.

## C. PORT VEHICLES

NOT all eligible vehicles arriving from the ports will have this recall completed. Vehicle eligibility must be confirmed as outlined in Step B. above.

## D. PARTS / PARTS RETURN

Please refer to Parts Bulletin RP1061.

## E. OWNER NOTIFICATION

An owner’s notification will be sent out that will notify the owner of this recall early August.

## F. VEHICLES IN INVENTORY

### New Vehicles in Inventory

**It is a violation of federal law for a retailer to deliver any new Polestar that is eligible for a recall. Service Points are advised to check all vehicles in inventory for recall eligibility and repair immediately. Violation of this requirement by a Service Point could result in a civil penalty of up to \$26,315.00 per vehicle.**

**Correct all vehicles in your new vehicle inventory before delivery.**

### Used Vehicles in Inventory

Polestar is ordering the stop-delivery of affected vehicles in auction and dealer inventory until the recalled item can be repaired. Stopping the delivery of affected used vehicles until the recall is complete is consistent with our commitment to safety.

### What does this mean for customers?

Customers will not be able to take delivery of affected vehicles until the recall has been completed.

# Quality Bulletin RP1061

## G. SERVICE POINT RESPONSIBILITY

All vehicles qualifying for this recall must be repaired prior to a customer taking possession of the vehicle.

## H. TECHNICIAN COMPETENCY REQUIREMENT

The technician's competency requirement for this campaign repair is G1.

## I. REIMBURSEMENT PROCEDURES & ALLOWANCE

Recall RP1061 claims should be submitted using the LONG FORM application only.

**Claim Type:** RP1061  
**Cause Code:** 02  
**CSC Code:** XW  
**Main OP:** 99942-2  
**Failed Part No:** 32292674 (Total Upgrade)

<u>Operation Number</u>	<u>Repair Description</u>	<u>Qty</u>	<u>Models</u>	<u>Labor Time</u>
99942-2	Software update acc To. QB	1	Polestar 2	0.3

\*Labor times provided are current at the time of release and are subject to change: Claims will be paid at the time in effect on the repair date.