

2. With the OE upper triple clamp (2) removed, set fork height. Refer to Table 4.
 - a. See Figure 2. Measure distance (1) from top of fork tube to top of lower triple clamp (3).
 - b. If distance is not within specification, set fork distance.
 - c. Loosen lower triple clamp (3) pinch screw (4).
 - d. Adjust as needed. Tighten screw (4).
Torque: 33 N·m (24 ft-lbs)
 - e. Repeat procedure on opposite side.
3. If distance is within specification, adjust lower triple clamp pinch screws (4) to **new torque**:
 - a. Leave lower triple clamp (3) in its current location.
 - b. Loosen screws (4) individually 90 degrees.
 - c. Tighten screws (4).
Torque: 33 N·m (24 ft-lbs)
4. See Figure 3. Install **new** upper triple clamp (3) from recall kit. See service manual.
 - a. See Figure 1. Use **new** screw (Part No. 10200925) supplied in recall kit for installation of fork lock to **new** upper triple tree.




Figure 1.

5. See Figure 3. Install screws (1, 2) from recall kit and tighten.
Torque: 33 N·m (24 ft-lbs)
6. Install remaining vehicle components that were removed to gain access to upper triple clamp. See service manual.




Figure 2. Front Fork Mount (typical)

Table 4. Fork Installation Distance

Model	Distance
RH1250S	177.8 ± 1.5 mm (7 ± 0.06 in)




Figure 3. Recall Kit 0190

Submit a claim for any upper triple clamp part numbers listed below that are in inventory:

Table 5. Old Service Part Numbers

Part Number
45900245
45900365

Credit Procedure

NOTE

Enter bulletin number into comment section of claim.

Claims for dealer inventory of parts listed in Table 5, submit a warranty claim per Table 6 or Table 7.

Table 6. Credit Procedure: Talon/H-Dnet.com Warranty Claim System Users Parts in Dealer Stock (Do not enter a VIN) - DEALER INVENTORY

ITEM	DATA
Claim Type	SNV
Problem Part Number	Refer to Table 5.
Quantity	Could Vary
Customer Concern Code	0190
Condition Code	9982

Table 7. Credit Procedure: GDP/SAP System Users - DEALER INVENTORY

ITEM	DATA
Claim Type	PAM - stock
Problem Part Number	Refer to Table 5.
Quantity	Could Vary
Customer Concern Code	9205
Condition Code	1517

For each vehicle involved in this recall (involvement of Vehicle Identification Number (VIN) has been verified on h-dnet.com), submit a recall claim per the table below.

Table 8. Credit Procedure: Talon/h-dnet.com Warranty Claim System Users - REPLACEMENT

ITEM	DATA
Claim Type	SRC
Problem Part Number	45900365
Quantity	Leave Blank
Primary Labor Code	2848
Labor Hours	1.0
Customer Concern Code	0190
Condition Code	9981
Replacement Part Number	91500125
Quantity	1

Table 9. Credit Procedure: GDP/SAP System Users - REPLACEMENT

ITEM	DATA
Claim Type	Recall Claim
Fix ID-Found in Recall Number	R
Problem Part Number	45900365
Customer Concern Code	0190
Condition Code	9981

Upon submission of the properly completed claim, you will be credited for 1.0 hours of labor time for performing the procedure, plus appropriate administrative time. Credit will also be issued for the recall kit (United States only). Submit campaign events on their own warranty claim. Do not mix them with other warranty events.

Return Parts

Hold all claimed parts for 60 days from date of credit issued for possible field inspection and/or request to return to factory. After 60 days, destroy and discard the parts.