



# Safety Recall

## Code: 694T

**Subject** Front Seat Safety Belt(s)

**Document History**

Date	Summary
10/23/2025	Original publication

**Affected Vehicles**

Country	Beginning Model Year	Ending Model Year	Vehicle	Vehicle Count
USA	2025	2025	GOLF GTI	325
USA	2025	2025	GOLF R	103
CAN	2025	2025	GOLF GTI	47
CAN	2025	2025	GOLF R	26

Check Campaigns/Actions screen in ELSA on the day of repair to verify that a VIN qualifies for repair under this action. ELSA is the only valid campaign inquiry & verification source.

- ✓ Campaign status must show "open."
- ✓ If ELSA shows other open action(s), inform your customer so that the work can also be completed at the same time the vehicle is in the workshop for this campaign.

**Problem Description**

One or both front seat safety belt retractors may have been built with a damaged torsion bar. In a crash, a damaged torsion bar could fail, causing the webbing to unwind uncontrollably. If this happens, the safety belt would not provide protection to the occupant, increasing the risk of injury.

**Corrective Action**

Replace the affected driver and/or front passenger safety belt(s).

**Precautions**

If customers have concerns about driving their vehicle before the recall remedy has been completed, they are advised to contact an authorized Volkswagen dealer for assistance in having the vehicle transported to the dealership for this recall repair, and to obtain alternate transportation while the vehicle is being repaired.

**Code Visibility**

On September 26, 2025, the campaign code was applied to affected vehicles.

**Owner Notification**

Owner notification will take place in October 2025. Owner letter examples are included in this bulletin for your reference.

**Additional Information**

**Please alert everyone in your dealership about this action, including Sales, Service, Parts and Accounting personnel. Contact Warranty if you have any questions.**

**IMPORTANT REMINDER ON VEHICLES AFFECTED BY SAFETY & COMPLIANCE RECALLS**

**USA Dealers - New Vehicles in Dealer Inventory:** It is a violation of federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by this notification under a sale or lease until the defect or noncompliance is remedied. By law, dealers must correct, prior to delivery for sale or lease, any vehicle that fails to comply with an applicable Federal Motor Vehicle Safety Standard or that contains a defect relating to motor vehicle safety.

**Canada Dealers – New Vehicles in Dealer Inventory:** Dealers must correct, prior to delivery for sale or lease, any vehicle that fails to comply with an applicable Canadian Motor Vehicle Safety Standard or that contains a defect relating to motor vehicle safety.

**All Dealers - Pre-Owned Vehicles in Dealer Inventory:** Dealers should not deliver any pre-owned vehicles in their inventory which are involved in a safety or compliance recall until the defect has been remedied.

Dealers must ensure that every affected inventory vehicle has this campaign completed before delivery to consumers.

Fill out and affix Campaign Completion Label (CAMP 010 000) after work is complete.  
*Labels can be ordered at no cost via the Compliance Label Ordering portal at [www.vwhub.com](http://www.vwhub.com).*

## Parts Information

Criteria	Quantity	Part Number	P.O.C. Part Description	Ordering Method
01	1	5H1-857-705-K RAA	SEAT BELT (left)	Reference POC comments individually by part number, or in the POC Campaign List
02	1	5H1-857-706-K RAA	SEAT BELT (right)	
ALL	2	5G0-886-373	GROMMET	

**Initial Allocation:**  
**YES**

Dealers will be sent an initial allocation prior to customer notification. If no initial allocation was received, please reference your dealer's Estimated Remaining Repairs by campaign to view your potential VIN population.

 **NOTE**

Your dealer's Estimated Remaining Repairs by campaign can be found in Parts on Command. Click on "View Campaign List" and review the Estimated Remaining Repairs column.

 **NOTE**

Campaign parts should always be ordered as per the parts information in this circular. The ordering system will supersede the part, if applicable.

## Claim Entry Instructions

The labor times listed here may differ from the labor operations and labor times listed in ELSA.

After campaign has been completed, enter claim as soon as possible to help prevent work from being duplicated elsewhere. Attach the ELSA screen print showing action *open on the day of repair* to the repair order.

If a customer declines campaign work, refer to the "Customer Declines Campaign/Update Repair" section in the Campaign/Update Policy and Procedures Manual.

<b>Service Number</b>	694T
<b>Damage Code</b>	0099
<b>Parts Vendor Code</b>	WWO
<b>Claim Type</b>	Sold vehicle: 7 10 Unsold vehicle: 7 90
<b>Causal Indicator</b>	Mark SEAT BELT* as causal part
<b>Vehicle Wash/Loaner</b>	Do not claim wash/loaner under this action.  Loaner/rental coverage cannot be claimed under this action. However, loaner/rental may be covered under the current loaner/mobility program. Please refer to the Volkswagen Warranty Policy and Procedures Manual for loaner claims information and reimbursement details.

**Vehicles may have more than one criteria.  
Complete and claim all applicable criteria on one claim.**

### LABOR

Criteria	Labor Op	Time Units	Description
01 and/or 02	6911 19 50	SEE ELSA	Seat belt, front remove+reinstall <i>(vehicles with criteria 01 AND 02: enter twice if both seat belts are replaced)</i>
	6805 19 50	SEE ELSA	Inner sill panel molding remove+reinstall <i>(vehicles with criteria 01 AND 02: enter twice if both seat belts are replaced)</i>
	2706 89 50	SEE ELSA	Connect battery charger
	0150 00 60	Time stated on diagnostic protocol	GFF/Guided Functions

### PARTS

Criteria	Quantity	Part Number	Description
01	1.00	5H1857705K RAA	SEAT BELT* (left)
02	1.00	5H1857706K RAA	SEAT BELT* (right)
ALL	2.00	5G0886373	GROMMET

## Customer Letter Example (USA)

<MONTH YEAR>

<CUSTOMER NAME>

<CUSTOMER ADDRESS>

<CUSTOMER CITY STATE ZIPCODE>

**This notice applies to your vehicle:** <MODEL YEAR> <BRAND> <CARLINE>, <VIN>

**NHTSA:** 25V638

**Subject: Safety Recall 694T - Front Seat Safety Belt(s)**

Dear Volkswagen Owner,

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act. Volkswagen has decided that a defect, which relates to motor vehicle safety, exists in certain 2025 model year Volkswagen vehicles. Our records show that you are the owner of a vehicle affected by this action.

### **What is the issue?**

One or both front seat safety belt retractors may have been built with a damaged torsion bar. In a crash, a damaged torsion bar could fail, causing the webbing to unwind uncontrollably. If this happens, the safety belt would not provide protection to the occupant, increasing the risk of injury.

### **What will we do?**

To correct this defect, your authorized Volkswagen dealer will replace the affected driver and/or front passenger safety belt(s). This work will take up to three hours to complete and will be performed for you free of charge. Please keep in mind that your dealer may need additional time for the preparation of the work, as well as to accommodate their daily workshop schedule.

### **What should you do?**

Please contact your authorized Volkswagen dealer without delay to schedule this recall work. To set up an appointment online, please visit [www.vw.com/find-a-dealer](http://www.vw.com/find-a-dealer).

### **Precautions you should take:**

If you have concerns about driving your vehicle before the recall remedy has been completed, please contact your authorized Volkswagen dealer for assistance in having the vehicle transported to the dealership for this recall repair, and to obtain alternate transportation while the vehicle is being repaired.

### **Additional Information**

- If you are the lessor and registered owner of the vehicle identified in this action, the law requires you to forward this letter immediately via first-class mail to the lessee within ten (10) days of receipt.
- If your authorized Volkswagen dealer fails or is unable to complete this work free of charge within a reasonable time, if you have changed your address or no longer own the vehicle identified in this letter, or if you should have any questions about this communication, please reach out to us using your preferred method of communication at [www.vw.com/contact](http://www.vw.com/contact) or by calling us at 800-893-5298.
- If you still cannot obtain satisfaction, you may file a complaint with: The Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE., Washington, DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-888-275-9171); or go to <http://www.safercar.gov>.
- To check your vehicle's eligibility for repair under this or any other recall/service campaign, please visit [www.vw.com/owners/recalls](http://www.vw.com/owners/recalls) and enter your Vehicle Identification Number (VIN) into the Recall/Service Campaign Lookup tool.

We apologize for any inconvenience this matter may cause; however, we are taking this action to help ensure your safety and continued satisfaction with your vehicle.

Sincerely,

Volkswagen Customer Protection

## Customer Letter Example (Canada)

<MONTH YEAR>

<CUSTOMER NAME>

<CUSTOMER ADDRESS>

<CUSTOMER CITY STATE ZIPCODE>

**This notice applies to your vehicle:** <MODEL YEAR> <BRAND> <CARLINE>, <VIN>

**Transport Canada Recall:** 2025-503

**Subject: Safety Recall 694T - Front Seat Safety Belt(s)**

Dear Volkswagen Owner,

This notice is sent to you in accordance with the requirements of the *Motor Vehicle Safety Act*. This is to inform you that your vehicle may contain a defect that could affect the safety of a person. Our records show that you are the owner of a vehicle affected by this action.

**What is the issue?**

One or both front seat safety belt retractors may have been built with a damaged torsion bar. In a crash, a damaged torsion bar could fail, causing the webbing to unwind uncontrollably. If this happens, the safety belt would not provide protection to the occupant, increasing the risk of injury.

**What will we do?**

To correct this defect, your authorized Volkswagen dealer will replace the affected driver and/or front passenger safety belt(s). This work will take up to three hours to complete and will be performed for you free of charge. Please keep in mind that your dealer may need additional time for the preparation of the work, as well as to accommodate their daily workshop schedule.

**What should you do?**

Please contact your authorized Volkswagen dealer without delay to schedule this recall work.

**Precautions you should take:**

If you have concerns about driving your vehicle before the recall remedy has been completed, please contact your authorized Volkswagen dealer for assistance in having the vehicle transported to the dealership for this recall repair, and to obtain alternate transportation while the vehicle is being repaired.

**Additional Information**


- If you are the lessor and registered owner of the vehicle identified in this letter, you shall forward this letter (and any subsequent notice, if applicable) to the lessee within ten (10) days of receipt.
- If your authorized Volkswagen dealer fails or is unable to complete this work free of charge within a reasonable time, if you have changed your address or no longer own the vehicle identified in this letter, or if you should have any questions about this communication, please contact Customer Relations, Monday through Friday from 8AM to 8PM EST by phone at 1-800-822-8987 or via our "Contact Us" page at [www.vw.ca](http://www.vw.ca).

We apologize for any inconvenience this matter may cause; however, we are taking this action to help ensure your safety and continued satisfaction with your vehicle.

Sincerely,

Volkswagen Customer Protection

## Repair Overview







- Replace affected front seat belt(s).

### NOTE

- These repair instructions may differ from the labor operations and labor times listed in ELSA.
- Damages resulting from improper repair or failure to follow these work instructions are the dealer's responsibility and are not eligible for reimbursement under this action.
- This procedure must be read in its entirety prior to performing the repair.
- Due to variations in vehicle equipment and options, the steps/illustrations in this work procedure may not identically match all affected vehicles.
- Diagnosis and repair of pre-existing conditions in the vehicle are not covered under this action.
- When working during extreme temperatures, it is recommended that the vehicle be allowed to acclimate inside the shop to avoid temperature-related component damage/breakage.

## Required Tools


	<p>Pry lever -80-200- (or equivalent)</p>		<p>Omega Clip Tool -T40280- (or equivalent)</p>
	<p>Battery Tester/Charger capable of <b>minimum 70 Amp</b> continuous supply</p>		<p>Diagnostic Tester -VAS6150X/6160X- (or equivalent)</p>

## Repair Instruction


### Section A - Check for Previous Repair

#### TIP

If Campaign Completion label is present, no further work is required.

Applicable criteria ID(s)	Campaign/Action Status
01 	Open 

**EXAMPLE**

Campaign/Action	Start	Designation
	2015-11-10	W-SERV_ACT -
	2018-12-13	RECALL -
	2017-05-16	A-RECALL -

**EXAMPLE**

- Enter the VIN in Elsa and proceed to the “Campaign/Action” screen.

#### TIP

On the date of repair, print this screen and keep a copy with the repair order.

- Confirm the Campaign/Action is open <arrow 1>. If the status is closed, no further work is required.
- Note the Applicable Criteria ID <arrow 2> for use in determining the correct work to be done and corresponding parts associated.

#### **CRITICAL REPAIR STEP**

 **STOP!** 


All campaigns/actions with a repair available must be performed in order of the Start date <arrow 3>. The oldest should be performed first (unless otherwise noted in the repair instructions).

**Proceed to Section B**

## Section B – Repair Procedure

### **⚠ WARNING**

Risk of injury. Refer to “Warning and Safety Precautions”, found in **Appendix A** at the end of this document.



### **⚠ CAUTION**

**Pyrotechnic components can deploy unexpectedly. A risk of injury is possible.**

- Keep as far away as possible from the pyrotechnic component when switching the ignition on.
- Discharge static electricity by briefly touching the door striker prior to working on the airbag system.

### **ⓘ NOTE**

The criteria assigned to the vehicle will determine which seat belt requires replacement:

- 01 = Driver front seat belt
  - 02 = Passenger front seat belt
  - 01 + 02 = Both front seat belts
- Replace the affected seat belt assembly per the ELSA repair manual:
    - *Repair manual > Body > Body Interior > 69 Passenger Protection, Airbags, Seat Belts > Seat Belts > Left/Right Front Seat Belt NX10/NX11, Removing and Installing.*
  - Connect the battery charger.
  - Scan the vehicle using the latest version of ODIS.
  - Clear any faults that may have generated from disconnection of the battery.

**Proceed to Section C**

## Section C – Campaign Completion Label

### Install Campaign Completion Label

- Fill out and affix Campaign Completion Label, part number CAMP 010 000, next to the vehicle emission control information label.

 **TIP**

Ensure Campaign Completion Label does not cover any existing label(s).

**Proceed to Section D**

## Section D - Parts Return/Disposal

Properly store (retain), destroy or dispose of removed parts in accordance with all state/province and local requirements, unless otherwise indicated and/or requested through the Warranty Parts Portal (WPP) for U.S. and the Part Destruction and Core Disposition Report for Canada.

## Appendix A – Warning and Safety Precautions

### WARNING

#### General Safety Precautions when Working with Pyrotechnic Components:

- Pyrotechnic components always contain propellant that generates a gas during combustion. In some components, there is also a supply of pressurized gas to ensure this gas is generated
- This pressurized gas is stored under high pressure in a compressed gas container. Pyrotechnic components are triggered by electrical/mechanical igniters.
- Only trained personnel should perform testing, assembly and servicing work. Airbags do not have a replacement interval.
- Never check with test lamps, voltmeter or ohmmeters.
- Only check pyrotechnic components when they are installed in the vehicle using vehicle diagnosis, testing and information systems approved by the manufacturer.
- When working on pyrotechnic components and the airbag control module, disconnect the battery ground strap while the ignition is switched on. Then cover the negative terminal.
- Wait 10 seconds after disconnecting the battery.
- The ignition must be SWITCHED ON when connecting the battery. There should not be anyone inside the vehicle when doing this.
- Exception: vehicles with batteries in the passenger compartment. In this case, stay outside the range of the airbags and seat belts.
- Wash your hands after touching ignited pyrotechnic components from the restraint system.
- Do not open or repair pyrotechnic components. Use only new components to reduce the risk of injury.
- Do not install pyrotechnic components that have fallen onto a hard surface or show signs of damage.
- Discharge static electricity before handling pyrotechnic components, for example before disconnecting the electrical connector. This can be done by touching grounded metal objects such as the door striker pin.
- Install pyrotechnic components immediately after removing them from their transport packaging. If you must stop working, store the pyrotechnic component in its original transport packaging.
- Do not leave pyrotechnic components lying in the open unattended.
- Do not treat pyrotechnic components with grease, cleaning solutions or similar products.
- Do not expose pyrotechnic components to temperatures above 100 °C, even for brief periods of time.