



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

26E040

Manufacturer Name: Chrysler (FCA US, LLC)

Submission Date: Jul 01, 2026

NHTSA Recall No.: 26E040

Manufacturer Recall No.: 63D

Manufacturer Information

Population

Manufacturer Name: Chrysler (FCA US, LLC)

Address: 800 Chrysler Drive
CIMS 482-00-91
Auburn Hills MI, 48326-
2757

Total number of potentially involved: 628

Estimated percentage with defect: 77%

Equipment Information

Brand / Trade 1: MOPAR

Model: HEADLAMP

Part Number: 68530384AD

Type:

Function:

Size:

Production Dates: Oct 29, 2025 - Feb 11, 2026

Number of potentially involved: 18

Descriptive Information:

Some premium headlamp assemblies may have been produced with internal harness connector terminals that were not fully connected which may turn off the Parking Lamps and/or Daytime Running Lamps ("DRLs").

Supplier shipment information and sales records were used to identify the headlamp assemblies which were manufactured between October 29, 2025, and February 11, 2026.

Similar headlamp assemblies not included in this recall were produced before or after the suspect build period or with fully connected terminals.

Brand / Trade 2: MOPAR

Model: HEADLAMP

Part Number: 68530384AE

Type:

Function:

Part 573 Safety Recall Report

26E040**Size:****Production Dates:** Oct 29, 2025 - Feb 11, 2026**Number of potentially involved:** 255**Descriptive Information:**

Some premium headlamp assemblies may have been produced with internal harness connector terminals that were not fully connected which may turn off the Parking Lamps and/or DRLs.

Supplier shipment information and sales records were used to identify the headlamp assemblies which were manufactured between October 29, 2025, and February 11, 2026.

Similar headlamp assemblies not included in this recall were produced before or after the suspect build period or with fully connected terminals.

Brand / Trade 3: MOPAR**Model:** HEADLAMP**Part Number:** 68530385AD**Type:****Function:****Size:****Production Dates:** Oct 29, 2025 - Feb 11, 2026**Number of potentially involved:** 19**Descriptive Information:**

Some premium headlamp assemblies may have been produced with internal harness connector terminals that were not fully connected which may turn off the Parking Lamps and/or DRLs.

Supplier shipment information and sales records were used to identify the headlamp assemblies which were manufactured between October 29, 2025, and February 11, 2026.

Similar headlamp assemblies not included in this recall were produced before or after the suspect build period or with fully connected terminals.

Brand / Trade 4: MOPAR**Model:** HEADLAMP**Part Number:** 68530385AE**Type:****Function:****Size:****Production Dates:** Oct 29, 2025 - Feb 11, 2026**Number of potentially involved:** 336**Descriptive Information:**

Part 573 Safety Recall Report

26E040

Some premium headlamp assemblies may have been produced with internal harness connector terminals that were not fully connected which may turn off the Parking Lamps and/or DRLs.

Supplier shipment information and sales records were used to identify the headlamp assemblies which were manufactured between October 29, 2025, and February 11, 2026.

Similar headlamp assemblies not included in this recall were produced before or after the suspect build period or with fully connected terminals.

Defect / Noncompliance Description

Description of the defect or noncompliance:

Federal Motor Vehicle Safety Standard ("FMVSS") No. 108 S6.1.1 referencing Table I requires subject equipments' Parking Lamps and DRL's (if equipped) to be steady burning when activated. Suspect vehicles may illuminate the DRLs and Parking Lamps intermittently.

FMVSS1: 108 - Lamps, reflective devices, and assoc. Equipment

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

Parking lamps and DRLs which turn off or flicker when not intended may reduce the conspicuity of the vehicle which may cause a vehicle crash without prior warning.

Description of the cause:

Identification of any warning that can occur:

None prior to failure. However, some customers may notice degraded function of the lamps and/or a message in the cluster.

Component Manufacturer

Tier of Supplier:

Supplier Type:

Name: Marelli North America

Address: 26555 Northwestern Hwy
Southfield MI, 48033

Country: United States

Involved Components

Part 573 Safety Recall Report

26E040

Component Name 1: HEADLAMP

Component Description: HEADLAMP

Component Part Number: 68530384AD

Component Name 2: HEADLAMP

Component Description: HEADLAMP

Component Part Number: 68530384AE

Component Name 3: HEADLAMP

Component Description: HEADLAMP

Component Part Number: 68530385AD

Component Name 4: HEADLAMP

Component Description: HEADLAMP

Component Part Number: 68530385AE

Purchaser Information

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name:

Address:

Country:

Chronology

- On April 16, 2026, the FCA US LLC ("FCA US") Technical Safety and Regulatory Compliance ("TSRC") organization opened an investigation into some 2026 MY Ram 1500 vehicles with premium headlamp assemblies (LM6) that may experience intermittent Parking Lamps and DRLs.
- From April 2026 through May 2026, FCA US TSRC met with FCA US Engineering to understand root cause, customer consequence and vehicle scope.
- From April 2026 through May 2026, FCA US TSRC conducted an analysis of field records and customer assistance records to understand potential customer consequences.
- On June 10, 2026, FCA US TSRC organization recognized that a build issue exists on certain premium headlamp assemblies, potentially resulting in a noncompliance with FMVSS No. 108.

Part 573 Safety Recall Report

26E040

- On June 25, 2026, FCA US determined, through the Vehicle Regulations Committee, that a noncompliance to Federal Motor Vehicle Safety Standard No. 108 exists in certain motor vehicle equipment.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Inspect, Replace, Repurchase

Consumer Advisories: ☐ Do Not Drive ☐ Park Outside

Description of remedy program:

FCA US will conduct a voluntary safety recall on all affected headlamp assemblies to inspect, and if necessary, replace the headlamp assembly if installed on a vehicle or repurchase the headlamp assembly if not installed on a vehicle.

How remedy component differs from recalled component:

Remedy component is a headlamp assembly that was produced with fully connected terminals.

Identify how/when recall condition was corrected in production:

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Recall Schedule

Description of recall schedule:

****07/01/2026:** FCA US will notify dealers on or about 07/02/2026 and begin notifying owners on or about 07/30/2026.

Planned Dealer Notification Date: Jul 02, 2026 - Jul 02, 2026

☐ No Dealers

Planned Interim Owner Notification Date: Jul 30, 2026 - Jul 30, 2026

☐ No Owners

Planned Remedy Owner Notification Date:

☐ Phased Recall