



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

26V115

Manufacturer Name: BMW of North America, LLC

Submission Date: Feb 26, 2026

NHTSA Recall No.: 26V115

Manufacturer Recall No.:

Manufacturer Information

Population

Manufacturer Name: BMW of North America,
LLC
Address: P.O. Box 1227
Westwood NJ, 07675-1227

Total number of potentially involved: 1
Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2026-2026 BMW S 1000 RR

Product Category: Motorcycles

Product Type: Motorcycles

Fuel / Propulsion: Spark Ignition Fuel

Production Dates: Jan 09, 2026 - Jan 09, 2026

Number of potentially involved: 1

Descriptive Information:

Approximately one (1) motorcycle was produced with a combination switch, which includes turn signal functionality, that may not have been produced to specifications by the supplier.

Basis for recall population determination:

Motorcycle manufacturing information and supplier production records were reviewed to determine the number and production date range of potentially affected motorcycles.

Recall component difference to non-recall component: The combination switch may not have been produced to specifications by the supplier.

Defect / Noncompliance Description

Description of the defect or noncompliance:

This noncompliance recall involves the turn signal toggle on the combination switch. The switch may not have been produced to specifications by the supplier. As a result, the turn signal reset button could be unintentionally activated at the same time as the turn signal itself, leading to a "double signal". As a consequence, the turn signal may be deactivated immediately after activation.

Part 573 Safety Recall Report

26V115

FMVSS1: 108 - Lamps, reflective devices, and assoc. Equipment

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

If the turn signal is not functioning to specifications, this could increase the risk of a crash.

Description of the cause:

Identification of any warning that can occur:

If the “double signal” occurs, the green turn signal symbols in the display will turn off immediately after being illuminated.

Component Manufacturer

Tier of Supplier: Tier 1

Supplier Type:

Name: Sensata Technologies Holland BV

Address: Jan-Tinbergen-Straat 80
Hengelo Foreign States, 7559 SP

Country: Netherlands

Involved Components

Component Name 1: Multifunction switch left

Component Description: Multifunction switch left

Component Part Number: 8394465

Chronology

In January 2026, BMW became aware of an increasing rate of combination switches that did not meet functional specifications during end-of-line testing at a motorcycle assembly plant. An engineering investigation was initiated. Potentially suspect motorcycles were placed on a delivery hold, and the supplier was contacted.

Switches were tested and evaluated, and supplier production data was analyzed.

Part 573 Safety Recall Report

26V115

The analysis found that, as a result of improper rework of supplier production tooling, potentially affected motorcycles could have been equipped with combination switches that did not meet specifications during a specific period of time.

On February 19, 2026, BMW decided to conduct a voluntary non-compliance recall.

BMW has not received any reports, nor is BMW otherwise aware, of any accidents or injuries related to this issue.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Replace

Consumer Advisories: Do Not Drive Park Outside

Description of remedy program:

The combination switch will be replaced.

How remedy component differs from recalled component:

Recall component:
Multifunction switch left – part number: 8394465

Identify how/when recall condition was corrected in production:

Reimbursement Plan

Description of reimbursement program:

Period of reimbursement:

Costs to be reimbursed:

Address for reimbursement claims:

Recall Schedule

Description of recall schedule:

Part 573 Safety Recall Report**26V115**

Notification to dealers is planned to begin and end on February 26, 2026.
Notification to owners is not necessary, as no motorcycles have been retailed.

Planned Dealer Notification Date: Feb 26, 2026 - Feb 26, 2026

No Dealers

Planned Interim Owner Notification Date:

No Owners

Planned Remedy Owner Notification Date:

Phased Recall

Date when VIN will be searchable: Apr 20, 2026