



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

26V127

Manufacturer Name: General Motors, LLC

Submission Date: Mar 05, 2026

NHTSA Recall No.: 26V127

Manufacturer Recall No.: N252542620

Manufacturer Information

Population

Manufacturer Name: General Motors, LLC

Address: 29427 Louis Chevrolet
Road
MAIL CODE 480-210-2V
WARREN MI, 48093

Total number of potentially involved: 826

Estimated percentage with defect: 95.4%

Vehicle Information

Vehicle 1: 2026-2026 GMC SAVANA

Product Category: Light Vehicles

Product Type:

Fuel / Propulsion: Spark Ignition Fuel

Production Dates: Oct 27, 2025 - Nov 26, 2025

Number of potentially involved: 192

Descriptive Information:

Manufacturing records were used to identify vehicles that may have had a right rear tire damaged during the alignment process in the plant.

Only the cutaway (incomplete/chassis cab) model produced by International Motors is included in this recall. Other (non-cutaway) models are not included.

Vehicle 2: 2025-2025 GMC SAVANA

Product Category: Light Vehicles

Product Type:

Fuel / Propulsion: Spark Ignition Fuel

Production Dates: Oct 07, 2025 - Oct 09, 2025

Number of potentially involved: 7

Descriptive Information:

Manufacturing records were used to identify vehicles that may have had a right rear tire damaged during the alignment process in the plant.

Part 573 Safety Recall Report

26V127

Only the cutaway (incomplete/chassis cab) model produced by International Motors is included in this recall. Other (non-cutaway) models are not included.

Vehicle 3: 2026-2026 CHEVROLET EXPRESS

Product Category: Light Vehicles

Product Type:

Fuel / Propulsion: Spark Ignition Fuel

Production Dates: Oct 20, 2025 - Nov 26, 2025

Number of potentially involved: 528

Descriptive Information:

Manufacturing records were used to identify vehicles that may have had a right rear tire damaged during the alignment process in the plant.

Only the cutaway (incomplete/chassis cab) model produced by International Motors is included in this recall. Other (non-cutaway) models are not included.

Vehicle 4: 2025-2025 CHEVROLET EXPRESS

Product Category: Light Vehicles

Product Type:

Fuel / Propulsion: Spark Ignition Fuel

Production Dates: Sep 23, 2025 - Oct 14, 2025

Number of potentially involved: 99

Descriptive Information:

Manufacturing records were used to identify vehicles that may have had a right rear tire damaged during the alignment process in the plant.

Only the cutaway (incomplete/chassis cab) model produced by International Motors is included in this recall. Other (non-cutaway) models are not included.

Defect / Noncompliance Description

Description of the defect or noncompliance:

General Motors has decided that a defect which relates to motor vehicle safety may exist in certain

Part 573 Safety Recall Report

26V127

2025 – 2026 model year Chevrolet Express Cutaway and GMC Savana Cutaway vehicles. These vehicles may have a tire with sidewall damage.

FMVSS1:

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

A tire with sidewall damage may experience sudden air loss, potentially causing reduced or loss of vehicle control, which increases the risk of a crash.

Description of the cause:

International Motors, the manufacturer of these vehicles, determined that a broken roller in a wheel alignment fixture caused the fixture to gouge the sidewalls of right rear tires during the vehicle manufacturing process.

Identification of any warning that can occur:

Component Manufacturer

Tier of Supplier: Tier 1

Supplier Type: OEM

Name: International Motors, LLC

Address: 2701 Navistar Drive
Lisle IL, 60532

Country: United States

Involved Components

Component Name 1: TIRE

Component Description: Tire

Component Part Number: 19296018

Chronology

On December 18, 2025, a GM brand quality manager submitted a report to GM's Speak Up For Safety (SUFS) program following a report from a fleet customer that they had received some vehicles with a gouge in the sidewall of the right rear tire. On January 7, 2026, International Motors identified a broken roller on the wheel alignment fixture in their assembly plant as the cause of the tire damage. On January

Part 573 Safety Recall Report

26V127

12, 2026, International Motors provided a list of potentially affected VINs. GM opened a product investigation on January 13, 2026. An analysis of field data completed on February 10, 2026, identified 37 complaints potentially related to this condition. GM received these reports between December 18, 2025, and January 16, 2026. GM is not aware of any crashes or injuries associated with this condition. On February 26, 2026, GM's Safety and Field Decision Authority decided to conduct a safety recall.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Inspect, Replace**Consumer Advisories:** ☐ Do Not Drive ☐ Park Outside**Description of remedy program:**

Dealers will inspect all tire sidewalls and replace tires with sidewall damage.

How remedy component differs from recalled component:

Replacement tires are new and have no sidewall damage.

Identify how/when recall condition was corrected in production:

The roller on the wheel alignment fixture at International Motors' assembly plant was fixed on November 25, 2025.

Reimbursement Plan

Description of reimbursement program:

Pursuant to 49 C.F.R. § 573.13(d)(1), all covered vehicles are under warranty, so reimbursement is not offered.

Period of reimbursement:**Costs to be reimbursed:****Address for reimbursement claims:**

Recall Schedule

Description of recall schedule:

Dealers will be notified on March 5, 2026. Owner notification of an available remedy is estimated to

Part 573 Safety Recall Report

26V127

start mailing on April 20, 2026.

Planned Dealer Notification Date: Mar 05, 2026 - Mar 05, 2026

☐ No Dealers

Planned Interim Owner Notification Date:

☐ No Owners

Planned Remedy Owner Notification Date: Apr 20, 2026 - Apr 20, 2026

☐ Phased Recall

Date when VIN will be searchable: Mar 05, 2026