



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

26V143

Manufacturer Name: BMW of North America, LLC

Submission Date: Mar 12, 2026

NHTSA Recall No.: 26V143

Manufacturer Recall No.:

Manufacturer Information

Population

Manufacturer Name: BMW of North America,
LLC
Address: P.O. Box 1227
Westwood NJ, 07675-1227

Total number of potentially involved: 102
Estimated percentage with defect: 30%

Vehicle Information

Vehicle 1: 2020-2026 Rolls-Royce Cullinan

Product Category: Light Vehicles

Product Type: Multipurpose Passenger Vehicle

Fuel / Propulsion: Spark Ignition Fuel

Production Dates: Nov 27, 2019 - Nov 19, 2025

Number of potentially involved: 102

Descriptive Information:

Cullinan

Approximately 102 vehicles have been assembled with fixing bolts on the left and right side of the rear seat safety belts, or on the rear bench seat configuration backrest locking brackets, one of which may not have been tightened to specifications on the vehicle body.

Basis for recall population determination: Vehicle assembly information was used to determine the specific dates of potentially affected vehicles.

Recall component difference to non-recall component: The fixing bolts for the left and right side rear seat safety belts or for the rear bench seat configuration backrest locking brackets may not have been tightened to specifications.

Defect / Noncompliance Description

Description of the defect or noncompliance:

This safety recall involves bolts which fix the left and right side rear seat safety belts to the vehicle body, or bolts which fix the rear bench seat configuration backrest locking brackets to the vehicle body.

Part 573 Safety Recall Report

26V143

One of these bolts may not have been tightened to specifications and, over time, could loosen, and also potentially cause damage to either the left or right side rear seat safety belt webbing.

FMVSS1:

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

In the event of a collision, either the left or right side rear seat safety belts may not provide sufficient restraint, or the rear bench seat backrest may move forward under load from goods in the luggage compartment. Both of these conditions could increase the risk of injury.

Description of the cause:

Identification of any warning that can occur:

Owners of the 102 vehicles affected by this recall will be advised not to use the rear seating area or carry goods in the rear luggage compartment until the vehicle has been inspected and, if applicable, remedied.

Component Manufacturer

Tier of Supplier:

Supplier Type:

Name: Rolls-Royce Motor Cars, Ltd.

Address:

Country:

Involved Components

Component Name 1: Fixing Bolts and Safety Belts

Component Description: Fixing Bolts and Safety Belts

Component Part Number: Bolts - (07119907361, 07149148299, 07129908679) Belts - (7489785 - 7489804)

Chronology

On January 23, 2026, during routine quality checks (specifically, road testing) of a Model Year 2026 Rolls-Royce Cullinan, a rattling noise was noticed near the right-hand rear location of the vehicle's C-pillar. Upon removing the applicable rear seat cover, a bolt for the safety belt retractor was found to be loose. An engineering investigation was initiated.

Part 573 Safety Recall Report

26V143

A review of all vehicles within the vehicle assembly plant was immediately performed. A second vehicle was identified with a similar condition.

On January 26th, a containment action via a vehicle block was implemented at the plant.

In February, a review of electronic records involving torque data was initiated. A review of this data included relevant plant production and quality personnel as well as engineering and technical specialists. For vehicle records that required additional and/or alternative analysis, other methods including scripts for large data set queries were utilized. Further analysis and reviews were conducted.

Vehicle assembly information was reviewed to determine the number and production dates of potentially affected vehicles.

On March 5, 2026, Rolls-Royce decided to conduct a voluntary safety recall.

Rolls-Royce has not received any reports, nor is Rolls-Royce otherwise aware, of any accidents or injuries related to this issue.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Inspect, Replace

Consumer Advisories: Do Not Drive Park Outside

Description of remedy program:

The possibly affected fixing bolts will be checked and either tightened to specifications or replaced as necessary. The condition of the left and right side rear seat safety belts will be checked and, if necessary, replaced.

Owners will be notified, including by First Class mail, and instructed to take their vehicle to an authorized Rolls-Royce Motor Cars dealer to have the remedy performed free of charge.

How remedy component differs from recalled component:

Fixing Bolts and Safety Belts
 Bolts - (07119907361, 07149148299, 07129908679) - re Location
 Belts - (7489785 - 7489804) - re Location / Color

Identify how/when recall condition was corrected in production:

Reimbursement Plan

Description of reimbursement program:

Part 573 Safety Recall Report

26V143

If this condition were noticed on a potentially affected vehicle prior to this recall, the remedy would be covered by the Rolls-Royce Motor Cars New Vehicle Limited Warranty program. Therefore, reimbursement for a pre-notification remedy re Part 573.13 and Part 577.11 is not necessary.

Period of reimbursement:

Costs to be reimbursed:

Address for reimbursement claims:

Recall Schedule

Description of recall schedule:

Dealer notification is planned to begin and end on March 19, 2026.
Owner notification is planned to begin and end on May 4, 2026.

Planned Dealer Notification Date: Mar 19, 2026 - Mar 19, 2026 No Dealers

Planned Interim Owner Notification Date: No Owners

Planned Remedy Owner Notification Date: May 04, 2026 - May 04, 2026 Phased Recall

Date when VIN will be searchable: