



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

26V163

Manufacturer Name: Jaguar Land Rover North America, LLC

Submission Date: Mar 18, 2026

NHTSA Recall No.: 26V163

Manufacturer Recall No.: D098

Manufacturer Information

Population

Manufacturer Name: Jaguar Land Rover North America, LLC

Address: 100 Jaguar Land Rover
Way
Mahwah NJ, 07495

Total number of potentially involved: 498

Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2026-2026 LAND ROVER DEFENDER

Product Category: Light Vehicles

Product Type: Multipurpose Passenger Vehicle

Fuel / Propulsion:

Production Dates: Nov 03, 2025 - Feb 20, 2026

Number of potentially involved: 498

Descriptive Information:

Jaguar Land Rover is conducting a voluntary safety recall campaign involving certain 2026 MY Land Rover Defender vehicles built at the Nitra Vehicle Assembly Plant from November 3, 2025 - February 20, 2026. 498 Land Rover Defender vehicles in the United States and Federalized Territories. The basis for the recall population of Land Rover Defenders was determined by matching the supplier raw material consumption records through to batch component production into vehicle production.

Defect / Noncompliance Description

Description of the defect or noncompliance:

A concern has been identified where the third-row lower seat belt anchorage bracket may contain a weld stud of insufficient ISO strength due to material contamination at the supplier.

FMVSS1:

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

Part 573 Safety Recall Report

26V163

An insufficiently strong weld stud in this position could result in the safety restraint system not functioning correctly in the event of a crash, increasing the risk of occupant injury.

Description of the cause:

Identification of any warning that can occur:

Component Manufacturer

Tier of Supplier:

Supplier Type:

Name: Belrise Industries

Address: Belrise Industries
Ranjangaon
Pune Foreign States, 412209

Country: India

Involved Components

Component Name 1: Lower seat belt anchorage bracket LH

Component Description: Lower seat belt anchorage bracket LH

Component Part Number: L8B2104B37AE

Component Name 2: Lower seat belt anchorage bracket RH

Component Description: Lower seat belt anchorage bracket RH

Component Part Number: L8B2104B36AE

Chronology

On 26 February 2026, a pre-stop shipment meeting was held following a small number of reports in the vehicle assembly plant of third row lower seat belt anchorage weld studs fracturing during manual torque operation. A cross-functional team was set up to establish whether there was any risk to the strength of bolts fitted to already built vehicles. It was reported that, whilst not conclusive, analysis of tooling records indicated potential anomalous stud performance in vehicles manufactured from 09 December 2025. It was decided in the abundance of caution to issue a Stop Ship order and pause the handover of affected vehicles to customers whilst the investigation continued.

Part 573 Safety Recall Report

26V163

On 05 March 2026, following results from a supplier 8D investigation, material analysis and component shipment records, the pre stop shipment meeting was reconvened and concluded that the earliest date that at-risk parts could have been fitted to vehicles was 04 November 2025. The Stop Ship vehicle range was extended, and as it was established that there were vehicles which were likely to have been handed over to customers. A Product Safety and Compliance Committee (PSCC) investigation was opened.

On 06 March 2026, the PSCC reviewed the issue and heard that destructive testing had been carried out on unfractured weld studs in the at-risk range. The results of this testing confirmed that the material composition of weld studs on customer vehicles was likely to be substandard. It was decided to refer the matter to the PSCC Decision Forum for determination.

On 12 March 2026, the PSCC Decision Forum determined that the defect represents an unreasonable risk to safety and instructed that a safety recall be carried out to remedy the affected vehicles.

JLR has not received any claims or field reports in the US related to this concern.

There have been no reported accidents, injuries or fires in the US as a result of this concern.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Repair, Replace

Consumer Advisories: ☐ Do Not Drive ☐ Park Outside

Description of remedy program:

Vehicles will have the third-row lower seat belt anchorage bracket replaced.

There will be no charge to the owners for this permanent repair.

How remedy component differs from recalled component:

The replacement parts incorporate weld studs which have been through additional quality control processes at the supplier and are assured to be of the correct material specification.

Identify how/when recall condition was corrected in production:

The defect was cut off in production when components of assured material quality were manufactured and shipped to JLR's vehicle assembly plant for use on vehicles from 27 February 2026.

Part 573 Safety Recall Report

26V163

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Recall Schedule

Description of recall schedule:

Notifications to dealers will occur on or before April 2, 2026. Distribution of owner notification letters will occur on or before May 15, 2026.

Planned Dealer Notification Date: Apr 02, 2026 - Apr 02, 2026

☐ No Dealers

Planned Interim Owner Notification Date:

☐ No Owners

Planned Remedy Owner Notification Date: May 15, 2026 - May 15, 2026

☐ Phased Recall

Date when VIN will be searchable: