



U.S. Department  
of Transportation

National Highway  
Traffic Safety  
Administration

## Part 573 Safety Recall Report

## 26V179

**Manufacturer Name:** Toyota Motor Engineering & Manufacturing

**Submission Date:** Mar 24, 2026

**NHTSA Recall No.:** 26V179

**Manufacturer Recall No.:** See attached Part573

### Manufacturer Information

### Population

**Manufacturer Name:** Toyota Motor Engineering & Manufacturing

**Address:** 6565 Headquarters Drive  
Plano TX, 75024

**Total number of potentially involved:** 8,230

**Estimated percentage with defect:** 100%

### Vehicle Information

**Vehicle 1:** 2024-2026 TOYOTA TUNDRA HYBRID

**Product Category:** Light Vehicles

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Apr 08, 2024 - Aug 26, 2025

**Number of potentially involved:** 47

**Descriptive Information:**

Although the involved vehicles are within the above production period range, not all vehicles in this range were sold in the U.S. Other Toyota/Lexus vehicles are not covered by this report because they either (1) did not have understated load capacity modification labels; (2) complied with the applicable requirements in FMVSS No. 110, paragraph S10; or (3) were not affected by this system error.

**Vehicle 2:** 2024-2025 TOYOTA TUNDRA

**Product Category:** Light Vehicles

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Apr 08, 2024 - Aug 01, 2025

**Number of potentially involved:** 250

**Descriptive Information:**

Although the involved vehicles are within the above production period range, not all vehicles in this range were sold in the U.S. Other Toyota/Lexus vehicles are not covered by this report because they

**Part 573 Safety Recall Report****26V179**

either (1) did not have understated load capacity modification labels; (2) complied with the applicable requirements in FMVSS No. 110, paragraph S10; or (3) were not affected by this system error.

**Vehicle 3:** 2024-2025 TOYOTA TACOMA HYBRID

**Product Category:** Light Vehicles

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** May 28, 2024 - Oct 10, 2025

**Number of potentially involved:** 1,223

**Descriptive Information:**

Although the involved vehicles are within the above production period range, not all vehicles in this range were sold in the U.S. Other Toyota/Lexus vehicles are not covered by this report because they either (1) did not have understated load capacity modification labels; (2) complied with the applicable requirements in FMVSS No. 110, paragraph S10; or (3) were not affected by this system error.

**Vehicle 4:** 2024-2025 TOYOTA TACOMA

**Product Category:** Light Vehicles

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Sep 03, 2024 - Sep 10, 2025

**Number of potentially involved:** 56

**Descriptive Information:**

Although the involved vehicles are within the above production period range, not all vehicles in this range were sold in the U.S. Other Toyota/Lexus vehicles are not covered by this report because they either (1) did not have understated load capacity modification labels; (2) complied with the applicable requirements in FMVSS No. 110, paragraph S10; or (3) were not affected by this system error.

**Vehicle 5:** 2025-2025 TOYOTA SEQUOIA HYBRID

**Product Category:** Light Vehicles

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Nov 13, 2024 - Feb 10, 2025

**Number of potentially involved:** 10

**Descriptive Information:**

Although the involved vehicles are within the above production period range, not all vehicles in this range were sold in the U.S. Other Toyota/Lexus vehicles are not covered by this report because they

**Part 573 Safety Recall Report****26V179**

either (1) did not have understated load capacity modification labels; (2) complied with the applicable requirements in FMVSS No. 110, paragraph S10; or (3) were not affected by this system error.

**Vehicle 6:** 2024-2025 TOYOTA RAV4 HYBRID

**Product Category:** Light Vehicles

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Apr 17, 2024 - Oct 27, 2025

**Number of potentially involved:** 40

**Descriptive Information:**

Although the involved vehicles are within the above production period range, not all vehicles in this range were sold in the U.S. Other Toyota/Lexus vehicles are not covered by this report because they either (1) did not have understated load capacity modification labels; (2) complied with the applicable requirements in FMVSS No. 110, paragraph S10; or (3) were not affected by this system error.

**Vehicle 7:** 2024-2025 TOYOTA LAND CRUISER HYBRID

**Product Category:** Light Vehicles

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Apr 01, 2024 - Aug 25, 2025

**Number of potentially involved:** 1,641

**Descriptive Information:**

Although the involved vehicles are within the above production period range, not all vehicles in this range were sold in the U.S. Other Toyota/Lexus vehicles are not covered by this report because they either (1) did not have understated load capacity modification labels; (2) complied with the applicable requirements in FMVSS No. 110, paragraph S10; or (3) were not affected by this system error.

**Vehicle 8:** 2025-2026 TOYOTA GRAND HIGHLANDER HYBRID

**Product Category:** Light Vehicles

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Feb 25, 2025 - Oct 30, 2025

**Number of potentially involved:** 21

**Descriptive Information:**

Although the involved vehicles are within the above production period range, not all vehicles in this range were sold in the U.S. Other Toyota/Lexus vehicles are not covered by this report because they

**Part 573 Safety Recall Report****26V179**

either (1) did not have understated load capacity modification labels; (2) complied with the applicable requirements in FMVSS No. 110, paragraph S10; or (3) were not affected by this system error.

**Vehicle 9:** 2025-2025 TOYOTA GRAND HIGHLANDER

**Product Category:** Light Vehicles

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Feb 25, 2025 - Jul 28, 2025

**Number of potentially involved:** 2

**Descriptive Information:**

Although the involved vehicles are within the above production period range, not all vehicles in this range were sold in the U.S. Other Toyota/Lexus vehicles are not covered by this report because they either (1) did not have understated load capacity modification labels; (2) complied with the applicable requirements in FMVSS No. 110, paragraph S10; or (3) were not affected by this system error.

**Vehicle 10:** 2025-2025 TOYOTA CROWN SIGNIA

**Product Category:** Light Vehicles

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Jul 02, 2024 - Sep 14, 2025

**Number of potentially involved:** 217

**Descriptive Information:**

Although the involved vehicles are within the above production period range, not all vehicles in this range were sold in the U.S. Other Toyota/Lexus vehicles are not covered by this report because they either (1) did not have understated load capacity modification labels; (2) complied with the applicable requirements in FMVSS No. 110, paragraph S10; or (3) were not affected by this system error.

**Vehicle 11:** 2025-2025 Lexus TX500h

**Product Category:**

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Aug 07, 2025 - Oct 09, 2025

**Number of potentially involved:** 1

**Descriptive Information:**

Although the involved vehicles are within the above production period range, not all vehicles in this range were sold in the U.S. Other Toyota/Lexus vehicles are not covered by this report because they

**Part 573 Safety Recall Report****26V179**

either (1) did not have understated load capacity modification labels; (2) complied with the applicable requirements in FMVSS No. 110, paragraph S10; or (3) were not affected by this system error.

**Vehicle 12:** 2025-2026 Lexus TX350

**Product Category:**

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Jun 05, 2025 - Jun 05, 2025

**Number of potentially involved:** 6

**Descriptive Information:**

Although the involved vehicles are within the above production period range, not all vehicles in this range were sold in the U.S. Other Toyota/Lexus vehicles are not covered by this report because they either (1) did not have understated load capacity modification labels; (2) complied with the applicable requirements in FMVSS No. 110, paragraph S10; or (3) were not affected by this system error.

**Vehicle 13:** 2025-2025 Lexus NX350h

**Product Category:**

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Jul 04, 2024 - Sep 05, 2024

**Number of potentially involved:** 7

**Descriptive Information:**

Although the involved vehicles are within the above production period range, not all vehicles in this range were sold in the U.S. Other Toyota/Lexus vehicles are not covered by this report because they either (1) did not have understated load capacity modification labels; (2) complied with the applicable requirements in FMVSS No. 110, paragraph S10; or (3) were not affected by this system error.

**Vehicle 14:** 2024-2025 Lexus GX550

**Product Category:**

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Apr 01, 2024 - Sep 18, 2025

**Number of potentially involved:** 4,709

**Descriptive Information:**

Although the involved vehicles are within the above production period range, not all vehicles in this range were sold in the U.S. Other Toyota/Lexus vehicles are not covered by this report because they

# Part 573 Safety Recall Report

# 26V179

either (1) did not have understated load capacity modification labels; (2) complied with the applicable requirements in FMVSS No. 110, paragraph S10; or (3) were not affected by this system error.

## Defect / Noncompliance Description

### Description of the defect or noncompliance:

Due to a system error, the total weight of the accessories installed in the subject vehicles by Toyota were miscalculated. In these vehicles, this resulted in a load carrying capacity modification label with an understated reduction in load carrying capacity greater than one percent of the actual added weight. As a result, the subject vehicles do not meet the requirements of FMVSS No. 110, paragraph S10.2. If a driver follows the understated label and loads the vehicle to the indicated load carrying capacity, it is possible that the vehicle will be loaded beyond its load carrying capacity, increasing the risk of a crash.

**FMVSS1:** 110 - Tire selection and rims

**FMVSS2:**

### Description of the safety risk, including crash, fire, death, injury:

If a driver follows the understated label and loads the vehicle to the indicated load carrying capacity, it is possible that the vehicle will be loaded beyond its load carrying capacity, increasing the risk of a crash.

### Description of the cause:

### Identification of any warning that can occur:

## Component Manufacturer

**Tier of Supplier:**

**Supplier Type:**

**Name:**

**Address:**

**Country:**

## Involved Components

**Component Name 1:**

# Part 573 Safety Recall Report

# 26V179

**Component Description:**

**Component Part Number:**

## Chronology

In August 2025, during an internal audit and preparation to launch a vehicle model, it was discovered that the accessory weight shown on the load carrying capacity modification label could be different from the actual total weight of added accessories. Further investigation revealed that this condition was due to a software error in the system that is used to prepare the information that is used to generate the labels and that this condition may affect other vehicles. From November 2025 to February 2026, the affected processing period (April 2024 to November 2025) was identified and the weight values that were used to print the labels of the affected vehicles were collected. From February to March 2026, Toyota conducted a VIN-by-VIN review on the affected vehicles to compare the weights that were used to print the labels to the weight of the total accessories installed by Toyota. On March 17, 2026, Toyota decided that the subject vehicles do not meet the requirement of FMVSS No. 110 paragraphs S10.2.

**Related NHTSA Recall Number:**

## Description of Remedy

**Remedy Type:**

**Consumer Advisories:**  Do Not Drive  Park Outside

**Description of remedy program:**

All known owners of the involved vehicles will be notified to return their vehicles to a Toyota or Lexus dealer. Dealers will replace the load carrying capacity modification label with an updated one at no cost to owners.

**How remedy component differs from recalled component:**

**Identify how/when recall condition was corrected in production:**

## Reimbursement Plan

**Description of reimbursement program:**

As the owner notification letters will be mailed out well within the active period of the Toyota or Lexus New Vehicle Limited Warranty, all involved vehicle owners for this recall would have been provided a repair at no cost under Toyota's or Lexus' Warranty.

**Part 573 Safety Recall Report****26V179**

Period of reimbursement:

Costs to be reimbursed:

Address for reimbursement claims:

**Recall Schedule**

Description of recall schedule:

Planned Dealer Notification Date: Mar 24, 2026 - Mar 24, 2026  No DealersPlanned Interim Owner Notification Date:  No OwnersPlanned Remedy Owner Notification Date: May 09, 2026 - May 23, 2026  Phased Recall

Date when VIN will be searchable: