



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

26V292

Manufacturer Name: Shyft Group

Submission Date: May 27, 2026

NHTSA Recall No.: 26V292

Manufacturer Recall No.: 26-05

Manufacturer Information

Population

Manufacturer Name: Shyft Group

Address: 1541 Reynolds Road
Charlotte MI, 48813

Total number of potentially involved: 836

Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2025-2025 Spartan RV Chassis K3

Product Category: Buses, Medium & Heavy Vehicles

Product Type: Other

Fuel / Propulsion: Compression Ignition Fuel

Production Dates: Aug 31, 2023 - May 13, 2025

Number of potentially involved: 149

Descriptive Information:

The recalled population was determined by conducting a where used query to identify the chassis on which the switch at issue was installed.

Vehicle 2: 2024-2024 Spartan RV Chassis K3

Product Category: Buses, Medium & Heavy Vehicles

Product Type: Other

Fuel / Propulsion: Compression Ignition Fuel

Production Dates: Sep 20, 2023 - Jun 17, 2024

Number of potentially involved: 149

Descriptive Information:

The recalled population was determined by conducting a where used query to identify the chassis on which the switch at issue was installed.

Vehicle 3: 2024-2024 Spartan RV Chassis K2

Part 573 Safety Recall Report

26V292**Product Category:** Buses, Medium & Heavy Vehicles**Product Type:** Other**Fuel / Propulsion:** Compression Ignition Fuel**Production Dates:** Nov 30, 2023 - Dec 26, 2025**Number of potentially involved:** 106**Descriptive Information:**

The recalled population was determined by conducting a where used query to identify the chassis on which the switch at issue was installed.

Vehicle 4: 2025-2025 Spartan RV Chassis K2**Product Category:** Buses, Medium & Heavy Vehicles**Product Type:** Other**Fuel / Propulsion:** Compression Ignition Fuel**Production Dates:** Sep 21, 2023 - Mar 03, 2025**Number of potentially involved:** 168**Descriptive Information:**

The recalled population was determined by conducting a where used query to identify the chassis on which the switch at issue was installed.

Vehicle 5: 2025-2025 Spartan RV Chassis K4**Product Category:** Buses, Medium & Heavy Vehicles**Product Type:** Other**Fuel / Propulsion:** Compression Ignition Fuel**Production Dates:** Oct 12, 2023 - Jul 23, 2024**Number of potentially involved:** 26**Descriptive Information:**

The recalled population was determined by conducting a where used query to identify the chassis on which the switch at issue was installed.

Vehicle 6: 2026-2026 Spartan RV Chassis K4**Product Category:** Buses, Medium & Heavy Vehicles**Product Type:** Other**Fuel / Propulsion:** Compression Ignition Fuel

Part 573 Safety Recall Report

26V292

Production Dates: Jun 26, 2024 - Jul 25, 2025

Number of potentially involved: 33

Descriptive Information:

The recalled population was determined by conducting a where used query to identify the chassis on which the switch at issue was installed.

Vehicle 7: 2026-2026 Spartan RV Chassis K3

Product Category: Buses, Medium & Heavy Vehicles

Product Type: Other

Fuel / Propulsion: Compression Ignition Fuel

Production Dates: Oct 10, 2024 - Sep 11, 2025

Number of potentially involved: 121

Descriptive Information:

The recalled population was determined by conducting a where used query to identify the chassis on which the switch at issue was installed.

Vehicle 8: 2027-2027 Spartan RV Chassis K4

Product Category: Buses, Medium & Heavy Vehicles

Product Type: Other

Fuel / Propulsion: Compression Ignition Fuel

Production Dates: Jun 26, 2025 - Oct 16, 2025

Number of potentially involved: 10

Descriptive Information:

The recalled population was determined by conducting a where used query to identify the chassis on which the switch at issue was installed.

Vehicle 9: 2025-2025 Spartan RV Chassis K1

Product Category: Buses, Medium & Heavy Vehicles

Product Type: Other

Fuel / Propulsion: Compression Ignition Fuel

Production Dates: Jan 29, 2024 - Apr 23, 2024

Number of potentially involved: 7

Descriptive Information:

Part 573 Safety Recall Report

26V292

The recalled population was determined by conducting a where used query to identify the chassis on which the switch at issue was installed.

Vehicle 10: 2026-2026 Spartan RV Chassis K2

Product Category: Buses, Medium & Heavy Vehicles

Product Type: Other

Fuel / Propulsion: Compression Ignition Fuel

Production Dates: Oct 16, 2024 - Sep 29, 2025

Number of potentially involved: 67

Descriptive Information:

The recalled population was determined by conducting a where used query to identify the chassis on which the switch at issue was installed.

Defect / Noncompliance Description

Description of the defect or noncompliance:

The brake pressure switch used in the air brake system may retain enough residual air pressure causing the brake lamps to be illuminated when the service brakes is not applied.

FMVSS1: 108 - Lamps, reflective devices, and assoc. Equipment

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

Brake lamps that are illuminated without the service brake being applied could be confusing to trailing drivers and could increase the risk of a crash.

Description of the cause:

A minimum release pressure was not specified during the selection of the pressure switch.

Identification of any warning that can occur:

Brake lights could be illuminated without warning.

Component Manufacturer

Tier of Supplier:

Supplier Type:

Part 573 Safety Recall Report

26V292**Name:****Address:****Country:**

Involved Components

Component Name 1: Pressure switch**Component Description:** SWITCH-N.C. S.P.S.T. PRES**Component Part Number:** 0108-GG3-031

Chronology

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Replace**Consumer Advisories:** ☐ Do Not Drive ☐ Park Outside**Description of remedy program:**

Shyft will supply new pressure switches with a pressure setting that will cause the brake lamps to not be illuminated with residual air pressure.

How remedy component differs from recalled component:

The remedy component has a specified pressure setting that will cause the circuit for the brake lamps to be closed and not allow them to be illuminated unless the service brake is applied.

Identify how/when recall condition was corrected in production:

New pressure switches were implemented in September 2025.

Reimbursement Plan

Part 573 Safety Recall Report**26V292**

Manufacturer used general reimbursement plan on file.

Recall Schedule**Description of recall schedule:**

Owners of the affected vehicles will be notified of the recall and will be offered a replacement pressure switch at no charge.

Planned Dealer Notification Date:☒ No Dealers**Planned Interim Owner Notification Date:**☐ No Owners**Planned Remedy Owner Notification Date:** Jun 05, 2026 - Jun 05, 2026☐ Phased Recall**Date when VIN will be searchable:**