



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

26V297

Manufacturer Name: Jaguar Land Rover North America, LLC

Submission Date: May 12, 2026

NHTSA Recall No.: 26V297

Manufacturer Recall No.: D105

Manufacturer Information

Population

Manufacturer Name: Jaguar Land Rover North America, LLC

Address: 100 Jaguar Land Rover Way
Mahwah NJ, 07495

Total number of potentially involved: 76

Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2026-2026 LAND ROVER RANGE ROVER VELAR

Product Category: Light Vehicles

Product Type: Multipurpose Passenger Vehicle

Fuel / Propulsion:

Production Dates: Feb 05, 2026 - Mar 04, 2026

Number of potentially involved: 30

Descriptive Information:

Jaguar Land Rover is conducting a voluntary safety recall campaign involving certain 2026MY Land Rover Range Rover Velar vehicles built at the Solihull Vehicle Assembly Plant from February 5, 2026 to March 4, 2026. 30 Land Rover Range Rover Velar vehicles in the United States and Federalized Territories. The basis of the recall population of vehicles was determined by interrogating vehicle build records and matching affected amplifiers to VINs.

Vehicle 2: 2026-2026 LAND ROVER RANGE ROVER SPORT

Product Category: Light Vehicles

Product Type: Multipurpose Passenger Vehicle

Fuel / Propulsion:

Production Dates: Feb 17, 2026 - Feb 27, 2026

Number of potentially involved: 30

Descriptive Information:

Jaguar Land Rover is conducting a voluntary safety recall campaign involving certain 2026MY Land Rover Range Rover Sport vehicles built at the Solihull Vehicle Assembly Plant from February 17, 2026 to February 27, 2026. 30 Land Rover Range Rover Sport vehicles in the United States and Federalized

Part 573 Safety Recall Report

26V297

Territories. The basis of the recall population of vehicles was determined by interrogating vehicle build records and matching affected amplifiers to VINs.

Vehicle 3: 2026-2026 LAND ROVER RANGE ROVER

Product Category: Light Vehicles

Product Type: Multipurpose Passenger Vehicle

Fuel / Propulsion:

Production Dates: Feb 17, 2026 - Feb 26, 2026

Number of potentially involved: 16

Descriptive Information:

Jaguar Land Rover is conducting a voluntary safety recall campaign involving certain 2026MY Land Rover Range Rover vehicles built at the Solihull Vehicle Assembly Plant from February 17, 2026 to February 26, 2026. 16 Land Rover Range Rover Sport vehicles in the United States and Federalized Territories. The basis of the recall population of vehicles was determined by interrogating vehicle build records and matching affected amplifiers to VINs.

Defect / Noncompliance Description

Description of the defect or noncompliance:

A concern has been identified on certain 2026 model year Range Rover, Range Rover Sport and Range Rover Velar vehicles where the audio amplifiers may have been subject to water damage and may not provide any audio output, including no seat belt reminder audible warnings to the driver.

FMVSS1: 208 - Occupant crash protection

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

A seat belt reminder audible warning chime that does not alert of an unlatched seat belt can increase the risk of occupant injury in the event of a crash.

Description of the cause:

Identification of any warning that can occur:

Component Manufacturer

Part 573 Safety Recall Report

26V297

Tier of Supplier:
Supplier Type:
Name: Lear Corporation

Address: Technopolis free zone B.P
CP11103, Rocade Rabat
Sala El Jadida Foreign States, CP11103

Country: Morocco

Involved Components

Component Name 1: Kit - Audio Amplifier

Component Description: Kit - Audio Amplifier

Component Part Number: T8B2-19C164-CA

Component Name 2: Kit - Audio Amplifier

Component Description: Kit - Audio Amplifier

Component Part Number: T8B2-19C164-HA

Component Name 3: Kit - Audio Amplifier

Component Description: Kit - Audio Amplifier

Component Part Number: T8B2-19C164-ZA

Chronology

On 05 March 2026, following information received through the supply chain that a shipment of audio amplifiers had been subject to potential water ingress, a Pre-Stop Shipment meeting was held at the Vehicle Assembly Plant. It was decided to implement a Quarantine and Update Prior to Sale notice (UPS) to ensure affected vehicles were remedied ahead of sale. Unused and potentially affected stock of audio amplifiers was quarantined at the Vehicle Assembly Plant. It was confirmed that no affected vehicles had entered into commerce.

On 23 April 2026, the Vehicle Assembly Plant reconvened the Pre-Stop Shipment meeting after an internal record check revealed that a small number of the quarantined audio amplifiers had subsequently been consumed in production. The UPS was updated to include further affected vehicles, and the matter was referred to the Product Safety and Compliance Committee (PSCC) as it was confirmed that a small number of affected vehicles had entered into commerce.

On 01 May 2026, the PSCC met following further work with the engineering team and suppliers to ascertain the extent of potential symptoms, and was informed that there was a risk of audio output not being provided, including driver warning tones. The matter was referred to the PSCC Decision Forum.

Part 573 Safety Recall Report

26V297

The PSCC Decision Forum reviewed the issue on 05 May 2026, and instructed that the UPS be upgraded to recall, and sold vehicles be added to the population.

JLR has received 0 claims and field reports in the US.

There have been no reported accidents, injuries or fires in the US as a result of this concern.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Replace, Repair

Consumer Advisories: Do Not Drive Park Outside

Description of remedy program:

Vehicles will have audio amplifier replaced free of charge.

How remedy component differs from recalled component:

The replacement amplifiers have not been subject to the same adverse conditions in the supply chain.

Identify how/when recall condition was corrected in production:

This defect affects a limited batch of components which were affected by a combination of monsoon conditions and airport labor shortages and storage restrictions

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Recall Schedule

Description of recall schedule:

Notifications to dealers will occur on May 26, 2026. Distribution of owner notification letters will occur on or before July 10, 2026.

Planned Dealer Notification Date: May 26, 2026 - May 26, 2026 No Dealers

Planned Interim Owner Notification Date: Jul 10, 2026 - Jul 10, 2026 No Owners

Planned Remedy Owner Notification Date: Phased Recall

Part 573 Safety Recall Report

26V297

Date when VIN will be searchable: