



U.S. Department  
of Transportation

National Highway  
Traffic Safety  
Administration

# Part 573 Safety Recall Report

## 26V306

**Manufacturer Name:** Honda (American Honda Motor Co.)

**Submission Date:** May 14, 2026

**NHTSA Recall No.:** 26V306

**Manufacturer Recall No.:** DO5, RO6

### Manufacturer Information

### Population

**Manufacturer Name:** Honda (American Honda Motor Co.)

**Address:** 1919 Torrance Blvd.  
Torrance CA, 90501

**Total number of potentially involved:** 59,887

**Estimated percentage with defect:** 4%

### Vehicle Information

**Vehicle 1:** 2024-2024 ACURA ZDX

**Product Category:** Light Vehicles

**Product Type:** Multipurpose Passenger Vehicle

**Fuel / Propulsion:** Electric Battery Power

**Production Dates:** Dec 19, 2023 - Jan 21, 2025

**Number of potentially involved:** 15,688

**Descriptive Information:**

The recall population was determined based on manufacturing records. The production range reflects all possible vehicles that could experience the problem.

**Vehicle 2:** 2024-2025 HONDA PROLOGUE

**Product Category:** Light Vehicles

**Product Type:** Multipurpose Passenger Vehicle

**Fuel / Propulsion:** Electric Battery Power

**Production Dates:** Oct 10, 2023 - Sep 03, 2025

**Number of potentially involved:** 44,199

**Descriptive Information:**

The recall population was determined based on manufacturing records. The production range reflects all possible vehicles that could experience the problem.

# Part 573 Safety Recall Report

# 26V306

## Defect / Noncompliance Description

### Description of the defect or noncompliance:

The rearview camera housing may be improperly bonded, allowing portions of the adhesive to separate over time. This can permit moisture intrusion into the camera assembly, leading to corrosion of internal electrical components. As a result, the rearview camera image may become blurry, distorted, or fail to display, resulting in a black screen.

**FMVSS1:**

**FMVSS2:**

### Description of the safety risk, including crash, fire, death, injury:

If the rearview camera image is distorted or fails to display, the risk of a crash or injury is increased.

### Description of the cause:

The adhesive separation is caused by improper pre-treatment (plasma irradiation) of the rearview camera case bonding surface by the supplier during the manufacturing process. The plasma treatment is believed to have caused deformation or chemical alteration of portions of the bonding surface, reducing adhesive strength and resulting in adhesive delamination over time.

### Identification of any warning that can occur:

## Component Manufacturer

**Tier of Supplier:** Tier 1

**Supplier Type:** OEM

**Name:** Sharp

**Address:** One Towne Square, Suite 200  
Southfield MI, 48076

**Country:** United States

## Involved Components

**Component Name 1:** REAR VIEW CAMERA

**Component Description:** REAR VIEW CAMERA

**Component Part Number:** 86583111

# Part 573 Safety Recall Report

**26V306**

## Chronology

May 14, 2024

Honda received notification of a potential incident and began to investigate.

June 20-25, 2024

Honda received returned parts and continued to investigate the issue.

June 26, 2024 – July 31, 2025

Honda collaborated with GM to investigate and analyze the issue.

August 2025

Honda and GM continued to monitor the issue for additional market data.

October 2025

Honda and GM continued their investigation by analyzing returned parts.

December 2025

Honda performed additional market and trend analysis and collaborated with GM to evaluate the issue.

February – April 2026

Honda and GM continued to investigate and analyze the issue.

May 7, 2026

Honda determined that a defect related to motor vehicle safety existed and decided to conduct a safety recall.

As of May 7, 2026, Honda has had 2,411 warranty claims and no reports of an injury or death related to this issue from October 10, 2023 – April 12, 2026.

**Related NHTSA Recall Number:**

## Description of Remedy

# Part 573 Safety Recall Report

# 26V306

**Remedy Type:** Repair

**Consumer Advisories:**  Do Not Drive  Park Outside

**Description of remedy program:**

Registered owners of all affected vehicles will be contacted by mail and asked to take their vehicle to an authorized Honda or Acura dealer. The dealer will replace the rearview camera with an improved part.

**How remedy component differs from recalled component:**

The remedy components have an improved bonding process.

**Identify how/when recall condition was corrected in production:**

The recall condition was corrected with improved rearview cameras in production on June 9, 2025.

## Reimbursement Plan

Manufacturer used general reimbursement plan on file.

## Recall Schedule

**Description of recall schedule:**

Dealer notification is scheduled to begin and end on or about 5/15/2026. Interim owner notification is scheduled to begin and end on or about 7/6/2026.

**Planned Dealer Notification Date:** May 15, 2026 - May 15, 2026  No Dealers

**Planned Interim Owner Notification Date:** Jul 06, 2026 - Jul 06, 2026  No Owners

**Planned Remedy Owner Notification Date:**  Phased Recall

**Date when VIN will be searchable:**