



U.S. Department  
of Transportation

National Highway  
Traffic Safety  
Administration

## Part 573 Safety Recall Report

# 26V313

**Manufacturer Name:** Keystone RV Company

**Submission Date:** Jun 03, 2026

**NHTSA Recall No.:** 26V313

**Manufacturer Recall No.:** 26-483

### Manufacturer Information

### Population

**Manufacturer Name:** Keystone RV Company

**Address:** PO Box 2000  
2642 Hackberry Drive  
Goshen IN, 46527

**Total number of potentially involved:** 926

**Estimated percentage with defect:** 100%

### Vehicle Information

**Vehicle 1:** 2025-2026 KEYSTONE ALPINE

**Product Category:** Trailers

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Sep 04, 2024 - Apr 14, 2026

**Number of potentially involved:** 267

**Descriptive Information:**

Alpine – All Models , Models with Curt Touring Coil Suspensions

**Vehicle 2:** 2024-2024 KEYSTONE COUGAR

**Product Category:** Trailers

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Apr 25, 2024 - Apr 25, 2024

**Number of potentially involved:** 1

**Descriptive Information:**

Cougar 316RLS, Models with Curt Touring Coil Suspensions

**Vehicle 3:** 2026-2026 Keystone Walkabout

**Product Category:** Trailers

**Part 573 Safety Recall Report****26V313****Product Type:****Fuel / Propulsion:****Production Dates:** Aug 18, 2025 - Apr 08, 2026**Number of potentially involved:** 330**Descriptive Information:**Walkabout – 22MAX, 26MAX, Models with Curt Touring Coil Suspensions**Vehicle 4:** 2026-2026 KEYSTONE MONTANA**Product Category:** Trailers**Product Type:****Fuel / Propulsion:****Production Dates:** Aug 25, 2025 - Apr 28, 2026**Number of potentially involved:** 328**Descriptive Information:**Montana – 3100RL, 3800FL, 3900RK, Models with Curt Touring Coil Suspensions**Defect / Noncompliance Description****Description of the defect or noncompliance:**

It has been decided that the vehicles in the recall population may have improperly torqued shock bolts.

**FMVSS1:****FMVSS2:****Description of the safety risk, including crash, fire, death, injury:**

Under certain conditions during travel, the vehicle may experience excessive bouncing or swaying with decreased stability, leading to an increased risk of a vehicle crash.

**Description of the cause:**

Improperly torqued shock bolts may damage or break the bolt if over torqued and may vibrate loose if under torqued.

**Identification of any warning that can occur:**

Clunking or rattling noise while traveling over bumps, visibly damaged components.

# Part 573 Safety Recall Report

# 26V313

## Component Manufacturer

**Tier of Supplier:**

**Supplier Type:**

**Name:** Lippert

**Address:** 2020 Blakesley Pkwy  
Bristol IN, 46507

**Country:** United States

## Involved Components

**Component Name 1:** Axle - Shock - TCS - 12.63" - EXT LG - 3.88 Stroke

**Component Description:** 3/8 x 16 x 3/4 shock bolts

**Component Part Number:** 771236 / 202304059244

## Chronology

05/08/2026 – Report was made. LCI notified Keystone RV that they have identified a potential concern involving shock bolts on the Curt Touring Suspension System installed on specific Lippert chassis. Sporadic instances of improper torque have been identified.

05/08/2026 – Investigation opened to determine scope and range of units affected.

05/10/2026 – Warranty claims for shock bolts include 1 claims, claim created start date 4/25/2024 to claim created end date 05/10/2026

05/15/2026 – Keystone Safety Committee reviewed the information and concluded that the data reviewed indicated a unanimous vote for a voluntary recall.

05/15/2026 – Investigation concluded and scope completed.

**Related NHTSA Recall Number:**

## Description of Remedy

**Remedy Type:**

**Consumer Advisories:**  Do Not Drive  Park Outside

**Description of remedy program:**

# Part 573 Safety Recall Report

# 26V313

The remedy is to replace the existing shock bolts with a bolt replacement kit. Manufacturer Reimbursement Plan on file as of 10/3/2024. General reimbursement plan to be updated every two years. New vehicles are covered under warranty.

## How remedy component differs from recalled component:

The remedy replaces the existing shock bolts with a higher-grade bolt kit while outlining specific torque requirements.

## Identify how/when recall condition was corrected in production:

Units not shipped were placed on hold for inspection and or repair.

## Reimbursement Plan

Manufacturer used general reimbursement plan on file.

## Recall Schedule

### Description of recall schedule:

Keystone will notify the dealers and owners of the recreational vehicles by letter. A final copy of the owner letter will be provided to NHTSA, along with the dealer repair procedures.

- Planned Dealer Notification Date:** Jun 01, 2026 - Jun 01, 2026  No Dealers
- Planned Interim Owner Notification Date:**  No Owners
- Planned Remedy Owner Notification Date:** Jun 01, 2026 - Jun 01, 2026  Phased Recall
- Date when VIN will be searchable:** Jun 01, 2026