



U.S. Department  
of Transportation

National Highway  
Traffic Safety  
Administration

## Part 573 Safety Recall Report

# 26V315

**Manufacturer Name:** Tesla, Inc.

**Submission Date:** May 18, 2026

**NHTSA Recall No.:** 26V315

**Manufacturer Recall No.:** SB-26-19-002

### Manufacturer Information

### Population

**Manufacturer Name:** Tesla, Inc.

**Address:** 1 Tesla Road  
Austin TX, 78725

**Total number of potentially involved:** 14,575

**Estimated percentage with defect:** 45%

### Vehicle Information

**Vehicle 1:** 2026-2026 TESLA MODEL Y

**Product Category:** Light Vehicles

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Feb 25, 2025 - Apr 21, 2026

**Number of potentially involved:** 11,878

**Descriptive Information:**

The recall population includes certain Model Year ("MY") 2025 Tesla Model Y vehicles manufactured between November 17, 2024 and February 24, 2025 and 2026 Tesla Model Y vehicles manufactured between February 25, 2025 and April 21, 2026 that may not have been equipped with the certification label required by 49 CFR Part 567.

**Vehicle 2:** 2025-2025 TESLA MODEL Y

**Product Category:** Light Vehicles

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Nov 17, 2024 - Feb 24, 2025

**Number of potentially involved:** 2,697

**Descriptive Information:**

The recall population includes certain Model Year ("MY") 2025 Tesla Model Y vehicles manufactured between November 17, 2024 and February 24, 2025 and 2026 Tesla Model Y vehicles manufactured between February 25, 2025 and April 21, 2026 that may not have been equipped with the certification label required by 49 CFR Part 567.

# Part 573 Safety Recall Report

**26V315**

## Defect / Noncompliance Description

**Description of the defect or noncompliance:**

Affected vehicles may not be equipped with the certification label required by 49 CFR Part 567.

**FMVSS1:** 567 - Certification

**FMVSS2:**

**Description of the safety risk, including crash, fire, death, injury:**

The absence of a certification label with weight specifications may lead to customers overloading the vehicle, increasing the risk of a crash.

**Description of the cause:****Identification of any warning that can occur:**

## Component Manufacturer

**Tier of Supplier:****Supplier Type:**

**Name:** Tesla, Inc.

**Address:** 1 Tesla Road  
Austin TX, 78725

**Country:** United States

## Involved Components

**Component Name 1:** Certification Label

**Component Description:** Certification Label

**Component Part Number:** 1462927-00-C

## Chronology

# Part 573 Safety Recall Report

# 26V315

- On April 17, 2026, Tesla discovered a vehicle with a missing certification label during a routine internal audit of its Fremont factory. Upon further investigation, Tesla discovered that its automated vision-scanning tool that verifies the presence of a properly affixed certification label was performing inconsistently.
- From April 20 through May 4, 2026, this issue was investigated internally to understand the impact and scope, including understanding if vehicles produced at the Tesla Gigafactory in Austin, TX were affected.
- On May 11, 2026, after completing the internal investigation, Tesla determined that a noncompliance exists and made a voluntary recall determination.
- As of May 13, 2026, Tesla has identified 0 warranty claims and 0 field reports that may be related to the condition. Tesla is not aware of any collisions, fatalities, or injuries that are or may be related to the condition.

**Related NHTSA Recall Number:**

## Description of Remedy

### Remedy Type:

**Consumer Advisories:**  Do Not Drive  Park Outside

### Description of remedy program:

At no cost to customers, Tesla will inspect affected vehicles and affix a certification label, if necessary.

### How remedy component differs from recalled component:

The remedy is to provide a certification label that complies with 49 CFR Part 567.

### Identify how/when recall condition was corrected in production:

On April 17, 2026, the Fremont factory team fixed the automated scanning tool and implemented additional manual checks for production teams to systematically track that each vehicle is equipped with the correct certification label. Manual checks were implemented at the Gigafactory Texas on April 21, 2026, and the automated scanning tool was fixed on May 7, 2026.

## Reimbursement Plan

### Description of reimbursement program:

Tesla does not plan to include a statement in the Part 577 owner notification about pre-notice reimbursement to owners because all affected vehicles are either covered under the new vehicle or extended service warranty, or no vehicle owner incurred costs for a pre-notification remedy associated with the noncompliance.

**Part 573 Safety Recall Report****26V315****Period of reimbursement:****Costs to be reimbursed:****Address for reimbursement claims:****Recall Schedule****Description of recall schedule:**

All Tesla stores and service centers will be notified about this recall on or shortly after May 21, 2026. Owner notification letters will be mailed in accordance with 49 C.F.R. § 577.7.

**Planned Dealer Notification Date:** May 21, 2026 - May 21, 2026  No Dealers

**Planned Interim Owner Notification Date:**  No Owners

**Planned Remedy Owner Notification Date:** Jul 17, 2026 - Jul 17, 2026  Phased Recall

**Date when VIN will be searchable:**