



U.S. Department  
of Transportation

National Highway  
Traffic Safety  
Administration

## Part 573 Safety Recall Report

## 26V350

**Manufacturer Name:** Volvo Trucks North America

**Submission Date:** May 28, 2026

**NHTSA Recall No.:** 26V350

**Manufacturer Recall No.:** RVXX2606

### Manufacturer Information

### Population

**Manufacturer Name:** Volvo Trucks North America

**Address:** 7900 National Service Road  
Greensboro NC, 27409

**Total number of potentially involved:** 155

**Estimated percentage with defect:** 2.5%

### Vehicle Information

**Vehicle 1:** 2026-2026 VOLVO VAH

**Product Category:** Buses, Medium & Heavy Vehicles

**Product Type:** Tractor

**Fuel / Propulsion:** Compression Ignition Fuel

**Production Dates:** Jun 16, 2025 - May 21, 2026

**Number of potentially involved:** 1

**Descriptive Information:**

Torque angles and traces were evaluated on all trucks from start of production for masking material.

Masking material changes the joint from a hard joint to a soft joint.

This can be observed in the torque curves when by displaying slow application to final torque.

**Vehicle 2:** 2027-2027 VOLVO VNR (4)

**Product Category:** Buses, Medium & Heavy Vehicles

**Product Type:** Tractor

**Fuel / Propulsion:** Compression Ignition Fuel

**Production Dates:** Jun 16, 2025 - May 21, 2026

**Number of potentially involved:** 3

**Descriptive Information:**

Torque angles and traces were evaluated on all trucks from start of production for masking material.

Masking material changes the joint from a hard joint to a soft joint.

**Part 573 Safety Recall Report****26V350**

This can be observed in the torque curves when by displaying slow application to final torque.

**Vehicle 3:** 2026-2027 VOLVO VN

**Product Category:** Buses, Medium & Heavy Vehicles

**Product Type:** Tractor

**Fuel / Propulsion:** Compression Ignition Fuel

**Production Dates:** Jun 16, 2025 - May 21, 2026

**Number of potentially involved:** 43

**Descriptive Information:**

Torque angles and traces were evaluated on all trucks from start of production for masking material.

Masking material changes the joint from a hard joint to a soft joint.

This can be observed in the torque curves when by displaying slow application to final torque.

**Vehicle 4:** 2026-2027 VOLVO VHD

**Product Category:** Buses, Medium & Heavy Vehicles

**Product Type:** Tractor

**Fuel / Propulsion:** Compression Ignition Fuel

**Production Dates:** Jun 16, 2025 - May 21, 2026

**Number of potentially involved:** 38

**Descriptive Information:**

Torque angles and traces were evaluated on all trucks from start of production for masking material.

Masking material changes the joint from a hard joint to a soft joint.

This can be observed in the torque curves when by displaying slow application to final torque.

**Vehicle 5:** 2026-2027 VOLVO VNL (4)

**Product Category:** Buses, Medium & Heavy Vehicles

**Product Type:** Tractor

**Fuel / Propulsion:** Compression Ignition Fuel

**Production Dates:** Jun 16, 2025 - May 21, 2026

**Number of potentially involved:** 70

**Descriptive Information:**

Torque angles and traces were evaluated on all trucks from start of production for masking material.

Masking material changes the joint from a hard joint to a soft joint.

**Part 573 Safety Recall Report****26V350**

This can be observed in the torque curves when by displaying slow application to final torque.

**Defect / Noncompliance Description****Description of the defect or noncompliance:**

Certain MY 2026-2027 Volvo VN, VNL(4), VNR(4), VHD, and VAH vehicles may have masking material from a painting process present between the wheels and axle hubs. This may cause the wheel lug nuts to loosen as the material compresses.

**FMVSS1:**

**FMVSS2:**

**Description of the safety risk, including crash, fire, death, injury:**

A wheel and tire assembly that detaches from a vehicle while driving may lead to loss of vehicle control or create a hazard to other road users, increasing the risk of a crash or injury.

**Description of the cause:**

Masking material was not removed after painting process. Operators did not visually recognize the error due to the material and hub having the same outer profile. Wheels were improperly installed with masking between mating surfaces, causing material compression which leads to a loss of torque on the wheel lug nuts.

**Identification of any warning that can occur:**

None

**Component Manufacturer**

**Tier of Supplier:**

**Supplier Type:**

**Name:**

**Address:**

**Country:**

**Involved Components**

**Component Name 1:** Wheel Nuts

**Component Description:** Connection between wheel and axle flange

# Part 573 Safety Recall Report

**26V350****Component Part Number:** 21807998

## Chronology

October 18, 2025: Product Safety Office opens a product safety related issue investigation on initial warranty claim  
 November 13, 2025: Product Safety Evaluation Committee review (1), committee requested additional vehicle inspections  
 January 12, 2026: Product Safety Evaluation Committee review (2), progress update provided to committee  
 January 22, 2026: Safety Office opens new product safety related issue investigation on two new warranty claims (not determined related at the time)  
 January 26, 2026: Product Safety Evaluation Committee review (3), all inspections show no masking present, decision to continue monitoring builds for 6 months  
 March 05, 2026: Masking presence confirmed on both new claim vehicles; safety investigations merged  
 April 06, 2026: Product Safety Evaluation Committee review (1), committee requested information from 3rd party supplier  
 May 04, 2026: Product Safety Evaluation Committee review (2), committee requested additional testing to support risk identification methodology  
 May 13, 2026: Product Safety Evaluation Committee review (3), decision to escalate to Product Safety Committee  
 May 21, 2026: Product Safety Committee determines that a product safety defect exists and decides to initiate a recall

There have been 4 warranty claims, 0 field reports, 0 accidents or 0 injuries reported with this issue.

**Related NHTSA Recall Number:**

## Description of Remedy

**Remedy Type:** Inspect, Repair**Consumer Advisories:**  Do Not Drive  Park Outside**Description of remedy program:**

Owners will be sent advance notice not to operate their affected vehicle(s) until the remedy is performed. When the remedy is performed, all wheel and hub mating surfaces will be inspected and if any masking material is found the material will be removed. If masking material is found wheel end components will be inspected and any worn parts will be replaced. Customers will be reimbursed for repair as necessary.

**How remedy component differs from recalled component:**

Remedy conditions will not have masking material between wheel and hub mounting surfaces.

**Identify how/when recall condition was corrected in production:**

Starting May 21, 2026, a new masking was rolled out in production that has a larger outer profile,

# Part 573 Safety Recall Report

# 26V350

exceeding the wheel hub size. The new masking also is a different shape (square) to further differentiate it from the hub assembly.

## Reimbursement Plan

Manufacturer used general reimbursement plan on file.

## Recall Schedule

### Description of recall schedule:

Dealers will be notified on or before May 29  
Owners will be notified on or before May 29

**Planned Dealer Notification Date:** May 29, 2026 - Jun 05, 2026  No Dealers

**Planned Interim Owner Notification Date:**  No Owners

**Planned Remedy Owner Notification Date:** May 29, 2026 - Jun 05, 2026  Phased Recall

**Date when VIN will be searchable:** May 29, 2026