



U.S. Department  
of Transportation

National Highway  
Traffic Safety  
Administration

## Part 573 Safety Recall Report

# 26V423

**Manufacturer Name:** Honda (American Honda Motor Co.)

**Submission Date:** Jul 01, 2026

**NHTSA Recall No.:** 26V423

**Manufacturer Recall No.:** HOX

### Manufacturer Information

### Population

**Manufacturer Name:** Honda (American Honda Motor Co.)

**Address:** 1919 Torrance Blvd.  
Torrance CA, 90501

**Total number of potentially involved:** 325,588

**Estimated percentage with defect:** 0.8%

### Vehicle Information

**Vehicle 1:** 2018-2020 HONDA ODYSSEY

**Product Category:** Light Vehicles

**Product Type:** Multipurpose Passenger Vehicle

**Fuel / Propulsion:** Spark Ignition Fuel

**Production Dates:** Jan 24, 2017 - Jul 22, 2020

**Number of potentially involved:** 325,588

#### Descriptive Information:

The recall population was identified based on manufacturing records and includes: (1) vehicles previously recalled under NHTSA Campaign No. 20V-438, and (2) 2018 model year vehicles equipped with Magna rearview cameras that were previously addressed through a Product Update (PUD) Campaign for the same condition. Both the previous recall and the PUD remedy used redesigned Magna rearview cameras, which will be replaced by Sony rearview cameras for this remedy. The production range encompasses all vehicles that may have been manufactured with the affected rearview camera and, therefore, could experience the condition.

### Defect / Noncompliance Description

#### Description of the defect or noncompliance:

Water can enter the rearview camera assembly and cause the printed circuit board (PCB) to corrode. As a result, the rearview camera image can fail to display when the vehicle is in the reverse gear.

**FMVSS1:** 111 - Rear visibility

**FMVSS2:**

**Description of the safety risk, including crash, fire, death, injury:**

# Part 573 Safety Recall Report

**26V423**

If the rearview camera image fails to display when the vehicle is in the reverse gear, rearward visibility is reduced, increasing the risk of a crash or injury.

**Description of the cause:**

The defect was caused by two contributing factors. First, the specification for the rearview camera housing boss hole was inadequate for the mounting screw. Second, due to variations in the positioning of the housing on the assembly jig, the mounting screw is susceptible to being misaligned during assembly. As a result, the stress generated during screw fastening exceeded the material strength of the boss, causing it to crack. Through environmental exposure (thermal expansion/freezing of trapped water), these cracks can expand, allowing water to penetrate the interior of the assembly.

**Identification of any warning that can occur:**

## Component Manufacturer

**Tier of Supplier:** Tier 1**Supplier Type:** OEM**Name:** Magna Electronics Holly**Address:** 10345 N Holly Rd  
Holly MI, 48442**Country:** United States

## Involved Components

**Component Name 1:** Camera**Component Description:** Camera**Component Part Number:** 39530-THRA210-M1

## Chronology

July 21, 2020

Honda determined that a FMVSS noncompliance existed and decided to conduct a noncompliance recall (NHTSA ID 20V-438).

June 11, 2021

Honda received report of the issue involving a previously repaired vehicle and began to investigate.

# Part 573 Safety Recall Report

# 26V423

August 16, 2022

Honda worked with the supplier to investigate and analyze the issue.

May 3, 2023

Honda and the supplier had been unable to recreate the issue thus far. Honda was informed by the supplier that it had concluded its participation in the investigation. Honda continued to monitor the market and investigate and analyze the issue.

April – December 2024

Honda conducted analysis of the issue by monitoring the market and observed a decrease in incidents.

April – September 2025

Honda continued to investigate the issue by analyzing design specifications.

January – June 2026

Honda continued to investigate and analyze the cause of the issue.

June 25, 2026

Honda determined that a defect related to motor vehicle safety and FMVSS noncompliance existed and decided to conduct a safety and noncompliance recall.

As of June 25, 2026, Honda has had 1648 warranty claims, no reports of an injury, and no reports of death related to this issue from July 21, 2020 – June 25, 2026.

**Related NHTSA Recall Number:** 20V438

## Description of Remedy

**Remedy Type:** Repair

**Consumer Advisories:**  Do Not Drive  Park Outside

**Description of remedy program:**

Registered owners of all affected vehicles will be contacted by mail and asked to take their vehicle to an authorized Honda dealer. The dealer will replace the rearview camera with an improved part.

**How remedy component differs from recalled component:**

# Part 573 Safety Recall Report

**26V423**

The remedy components are produced by a different supplier (Sony).

**Identify how/when recall condition was corrected in production:**

The affected vehicles are no longer in production.

## Reimbursement Plan

Manufacturer used general reimbursement plan on file.

## Recall Schedule

**Description of recall schedule:**

Dealer notification is scheduled to begin and end on or about 7/2/2026. Owner notification is scheduled to begin and end on or about 8/24/2026.

**Planned Dealer Notification Date:** Jul 02, 2026 - Jul 02, 2026

No Dealers

**Planned Interim Owner Notification Date:**

No Owners

**Planned Remedy Owner Notification Date:** Aug 24, 2026 - Aug 24, 2026

Phased Recall

**Date when VIN will be searchable:**