



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

26V456

Manufacturer Name: Chrysler (FCA US, LLC)

Submission Date: Jul 16, 2026

NHTSA Recall No.: 26V456

Manufacturer Recall No.: 05D

Manufacturer Information

Population

Manufacturer Name: Chrysler (FCA US, LLC)

Address: 800 Chrysler Drive
CIMS 482-00-91
Auburn Hills MI, 48326-
2757

Total number of potentially involved: 641

Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2026-2026 JEEP GLADIATOR

Product Category: Light Vehicles

Product Type:

Fuel / Propulsion:

Production Dates: Nov 10, 2025 - Nov 15, 2025

Number of potentially involved: 35

Descriptive Information:

Some 2026MY Jeep Gladiator vehicles may have been built with a steel wheel that was produced with a thin wall condition.

The suspect period began on November 10, 2025, when the first suspect vehicle was produced and ended on November 15, 2025, when the last suspect vehicle was produced. Supplier and vehicle production records were used to determine the suspect population.

Similar vehicles not included in this recall were produced before or after the suspect period or were built without a steel wheel.

Vehicle 2: 2026-2026 JEEP WRANGLER

Product Category: Light Vehicles

Product Type:

Fuel / Propulsion:

Production Dates: Nov 10, 2025 - Nov 16, 2025

Number of potentially involved: 606

Descriptive Information:

Part 573 Safety Recall Report

26V456

Some 2026MY Jeep Wrangler vehicles may have been built with a steel wheel that was produced with a thin wall condition.

The suspect period began on November 10, 2025, when the first suspect vehicle was produced and ended on November 16, 2025, when the last suspect vehicle was produced. Supplier and vehicle production records were used to determine the suspect population.

Similar vehicles not included in this recall were produced before or after the suspect period or were built without a steel wheel.

Defect / Noncompliance Description

Description of the defect or noncompliance:

A steel wheel with a thin wall condition can contribute to potential wheel cracking and separating resulting in potential compromised vehicle control.

FMVSS1:

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

Compromised control of the vehicle can cause a vehicle crash without prior warning.

Description of the cause:

Identification of any warning that can occur:

None

Component Manufacturer

Tier of Supplier:

Supplier Type:

Name: Maxion Wheels

Address: 39500 Orchard Hill Place
Novi MI, 48375

Country: United States

Involved Components

Part 573 Safety Recall Report

26V456

Component Name 1: Steel Wheel

Component Description: Wheel

Component Part Number: 5VH22RXFAB

Chronology

- On December 9, 2025, the FCA US LLC ("FCA US") Technical Safety and Regulatory Compliance ("TSRC") organization opened an investigation into a potential issue related to the suspect vehicles with a steel wheel that were produced with a thin wall condition.
- From December 2025, through June 2026, FCA US TSRC met with FCA Engineering and Supplier Quality to review the issue, understand the potential failure mode, and to determine the suspect population.
- As of June 24, 2026, FCA US is not aware of any customer assistance records, warranty claims, or field reports potentially relating to this issue for all markets.
- As of June 24, 2026, FCA US is not aware of any accidents or injuries potentially related to this issue for all markets.
- On July 9, 2026, FCA US determined, through the Vehicle Regulations Committee, that a safety defect exists in certain vehicles.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Replace, Inspect

Consumer Advisories: ☐ Do Not Drive ☐ Park Outside

Description of remedy program:

FCA US will conduct a voluntary safety recall to inspect and if necessary, replace the steel wheel and valve stem.

How remedy component differs from recalled component:

Remedy is a steel wheel and valve stem.

Identify how/when recall condition was corrected in production:

Part 573 Safety Recall Report

26V456

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Recall Schedule

Description of recall schedule:

****07/16/2026:** FCA US will notify dealers on or about 07/23/2026 and begin notifying owners on or about 09/04/2026.

Planned Dealer Notification Date: Jul 23, 2026 - Jul 23, 2026

☐ No Dealers

Planned Interim Owner Notification Date:

☐ No Owners

Planned Remedy Owner Notification Date: Sep 04, 2026 - Sep 04, 2026

☐ Phased Recall

Date when VIN will be searchable: Jul 23, 2026