



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

26V496

Manufacturer Name: General Motors, LLC

Submission Date: Jul 30, 2026

NHTSA Recall No.: 26V496

Manufacturer Recall No.: N262556920

Manufacturer Information

Population

Manufacturer Name: General Motors, LLC

Address: 29427 Louis Chevrolet
Road
MAIL CODE 480-210-2V
WARREN MI, 48093

Total number of potentially involved: 952

Estimated percentage with defect: 74%

Vehicle Information

Vehicle 1: 2026-2026 CHEVROLET SILVERADO EV

Product Category: Light Vehicles

Product Type:

Fuel / Propulsion: Electric Battery Power

Production Dates: Nov 25, 2025 - Mar 13, 2026

Number of potentially involved: 513

Descriptive Information:

Manufacturing records were used to identify the affected population.

This recall only involves Silverado EV vehicles with steel road wheels (RPO RT3) and/or steel spare wheels (RPO SG8).

Vehicle 2: 2026-2026 GMC SIERRA EV

Product Category: Light Vehicles

Product Type:

Fuel / Propulsion: Electric Battery Power

Production Dates: Oct 24, 2025 - Mar 13, 2026

Number of potentially involved: 439

Descriptive Information:

Manufacturing records were used to identify the affected population.

Part 573 Safety Recall Report

26V496

This recall only involves Sierra EV vehicles with steel spare wheels (RPO SG8). Vehicles not equipped with a spare wheel are not affected by this recall.

Defect / Noncompliance Description

Description of the defect or noncompliance:

General Motors has decided that a defect which relates to motor vehicle safety may exist in certain 2026 model year Chevrolet Silverado EV and GMC Sierra EV vehicles. One or more of the steel wheels and/or the spare tire wheel on these vehicles may have a manufacturing defect that can eventually result in cracking at the disc vent holes.

FMVSS1:

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

A cracked wheel that goes undetected could lead to disc separation, reducing the driver's ability to steer and increasing the risk of a crash.

Description of the cause:

A manufacturing process at the supplier to form vent holes in the wheel disc may not have been properly adjusted.

Identification of any warning that can occur:

Component Manufacturer

Tier of Supplier:

Supplier Type:

Name: Topy America Inc.

Address: 980 Chenault Rd
Frankfort KY, 40601

Country: United States

Involved Components

Component Name 1: WHEEL-FRT & RR

Component Description: Steel Road Wheel (RPO RT3)

Part 573 Safety Recall Report

26V496

Component Part Number: 85162242

Component Name 2: WHEEL-SPA

Component Description: Steel Spare Wheel (RPO SG8)

Component Part Number: 85535663

Chronology

On April 9, 2026, a GM engineer submitted a report through GM's Speak Up for Safety (SUFS) program after the wheel supplier notified GM that certain steel wheels may have been shipped to GM's assembly plant without meeting GM's internal fatigue-testing requirements. GM opened a product investigation on May 19, 2026. During continuous conformance fatigue testing, the supplier found hairline cracks and traced the condition to the piercing/coining process that forms the outer ring of the vent holes in the wheel disc. These hairline cracks could propagate over time and potentially lead to disc separation. GM's investigation identified Silverado EV and Sierra EV vehicles that may have received one or more wheels from the supplier's suspect lots. GM is not aware of any field complaints or incidents associated with this condition. On July 23, 2026, GM's Safety Field Action Decision Authority (SFADA) decided to conduct a safety recall.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Inspect, Replace

Consumer Advisories: ☐ Do Not Drive ☐ Park Outside

Description of remedy program:

Dealers will inspect the spare on Silverado EVs and Sierra EVs and all four road wheels on Silverado EVs for the suspect disc lot dates. Wheels will be replaced as necessary.

How remedy component differs from recalled component:

Replacement wheels do not have discs from the supplier's suspect lots.

Identify how/when recall condition was corrected in production:

Containment efforts and validation improvements were implemented by April 24, 2026.

Reimbursement Plan

Part 573 Safety Recall Report

26V496**Description of reimbursement program:**

Pursuant to 49 C.F.R. § 573.13(d)(1), all covered vehicles are under warranty, so reimbursement is not offered.

Period of reimbursement:**Costs to be reimbursed:****Address for reimbursement claims:**

Recall Schedule

Description of recall schedule:

Dealers will be notified on July 30, 2026. Owner notification is estimated to start mailing on September 14, 2026. This will be executed under two bulletins: N262556920 and N262556921.

Planned Dealer Notification Date: Jul 30, 2026 - Jul 30, 2026☐ No Dealers**Planned Interim Owner Notification Date:**☐ No Owners**Planned Remedy Owner Notification Date:** Sep 14, 2026 - Sep 14, 2026☐ Phased Recall**Date when VIN will be searchable:** Jul 30, 2026