



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

26V501

Manufacturer Name: Autocar, LLC

Submission Date: Jul 30, 2026

NHTSA Recall No.: 26V501

Manufacturer Recall No.: ACTT-2601

Manufacturer Information

Population

Manufacturer Name: Autocar, LLC

Address: 551 S WASHINGTON
STREET
HAGERSTOWN IN, 47346

Total number of potentially involved: 137

Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2023-2027 Autocar ACTT

Product Category: Buses, Medium & Heavy Vehicles

Product Type:

Fuel / Propulsion: Electric Battery Power

Production Dates: Feb 21, 2022 - Jul 26, 2026

Number of potentially involved: 137

Descriptive Information:

All E-ACTT units manufactured with the suspect ABS ECU are included.

Defect / Noncompliance Description

Description of the defect or noncompliance:

The Antilock Braking System (ABS) Electronic Control Unit (ECU) may not be properly secured.

FMVSS1:

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

If the ABS ECU becomes separated from its mounting, it can become damaged and the ABS system may no longer function, increasing the risk of a crash.

Description of the cause:

Part 573 Safety Recall Report

26V501

An Autocar manufacturing error resulted in the ABS ECU not properly secured.

Identification of any warning that can occur:

ABS Malfunction Indicator Light (MIL).

Component Manufacturer

Tier of Supplier:

Supplier Type: OEM

Name: Autocar

Address: 551 S Washington St
Hagerstown IN, 47346

Country: United States

Involved Components

Component Name 1: Autocar ABS ECU

Component Description: ABS ECU

Component Part Number: A7471037-002

Component Name 2: Autocar Flat Washer

Component Description: Flat Washer

Component Part Number: GE811625NB01

Component Name 3: Autocar ABS ECU

Component Description: ABS ECU

Component Part Number: A7471037-001

Chronology

April 20, 2026, during a routine inspection, Autocar personnel identified a unit with missing fasteners at the ABS ECU. The unit was corrected and an investigation initiated. May 12, 2026, through July 10, 2026, the investigation continued. July 23, 2026, all relevant information was presented to Autocar's management team and out of an abundance of caution, Autocar decided to perform a voluntary Safety Recall for all suspect units. We have no known cases, claims or complaints.

Part 573 Safety Recall Report

26V501

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Repair

Consumer Advisories: ☐ Do Not Drive ☐ Park Outside

Description of remedy program:

Autocar will voluntarily initiate an owner notification and recall of all affected vehicles. Autocar will distribute to owners of affected vehicles an Owner Notification Letter, which will describe the defect and provide instructions for scheduling the inspection/repair of the vehicle at no cost to the vehicle's owner. The owner letter will instruct vehicle owners who have paid to have this condition remedied prior to this campaign to seek reimbursement pursuant to Autocar's General Reimbursement Plan, on file with the agency pursuant to 49 C.F.R. 573.6(c)(8)(i) and 49 C.F.R 573.13.

How remedy component differs from recalled component:

The suspect fasteners will be replaced and properly secured at no charge to the owner.

Identify how/when recall condition was corrected in production:

July 10, 2026, and July 23, 2026, the fasteners and manufacturing process were updated.

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Recall Schedule

Description of recall schedule:

Dealer and owner notifications will begin September 26, 2026, and end September 28, 2026.

Planned Dealer Notification Date: Sep 25, 2026 - Sep 28, 2026 ☐ No Dealers

Planned Interim Owner Notification Date: ☐ No Owners

Planned Remedy Owner Notification Date: Sep 25, 2026 - Sep 28, 2026 ☐ Phased Recall

Date when VIN will be searchable: