



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

26V539

Manufacturer Name: General Motors, LLC

Submission Date: Sep 25, 2026

NHTSA Recall No.: 26V539

Manufacturer Recall No.: A262554900

Manufacturer Information

Population

Manufacturer Name: General Motors, LLC

Address: 29427 Louis Chevrolet
Road
MAIL CODE 480-210-2V
WARREN MI, 48093

Total number of potentially involved: 306,511

Estimated percentage with defect: 10%

Vehicle Information

Vehicle 1: 2026-2026 CHEVROLET TRAILBLAZER

Product Category: Light Vehicles

Product Type:

Fuel / Propulsion: Spark Ignition Fuel

Production Dates: Nov 05, 2024 - Dec 18, 2024

Number of potentially involved: 7

Descriptive Information:

Manufacturing records were used to identify the affected population.

Vehicles produced outside of the suspect manufacturing window are not included in this recall.

Vehicle 2: 2024-2024 BUICK ENVISTA

Product Category: Light Vehicles

Product Type:

Fuel / Propulsion: Spark Ignition Fuel

Production Dates: Apr 01, 2024 - May 16, 2024

Number of potentially involved: 5,857

Descriptive Information:

Manufacturing records were used to identify the affected population.

Vehicles produced outside of the suspect manufacturing window are not included in this recall.

Part 573 Safety Recall Report

26V539**Vehicle 3:** 2024-2024 CHEVROLET TRAILBLAZER**Product Category:** Light Vehicles**Product Type:****Fuel / Propulsion:** Spark Ignition Fuel**Production Dates:** Apr 01, 2024 - May 04, 2024**Number of potentially involved:** 843**Descriptive Information:**

Manufacturing records were used to identify the affected population.

Vehicles produced outside of the suspect manufacturing window are not included in this recall.

Vehicle 4: 2025-2025 CHEVROLET TRAX**Product Category:** Light Vehicles**Product Type:****Fuel / Propulsion:** Spark Ignition Fuel**Production Dates:** Apr 01, 2024 - Dec 31, 2024**Number of potentially involved:** 159,821**Descriptive Information:**

Manufacturing records were used to identify the affected population.

Vehicles produced outside of the suspect manufacturing window are not included in this recall.

Vehicle 5: 2024-2024 BUICK ENCORE GX**Product Category:** Light Vehicles**Product Type:****Fuel / Propulsion:** Spark Ignition Fuel**Production Dates:** Apr 01, 2024 - Apr 11, 2024**Number of potentially involved:** 701**Descriptive Information:**

Manufacturing records were used to identify the affected population.

This recall only involves vehicles equipped with the standard rearview camera (RPO UVB). Vehicles equipped with Surround Vision (camera RPO UV2) and vehicles produced outside of the suspect manufacturing window are not included in this recall.

Vehicle 6: 2025-2025 CHEVROLET TRAILBLAZER

Part 573 Safety Recall Report

26V539

Product Category: Light Vehicles
Product Type:
Fuel / Propulsion: Spark Ignition Fuel
Production Dates: Apr 03, 2024 - Dec 31, 2024
Number of potentially involved: 73,665

Descriptive Information:

Manufacturing records were used to identify the affected population.

Vehicles produced outside of the suspect manufacturing window are not included in this recall.

Vehicle 7: 2025-2025 BUICK ENVISTA
Product Category: Light Vehicles
Product Type:
Fuel / Propulsion: Spark Ignition Fuel
Production Dates: May 06, 2024 - Dec 31, 2024
Number of potentially involved: 35,466

Descriptive Information:

Manufacturing records were used to identify the affected population.

Vehicles produced outside of the suspect manufacturing window are not included in this recall.

Vehicle 8: 2025-2025 BUICK ENCORE GX
Product Category: Light Vehicles
Product Type:
Fuel / Propulsion: Spark Ignition Fuel
Production Dates: Apr 03, 2024 - Dec 31, 2024
Number of potentially involved: 30,150

Descriptive Information:

Manufacturing records were used to identify the affected population.

This recall only involves vehicles equipped with the standard rearview camera (RPO UVB). Vehicles equipped with Surround Vision (camera RPO UV2) and vehicles produced outside of the suspect manufacturing window are not included in this recall.

Vehicle 9: 2026-2026 BUICK ENCORE GX
Product Category: Light Vehicles

Part 573 Safety Recall Report

26V539**Product Type:****Fuel / Propulsion:** Spark Ignition Fuel**Production Dates:** Dec 02, 2024 - Dec 02, 2024**Number of potentially involved:** 1**Descriptive Information:**

Manufacturing records were used to identify the affected population.

This recall only involves vehicles equipped with the standard rearview camera (RPO UVB). Vehicles equipped with Surround Vision (camera RPO UV2) and vehicles produced outside of the suspect manufacturing window are not included in this recall.

Defect / Noncompliance Description

Description of the defect or noncompliance:

General Motors has decided that a defect which relates to motor vehicle safety may exist in certain 2024 – 2025 model year Buick Envista, 2024 – 2026 model year Buick Encore GX and Chevrolet Trailblazer, and 2025 model year Chevrolet Trax vehicles. The rearview camera screen in these vehicles may display a distorted or blank image.

FMVSS1:**FMVSS2:****Description of the safety risk, including crash, fire, death, injury:**

If the rearview camera is not functioning properly, rear visibility is reduced, increasing the risk of a crash during a backing event.

Description of the cause:

An issue with the bonding process used to assemble the camera housing could weaken the adhesive bond on some assemblies.

Identification of any warning that can occur:

Component Manufacturer

Tier of Supplier:**Supplier Type:****Name:** Wuxi Sharp Optoelectronic Technology Co.**Address:** No. 60C, Minshan Rd., Xinwu District

Part 573 Safety Recall Report

26V539

Country: Wuxi Foreign States
China

Involved Components

Component Name 1: CAMERA ASM-RR VIEW DRVR INFO
Component Description: Rearview Camera
Component Part Number: 86554978, 86554977

Chronology

On May 20, 2025, GM opened an investigation into complaints involving inoperative rearview cameras. On September 4, 2025, GM decided to close its investigation as no defect trend was identified, while continuing to monitor field data at six-month intervals.

On March 25, 2026, GM opened a new product investigation based on a rise in claim rates identified during continued monitoring. GM's investigation determined that a plasma-cleaning treatment used to prepare the camera housing assembly could weaken the adhesive bond in some assemblies.

GM's analysis of field data identified an elevated rate of complaints among vehicles built between April and December 2024. The end of this suspect window coincides with a modification the supplier made to the plasma-cleaning fixture. GM identified 33,365 field complaints received between July 3, 2024 and May 30, 2026 that were potentially related to this condition and associated with the suspect production window.

GM is not aware of any accidents or injuries associated with this condition. On August 13, 2026, GM's Safety Field Action Decision Authority (SFADA) decided to conduct a safety recall.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Inspect, Replace

Consumer Advisories: ☐ Do Not Drive ☐ Park Outside

Description of remedy program:

Dealers will inspect and replace the rearview camera as necessary.

How remedy component differs from recalled component:

Replacement parts were produced outside the supplier's suspect manufacturing window.

Identify how/when recall condition was corrected in production:

Part 573 Safety Recall Report

26V539

Vehicles produced after December 31, 2024, were built with parts outside the supplier's suspect manufacturing window.

Reimbursement Plan

Description of reimbursement program:

Pursuant to 49 C.F.R. § 573.13(d)(1), all covered vehicles are under warranty, so reimbursement is not offered.

Period of reimbursement:

Costs to be reimbursed:

Address for reimbursement claims:

Recall Schedule

Description of recall schedule:

Dealers were notified on August 20, 2026. An initial first phase of owner remedy notification is estimated to mail on October 2, 2026. All other owners were mailed an interim notification on September 17 and 18, 2026. GM will provide an estimated end date for the final phase of owner remedy notification when timing is available.

Planned Dealer Notification Date: Aug 20, 2026 - Aug 20, 2026

☐ No Dealers

Planned Interim Owner Notification Date: Sep 17, 2026 - Sep 17, 2026

☐ No Owners

Planned Remedy Owner Notification Date: Oct 30, 2026

☒ Phased Recall

Date when VIN will be searchable: Aug 20, 2026