



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

26V607

Manufacturer Name: Jaguar Land Rover North America, LLC

Submission Date: Sep 23, 2026

NHTSA Recall No.: 26V607

Manufacturer Recall No.: D164

Manufacturer Information

Population

Manufacturer Name: Jaguar Land Rover North America, LLC

Address: 100 Jaguar Land Rover Way
Mahwah NJ, 07495

Total number of potentially involved: 1

Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2026-2026 LAND ROVER RANGE ROVER SPORT

Product Category: Light Vehicles

Product Type: Multipurpose Passenger Vehicle

Fuel / Propulsion:

Production Dates: Feb 16, 2026 - Feb 16, 2026

Number of potentially involved: 1

Descriptive Information:

Jaguar Land Rover is conducting a voluntary safety recall campaign involving a 2026 MY Land Rover Range Rover Sport built at the Solihull Vehicle Assembly Plant on February 16, 2026.

1 Land Rover Range Rover vehicle in the United States and Federalized Territories. The basis of the recall population of vehicles was determined through supplier analysis of build records, matched against JLR production records.

Defect / Noncompliance Description

Description of the defect or noncompliance:

A concern has been identified where a misalignment may have occurred during printed circuit board assembly resulting in potential deformation to the circuit board within the Powertrain Control Module (PCM).

FMVSS1:

FMVSS2:

Part 573 Safety Recall Report

26V607**Description of the safety risk, including crash, fire, death, injury:**

Deformation of the circuit board in the PCM can result in various effects including engine stall without prior warning. This can increase the risk of a crash.

Description of the cause:**Identification of any warning that can occur:**

Component Manufacturer

Tier of Supplier:**Supplier Type:**

Name: Robert Bosch Elektronik GmbH
Address: Postfach 10 01 07
Salzgitter Foreign States, 38201
Country: Germany

Involved Components

Component Name 1: Powertrain Control Module
Component Description: Powertrain Control Module
Component Part Number: R8A2-14C568-JB

Chronology

On 18 August 2026, the Powertrain Control Module (PCM) supplier informed JLR that a review of production records had identified a small number of modules which had been identified as having anomalous production parameters. Work was started to trace the affected parts to vehicles.

On 24 August 2026, a pre stop shipment meeting was held where it was confirmed that a number of at-risk PCMs had been assembled into new vehicles, and a Quarantine notice was issued together with an Update Prior to Sale instruction. It was reported that 4 additional vehicles had been manufactured in this condition, but records showed that they were in the hands of customers. The Product Safety and Compliance Committee (PSCC) requested that an investigation be launched to review the potential effect on vehicle operation to ascertain whether this issue would pose any elevated risk to the customers.

On 11 September 2026, the issue was further reviewed at PSCC where the range of possible effects on vehicle operation was reviewed and confirmed to include potential engine stall without warning. The

Part 573 Safety Recall Report

26V607

matter was referred to the PSCC Decision Forum.

On 16 September 2026, the PSCC Decision Forum agreed that the issue constitutes a safety defect and requested that a safety recall be launched to remedy the affected vehicles.

JLR has not received any claims or field reports in the US related to this issue.

There have been no reported accidents, injuries or fires in the US as a result of this concern.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Repair

Consumer Advisories: ☐ Do Not Drive ☐ Park Outside

Description of remedy program:

The vehicle will have the Powertrain Control Module (PCM) replaced.

There will be no charge to the owners for this repair.

How remedy component differs from recalled component:

The replacement module has been confirmed to not contain this defect.

Identify how/when recall condition was corrected in production:

The quality control mechanisms at the supplier have been updated to detect this condition.

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Recall Schedule

Description of recall schedule:

Notifications to dealers will occur on October 7, 2026. Distribution of owner notification letters will occur on or before November 20, 2026.

Planned Dealer Notification Date: Oct 07, 2026 - Oct 07, 2026 ☐ No Dealers

Planned Interim Owner Notification Date: Nov 20, 2026 - Nov 20, 2026 ☐ No Owners

Part 573 Safety Recall Report**26V607**

Planned Remedy Owner Notification Date:

☐ Phased Recall

Date when VIN will be searchable: