



Service Engineering Operations  
Customer Service Division

Ford Motor Company  
PO Box 1904  
Dearborn, Michigan 48121

May 27, 2026

**TO:** All U.S. Ford and Lincoln Dealers

**SUBJECT:** **NEW VEHICLE DEMONSTRATION / DELIVERY HOLD – Supplement #2**  
**Safety Recall 26S09**  
Certain 2021-2024 Model Year Edge and 2021-2026 Model Year Bronco Vehicles  
Infotainment Screen Blank

**REF :** **NEW VEHICLE DEMONSTRATION / DELIVERY HOLD – Supplement #1**  
**Safety Recall 26S09**  
Certain 2021-2024 Model Year Edge and 2021-2026 Model Year Bronco Vehicles  
Infotainment Screen Blank – Date: April 7, 2026

**New! REASON FOR THIS SUPPLEMENT**

- **SOFTWARE AVAILABILITY CHART:** *Software is available for all vehicles in this recall.*
- **SUPPLEMENTAL LABOR ALLOWANCES:** *Updated labor chart.*

**AFFECTED VEHICLES (U.S. Population Of Affected Vehicles 847,970):**

Vehicle	Model Year	Assembly Plant	Build Date Range
Edge	2021-2024	Oakville	August 14, 2020 through May 3, 2024
Bronco	2021-2026	Michigan	September 23, 2020 through February 10, 2026

Affected vehicles are identified in OASIS and FSA VIN Lists.

**REASON FOR THIS SAFETY RECALL**

On some of the affected vehicles, customers may experience an unexpected black infotainment screen due to the Accessory Protocol Interface Module (APIM) temporarily shutting down when detecting high temperatures. When the temporary APIM shutdown occurs, customers lose the ability to display the rearview camera image while in reverse gear. A rearview camera that does not display an image while in reverse gear can reduce the driver’s view of what is behind the vehicle, increasing the risk of a crash.

**SERVICE ACTION**

Before demonstrating or delivering any new in-stock vehicles involved in this recall, dealers are to update the APIM module software using the FDRS tool. This service must be performed on all affected vehicles at no charge to the vehicle owner. For new vehicle storage guidelines, refer to EFC13033, Storage Guidelines for New Vehicles.

**New! REMEDY AVAILABILITY CHART**

Reference this chart for current remedy availability.

Vehicle	Model Year	Remedy Available
Bronco	2026	Yes
	2025	Yes
	2024	Yes

Bronco	2023	Yes
	2022	Yes
	2021	Yes
Edge	2024	Yes
	2023	Yes
	2022	Yes
	2021	Yes

### **FSA PROGRAM OPTIONS**

<b>Program Option</b>	<b>Eligibility</b>	<b>Comments</b>
Mobile Repair	Yes	See <b>Mobile Service Repair Assessment Level</b> section below, if applicable.
Over-the-Air (OTA) Update	Yes	See <b>Over-The-Air (OTA) Updates</b> section of the FSA Policy Document, if applicable.
Rentals	No	See the <b>Rental Vehicles</b> section below, if applicable.
Alternative Transportation Available	No	See <b>Alternate Transportation</b> section in the FSA Policy Document.
Pickup & Delivery (PDL)	Yes	See <b>Pickup &amp; Delivery</b> section in the FSA Policy document.
Towing	No	See <b>Towing</b> section below, if applicable.
Essential Special Service Tools (ESST)	No	See <b>Technical Instructions</b> and/or <b>Workshop Manual (WSM)</b> as needed.
Administrative Allowance	No	See <b>Administrative Allowance</b> section in FSA Policy Document, and if applicable, <b>Labor Allowances</b> table below.
Owner Refunds	Yes	See <b>Owner Refunds</b> section below, if applicable.
Photo Submission	No	See <b>Repair Photo Submission</b> section below, if applicable.

**Note:** For further information on certain Program Options above, see the corresponding section within the FSA Policy Document.

### **OWNER NOTIFICATION MAILING SCHEDULE**

Owners' letters will be mailed the week of June 1, 2026. Owners will be given the option of installing the software update themselves through Over the Air Updates (OTA), or they can have their dealer perform the service for them.

### **PLEASE NOTE**

**Federal law requires dealers to complete this recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to \$27,168 per vehicle. Correct all vehicles in your new vehicle inventory before delivery.**

## **ATTACHMENTS**

- Technical Instructions
- Owner Notification
- Mobile Repair/Vehicle Pickup & Delivery Record
- Recall Reimbursement

## **REFERENCE MATERIAL**

- Warranty & Policy Manual (located on FMCDealer Warranty Portal Page):  
[www.fmcdealer.dealerconnection.com/content/fmcdealer/us/en/parts\\_service/wty.html](http://www.fmcdealer.dealerconnection.com/content/fmcdealer/us/en/parts_service/wty.html)
- FSA Policy Document (located on FMCDealer FSA Resources Page for Ford and Lincoln dealerships):  
[www.fmcdealer.dealerconnection.com/content/fmcdealer/us/en/parts\\_service/fsa/rsc.html](http://www.fmcdealer.dealerconnection.com/content/fmcdealer/us/en/parts_service/fsa/rsc.html)
- FSA Policy Document (located on the Fleet SharePoint site for Fleets with in-house warranty):  
<https://azureford.sharepoint.com/sites/OneWarrantySolution/usfleet/SitePages/Home.aspx>
- The Mobile Repair / Vehicle Pickup & Delivery Record can be found on the Technical Assistance tab in PTS:  
<https://www.fordtechservice.dealerconnection.com>

## **QUESTIONS & ASSISTANCE**

For questions and assistance, contact the Special Service Support Center (SSSC) via the SSSC Web Contact Site. The SSSC Web Contact Site can be accessed through the Professional Technician System (PTS) website using the SSSC link listed at the bottom of the OASIS VIN report screen or listed under the SSSC tab.

Customer Service Division

**Safety Recall 26S09 – Supplement #2****MOBILE SERVICE REPAIR ASSESSMENT LEVEL**

- Arrange for mobile repair at the owner's location
- All Vehicles Affected
  - 🔧 - Mobile Reprogramming (MRA1)

**OASIS ACTIVATION**

OASIS was activated on March 5, 2026.

**FSA VIN LISTS ACTIVATION**

FSA VIN Lists will be available through <https://web.fsavinlists.dealerconnection.com> on March 5, 2026. Owner names and addresses have been available since March 27, 2026.

**NOTE:** Your FSA VIN Lists may contain owner names and addresses obtained from motor vehicle registration records. The use of such motor vehicle registration data for any purpose other than in connection with this recall is a violation of law in several states, provinces, and countries. Accordingly, you must limit the use of this listing to the follow-up necessary to complete this recall.

**SOLD VEHICLES**

- Ford has not issued instructions to stop selling/delivering or driving used vehicles under this safety recall. Owners should contact their dealers for an appointment to have their vehicles remedied as soon as practicable.
- Immediately contact any of your affected customers whose vehicles are not on your VIN list but are identified in OASIS. Give the customer a copy of the Owner Notification Letter (when available) and schedule a service date.
- Correct other affected vehicles identified in OASIS which are brought to your dealership.
- Dealers are to prioritize repairs of customer vehicles over repairs of new and used vehicle inventory.

**IN-STOCK VEHICLES**

- Correct all affected units in your new vehicle inventory before delivery.
- Use OASIS to identify any affected vehicles in your used vehicle inventory.

**DEALER-OPERATED RENTAL VEHICLES**

The Fixing America's Surface Transportation (FAST) Act law effective June 2016 prohibits a rental company from selling, renting, or leasing vehicles subject to a safety or compliance recall. Please consult your legal counsel for legal advice.

**BRANDED / SALVAGED TITLE VEHICLES**

Affected branded / salvaged title vehicles are eligible for this recall.

**OWNER REFUNDS**

- **This Safety Recall must still be performed, even if the owner has paid for a previous repair. Claiming a refund will not close the recall on the vehicle.**
- Ford Motor Company is offering a refund for owner-paid repairs covered by this recall if the repair was performed before the date indicated in the reimbursement plan, which is posted with this bulletin. Owners are directed to seek reimbursement through authorized dealers or, at their option, directly through Ford Motor Company at PO Box 6251, Dearborn, MI 48121-6251.
- Dealers are also pre-approved to refund owner-paid emergency repairs that were performed away from an authorized servicing dealer after the end date specified in the reimbursement plan. Non-covered repairs, or those judged by Ford to be excessive, will not be reimbursed.
- Refunds will only be provided for the cost associated with APIM module software update.

**Safety Recall 26S09 – Supplement #2****RENTAL VEHICLES**

Rental vehicles are not approved for this program.

**ADDITIONAL REPAIR (LABOR TIME AND/OR PARTS)**

Additional repairs identified as necessary to complete the FSA should be managed as follows:

- For related damage and access time requirements, refer to the Warranty and Policy Manual / Section 6 – Ford & Lincoln Program Policies / General Information & Special Circumstances for FSAs / Related Damage.
- **For software module replacement:**
  - If module replacement is required, confirm if a Repair Validation Code (RVC) is required. Reference PTS / Technical Assistance / Components Requiring a Repair Validation Code.
  - Claiming the MT26S09RR labor operation code does **not** require an RVC code if no module replacement is required, however, clock times should be consistent with vehicle history on PTS.
- **For modules not requiring an RVC, use normal diagnostics.**
- **For vehicles within new vehicle bumper-to-bumper warranty coverage, no SSSC approval is required**, although related damage must be on a separate repair line with the “Related Damage” radio button checked.
  - Ford vehicles – 3 years or 36,000 miles
- **For vehicles outside new vehicle bumper-to-bumper warranty coverage:**
  - Submit an Approval Request to the SSSC Web Contact Site before completing the repair.
- See “Additional Repair Info” in the FSA Policy Document for further Terms and Conditions.

**CLAIMS PREPARATION AND SUBMISSION**

- **Technician Competency Requirement:** The STST Competency 10 certification requirement in the U.S. market only will be enforced starting with repair orders opened on or after August 31, 2024. FSA repairs will be rejected, and the claim will not be paid if the repairing technician is not certified in STST Competency 10 FSA. See EFC15936 for more details.
- **Software Verification Approval Code Requirement:** Beginning with Repair Orders (ROs) opened on or after January 15th, 2025, new FSA software repairs and the first phase of already launched FSAs will require Software Verification and an approval code provided by Ford. The approval code will be required when performing software repairs using the FDRS and IDS. See EFC17526 for more details.
- **Claim Entry:** Enter claims using Dealer Management System (DMS) or One Warranty Solution (OWS) online.
  - When entering claims, select claim type **31**: Field Service Action. The FSA number 26S09 is the subcode.
  - If other services are requested on the same RO, please complete them. Once they are completed, and if the customer elects to take delivery of their vehicle while waiting for parts to arrive to complete this program, dealers should close the repair order. Reference to W&P manual section 1.3.09 for detailed information associated with these applicable process steps.
  - For additional claims preparation and submission information, refer to the Recall and Customer Satisfaction Program (CSP) Repairs in the OWS User Guide.

**Safety Recall 26S09 – Supplement #2****CLAIMS PREPARATION AND SUBMISSION – Continued:**

- **Related Damage/Additional labor and/or parts:** Must be claimed as Related Damage on a separate repair line from the FSA with the same claim type and subcode as described in Claim Entry above.  
**IMPORTANT:** Click the Related Damage Indicator radio button.
- **Refunds:** Submit refunds on a separate repair line.
  - Program Code: 26S09                      - Misc. Expense: ADMIN
  - Misc. Expense: REFUND                      - Misc. Expense: 0.2 Hrs.
  - Multiple refunds should be submitted on one repair line and the invoice details for each repair should be detailed in the comments section of the claim.

**Safety Recall 26S09 – Supplement #2**

**LABOR ALLOWANCES**

**Note:** Only one labor operation may be claimed from this table. (Additional supplemental labor operations may be claimed from the Supplemental Labor Allowances table.)

Description	Labor Operation	Labor Time Hour(s)
<p><u>Software Update:</u> Update APIM module software using the FDRS tool. Can not be combined with 26S09C. <b>This labor operation code closes the FSA.</b></p>	26S09B	0.9
<p>APIM Software at the latest level. Time to submit the Software Validation Code (SVC). Can not be combined with 26S09B and MT26S09RR. <b>This labor operation code closes the FSA</b></p>	26S09C	0.3

**New! SUPPLEMENTAL LABOR ALLOWANCES These labor operation codes DO NOT close the FSA.**

**Note:** Claim any relevant supplemental labor operations in addition to the primary labor operation.

Description	Labor Operation	Labor Time Hour(s)
Additional time to update dependent modules, if necessary	MT26S09D	Up to <b>6.5</b>
<p>APIM/<b>GWM/TCU</b> software failed and/or APIM/<b>GWM/TCU</b> module replacement required. SSSC approval is not required unless M-Time is exceeded. <b>Clock times should be consistent with vehicle history on PTS.</b></p>	MT26S09RR	Up to <b>7</b>
<p>Mobile Service: <b>This allowance is only for <u>non-eligible</u> 2026 Remote Experience Program Dealers.</b> Can be used when the repair takes place away from the dealership. If Additional Time is Required Due to Travel, Please Submit an SSSC Approval Form.</p>	26S09MM	0.5
<p><b>Ford Vehicle Pick-Up &amp; Delivery Allowance:</b> <b>This allowance is only for <u>non-eligible</u> 2026 Remote Experience Program Dealers.</b> <b>NOTE:</b> This allowance is for dealer-performed vehicle Pick-Up &amp; Delivery for dealership repairs only. Can only be claimed once, regardless of outstanding FSAs repaired.</p>	26S09PP	0.5

**PARTS REQUIREMENTS / ORDERING INFORMATION**

Parts are not required to complete this repair.

## CERTAIN 2021-2024 MODEL YEAR EDGE AND 2021-2026 MODEL YEAR BRONCO VEHICLES INFOTAINMENT SCREEN BLANK — ACCESSORY PROTOCOL INTERFACE MODULE (APIM) SOFTWARE UPDATE

### **NEW !** SERVICE PROCEDURE

**IMPORTANT!** The Service Technician Specialty Training (STST) Competency 10 certification requirement in the U.S. market only will be enforced starting with repair orders opened on or after August 31, 2024. Field Service Action (FSA) repairs will reject and the claim will not be paid if the repairing technician is not certified in STST Competency 10 FSA. See Electronic Field Communication (EFC) 15936 for more details.

### Module Programming

#### **VCM3**

*It is highly recommended that a Vehicle Communication Module 3 (VCM3) or Vehicle Communication Measurement Module (VCMM) be used when updating vehicle software. Using a VCM3 or VCMM reduces the chances of programming failures on modules when very large files are being transferred.*

**FSA Quick Response Team – Assistance for Software Related Concerns Performing This FSA**  
*If you experience software programming errors or multiple programming failures, require module replacement, or have difficulty generating a Software Verification Code (SVC) for this FSA, contact the FSA Quick Response team using the link shown in Figure 3 from the Ford Diagnostic and Repair System (FDRS).*

- *A Repair Validation Code (RVC) will be provided, if needed, by the FSA Quick Response team if module replacement is required.*

**If you are provided with an RVC:**

- **For this program it is NOT necessary to contact the SSSC for additional approvals, this includes the following:**
  - additional labor hours
  - module replacement
  - related damage

**NOTE:** Before beginning programming make sure the vehicle has enough fuel to idle for 2 hours.

**NOTE:** Program appropriate vehicle modules before performing diagnostics and clear all Diagnostic Trouble Codes (DTCs) after programming. For DTCs generated after programming, follow normal diagnostic service procedures.

**NOTE:** *The following modules may each require more than one software update: Gateway Module (GWM), Telematic Control Unit (TCU) and/or Accessory Protocol Interface Module (APIM).*



*1. Launch Ford Diagnostic and Repair System (FDRS).*

**NOTE:** Vehicle information is automatically retrieved by the diagnostic software and a Network Test is run. Vehicle identification data appears on the screen when this is complete.

*2. Check the vehicle's **State Of Charge (SOC)** by performing the following:*

- a. Double click the battery icon in the lower right corner of FDRS.*
- b. Make sure the SOC reads over 50%. If the SOC is less than 50%, fully recharge the vehicle's 12-volt battery using the DCA-8000 tester to verify battery condition.*
- c. Remove the charger from the vehicle once the battery is fully charged. Using FDRS, navigate to toolbox tab > BCM > **Reset Battery**. Monitor Sensor Learned Values application. Perform the BMS reset.*

3. Connect the Rotunda battery tester and charger and set it to maintain 12.6 to 13.6 volts. Monitor the voltage real time using the indicator at the bottom right corner of FDRS to make sure that it is within this range. **The SOC must be greater than 50% to continue with this FSA.**

**NOTE:** Verify that the negative cable of the charger is installed on a chassis or engine ground, and not the 12-volt battery negative terminal to prevent the battery saver mode from activating on the vehicle.

**NOTE:** If the diagnostic software does not load or if the vehicle cannot be identified properly, make sure there is a good internet connection, and the Vehicle Communication Module (VCM) is properly connected to the Data Link Connector (DLC).

**NOTE:** Make sure the Ford Diagnostic and Repair System (FDRS) does not enter sleep mode during module configuration.

4. Click **Read VIN from Vehicle** or manually enter the Vehicle Identification Number (VIN).

**NOTE:** Available modules are shown on the left-hand (LH) side of the screen, and available procedures are listed on the right-hand (RH) side of the screen. Modules that are communicating are highlighted in green.

5. Select **Toolbox** tab.

6. Select **Multi-Module** tab.

7. Select **Read the Configuration Data**. Click **RUN**.

*8. Select the **SW Updates** tab.*

*9. Is there a software update available for the APIM?*

***Yes** - Proceed to Step 10.*

***No** - Proceed to Step 11.*



10. Download and run the APIM Software Update application on the FDRS and follow the on-screen prompts. For instructions on the USB update process or if any error conditions are experienced during programming refer to Workshop Manual (WSM) Section 418-01A > General Procedures > Module Programming. Upon completion of the APIM update, proceed to Step 17.

11. Is there a software update available for the Gateway Module (GWM)?

**Yes** - Proceed to Step 12.

**No** - Proceed to Step 13.

12. Download and run the GWM Software Update application on the FDRS and follow the on-screen prompts. For instructions on the USB update process or if any error conditions are experienced during programming refer to Workshop Manual (WSM) Section 418-01A > General Procedures > Module Programming.

13. Is there a software update available for the Telematic Control Unit (TCU)?

**Yes** - Proceed to Step 14.

**No** - Proceed to Step 15.

14. Download and run the TCU Software Update application on the FDRS and follow the on-screen prompts. For instructions on the USB update process or if any error conditions are experienced during programming refer to Workshop Manual (WSM) Section 418-01A > General Procedures > Module Programming.

15. After GWM and/or TCU updates are performed, has a new APIM update become available?

**Yes** - Return to Step 10.

**No** - Go to Step 16.

16. Is there another GWM or TCU update available?

**Yes** - Return to Step 11.

**No** - Go to Step 17.

17. From the list on the RH side of the screen, select **Self-Test** and click **RUN**.

18. Click the **Run Selected Tests** button in the lower right.

19. Click the **Clear & Retest** button at the top of the screen to clear Diagnostic Trouble Codes (DTCs) in all modules.

**20. This FSA requires a Software Verification Approval Code after performing the software update. Please follow the instructions below to obtain the approval code. The claim will not be paid and the FSA will remain open if a Software Verification Approval Code is not provided. For more information, see EFC 17526.**



21. Select the **SW Updates** tab (1). See Figure 1.
22. **Warranty Dealer Code** (2) - Change the displayed PA code as necessary. See Figure 1.
23. Select the **FSA** (3) from the drop-down menu. See Figure 1.
24. Select **Submit** (4). See Figure 1.




FIGURE 1




25. Does the FDRS Field Service Action Software Verification Status display a **Complete** status?  
 See Figure 2.

**Yes** - This FSA is complete. The FDRS Field Service Action Software Verification will provide an on-screen Software Verification approval code.

**NOTE:** The vehicle may be returned to the customer when the Software Verification Form provides a Complete status for ALL modules listed.

**No** - Proceed to Step 26.

**NOTE:** *The complete status may not be received until up to 4 APIM updates and the dependent module updates (GWM or TCU) are complete. If an SVC cannot be obtained, additional updates to the APIM, GWM, or TCU may be needed to reach the correct software level for this FSA.*




**FIGURE 2**



26. Does the FDRS Field Service Action Software Verification Status display a **Not Complete** status (1)?  
 See Figure 3.

**Yes** - Proceed to next step.  
**No** - Proceed to Step 30.



**FIGURE 3**

27. Have the module software updates in the FSA been reattempted?

**Yes** - Proceed to Step 28.  
**No** - Reattempt the software update programming steps in the FSA.

28. Use the "Click Here to submit a request to the FSA quick response team" link (2) shown in Figure 3. Follow the on-screen prompts to enter the following information:

- Phone number (such as cell) where you can be reached for immediate support
- Any specific error messages received when programming was attempted
- Battery SOC when programming was attempted
- Scan tool software level
- Any known aftermarket devices installed on the vehicle
- Detailed documentation of the diagnostic steps already performed attempting to determine why the module will not update to the correct level

29. Upon completion of the Technical Support Request (TSR) form, click "Submit Request". The TSR will be routed to a prioritized FSA quick response team queue. This team will contact you via phone using the contact information provided in the form. Please follow the recommendations from the FSA quick response team to resolve any issues preventing SVC generation.



30. If the FDRS Field Service Action Software Verification Status displays "**An error occurred. Unable to retrieve FSA information**", please reattempt to generate an SVC. The error can be caused by a connectivity or server issue where the status of the FSA cannot be verified. This is typically resolved upon reattempting to generate an SVC. See Figure 4.

The screenshot displays the FDRS Field Service Action Software Verification interface. On the left, there are three sections: MS1 (containing HVAC, SODL, and SOBR buttons), MS2 (containing ABS, BCM, GWM, IPMA, OCCM, and FSCM buttons), and MS3 (containing ACM, IPC, TCU, and TRM buttons). On the right, there is a table of software updates:

All	Favorites	Offline	Multi-Module	SW Updates	Programmable Features	Guided Routines
★	▲			ACM - Audio Front Control Module (ACM) Software Update		Download
★	▲			IPC - Instrument Panel Cluster (IPC) Software Update		Download
★	▲			TCU - Telematics Control Unit (TCU) Module Software Update		Download

Below the table, the text reads: "FDRS checks the software level in all modules during Vehicle ID. If a software update is available for any module, then the tool needed to download and install the update will be shown above. If directed to perform module software updates by a service publication, follow the instructions closely to ensure affected modules are updated to the latest levels."

The "Field Service Action Software Verification" section includes a "Warranty Dealer Code" field, a dropdown menu with "24S09" selected, and a "Submit" button. Below this is a note: "Note: With all software updates complete, there may be further repairs required to close the FSA. Refer to the FSA documentation for additional requirements."

A red-bordered error message is displayed at the bottom: "An error occurred. Unable to retrieve FSA information." An arrow points to this message from the right.

At the bottom of the interface, the vehicle information "FTTW8E94PRA33711 Maverick 2.0L EcoBoost (240PS)" and "FDRS R44 2025.02.10\_09.06.09" are shown, along with a "Not Connected" status and a "Click the icon to connect." button.

FIGURE 4



## Important Information for Module Programming

**NOTE:** When programming a module, use the following basic checks to make sure the programming completes without errors.

- Make sure the 12-volt battery is fully charged before carrying out the programming steps and connect FDRS/scan tool to a power source.

**NOTE:** A good internet connection is necessary to identify the vehicle and to load the diagnostic software.

- Inspect the Vehicle Communication Module II (VCM II)/Vehicle Communication Module 3 (VCM3) or the Vehicle Communication and Measurement Module (VCMM) and the cables for any damage. Make sure scan tool connections are not interrupted during programming.
- A hardwired connection is strongly recommended.
- Turn off all unnecessary accessories (radio, heated/cooled seats, headlamps, interior lamps, HVAC system, etc.) and close doors.
- Turn the accessories back on after programming has completed.
- Disconnect/depower any aftermarket accessories (remote start, alarm, power inverter, CB radio, etc.).
- Follow all scan tool on-screen instructions carefully.
- Disable FDRS/scan tool sleep mode, screensaver, hibernation modes.
- Create all sessions key on engine off (KOEO). Starting the vehicle before creating a session will cause errors within the programming inhale process.

## Recovering a module when programming has resulted in a blank module

- a. Disconnect the VCM II/VCM3 or the VCMM from the data link connector (DLC) and your computer.
- b. After ten seconds, reconnect the VCM II/VCM3 or the VCMM to the DLC and the PC. Launch FDRS. The VCM II/VCM3 or the VCMM icon should turn green in the bottom right corner of the screen. If it does not, troubleshoot the FDRS to VCM connection.
- c. If you are using the same FDRS as the initial programming attempt, select the appropriate VIN from the Vehicle Identification menu. If you are using a different FDRS, select "Read VIN from Vehicle" and proceed through the Network Test.
- d. In the Toolbox menu, navigate to the failed module and Download/Run Programmable Module Installation (PMI). Follow the on-screen prompts. When asked if the original module is installed, select "No" and continue through the installation application.
- e. Once programming has completed, a screen may list additional steps required to complete the programming process. Make sure all applicable steps are followed in order.



**Safety Recall 26S09**

**Mobile Repair / Vehicle Pickup and Delivery Record**

VIN \_\_\_\_\_ received (check one):

- Mobile Repair
- Pickup and/or delivery service

As outlined below for the 26S09 Field Service Action program.

Mobile Repair – Date: \_\_\_\_\_

OR

Pickup – Date: \_\_\_\_\_

Delivery – Date: \_\_\_\_\_

\_\_\_\_\_  
Repair Order #

\_\_\_\_\_  
Repair Order Date

\_\_\_\_\_  
Service Manager Signature

\_\_\_\_\_  
Date

**Ford Motor Company**  
**Recall Reimbursement Plan for 26S09**

*Ford and Lincoln dealers are in the best position to quickly and efficiently process reimbursement requests. However, federal legislation requires all motor vehicle manufacturers to establish processes through which customers may seek recall reimbursement directly from the manufacturer or the dealers.*

*Regarding the specific reimbursement plan for Recall # 26S09, owners who have paid for service to remedy the defect or noncompliance must have had that service performed before June 1, 2026. After this date, if repairs related to this recall are performed by a non-Ford repair facility in an emergency, customers must submit any refund requests through their dealership. As required by this federal regulation, Ford Motor Company submitted the details of its latest General Recall Reimbursement Plan in a letter to the National Highway Traffic Safety Administration (NHTSA) in May 2025. The following is the text of that letter and the Plan:*

**General Recall Reimbursement Plan**  
(As submitted to the NHTSA)

Pursuant to the requirements set forth in 49 CFR Part 573 and Part 577 of the Code of Federal Regulations, Ford Motor Company (Ford) is submitting required information pertaining to our general reimbursement plan for the cost of remedies paid for by vehicle owners before they are notified of a related safety recall.

Set forth below is Ford's general plan to reimburse owners and purchasers for costs incurred for remedies in advance of notification of potential safety-related defects or non-compliances pursuant to Part 573.6 (c)(8)(i). This plan has not changed since our May 21, 2025 submission.

Reimbursement Notification

Ford's notice to a vehicle owner in accordance with 49 CFR Part 577 will indicate that Ford is offering a refund if the owner paid to have service to remedy the defect or noncompliance prior to a specified ending date. In accordance with Part 573.13 (c)(2), this ending date will be defined as a minimum of ten calendar days after the date on which Ford mailed the last of its Part 577 notifications to owners and will be indicated in the specific reimbursement plan available to owners for an individual recall. This notice will direct owners to seek eligible reimbursement through authorized dealers or, at their option, directly through Ford at the following address:

Ford Motor Company  
P.O. Box 6251  
Dearborn, MI 48121-6251

Ford notes that this rule allows for the identification of a beginning date for reimbursement eligibility. Under the rule, an owner who paid to remedy the defect or noncompliance prior to the identified beginning date would not be eligible for reimbursement. Ford generally has not established such a beginning date for reimbursement eligibility and does not presently anticipate changing this general policy. However, in any case where Ford determines a beginning date is appropriate, Ford will indicate that date in the owner notice. As permitted by 577.11(e), Ford may not include a reimbursement notification when all vehicles are well within the warranty period, subject to approval by the Agency.

## Costs to be Reimbursed

For vehicles, reimbursement will not be less than the lesser of:

- The amount paid by the owner for the remedy that specifically addressed and was reasonably necessary to correct the defect or noncompliance that is the subject of the recall, or
- The cost of parts for the remedy (to be no more than the manufacturer's list retail price for authorized part(s), plus associated labor at local labor rates, miscellaneous fees (such as disposal of waste) and taxes.

For replacement equipment, reimbursement will be the amount paid by the owner for the replacement item (limited by the amount of the retail list price of the defective or noncompliant item that was replaced, plus taxes, where the brand or model purchased by the owner was different than the brand or model that was the subject of the recall). If the item of motor vehicle equipment was repaired, the reimbursement provisions identified above for vehicles will apply.

Ford notes that costs incurred by the owner within the period during which Ford's original or extended warranty would have provided for a free repair of the problem will not be eligible for reimbursement, as provided by Part 573.13 (d)(1).

## Entities Authorized to Provide Reimbursement

Ford will continue to use authorized dealers to reimburse owners under the specific reimbursement plans for a particular recall and will encourage owners to pursue requests for reimbursement directly through dealers to expedite reimbursement. Ford will also provide a mailing address to which customers can, at their option, send requests for reimbursement directly to Ford, as previously noted. Requests for reimbursement sent directly to Ford may take up to 60 days to process. Whether the owner chooses to pursue reimbursement requests through a dealer or directly through Ford, the owner will be directed to submit the required documentation, upon which reimbursement eligibility will be determined.

## Required Documentation

The reimbursement determination will depend upon the information provided by the customer. Consistent with Part 573.13 (d)(4) the following information must be submitted:

- Claimant name and address
- Vehicle make, model and model year
- Vehicle identification number (VIN) and, for replacement equipment, a description of such equipment or, for tires, the model, size and TIN (DOT code)
- Identification of the recall number (either the Ford recall number or the NHTSA recall number)
- Identification of the owner of the recalled vehicle at the time that the pre-notification remedy was obtained
- An original receipt for the pre-notification remedy that includes a breakdown of the amount for parts, labor, other costs and taxes, including costs for the replacement item. Where the receipt covers work other than to address the recall or noncompliance, Ford may require the claimant to separately identify costs that are eligible for reimbursement.
- If the remedy was obtained during the warranty repair did not correct the problem related to the recall

Failure to submit all the above information may result in denial of the reimbursement request.

### Additional Information

The Part 577 required owner notice will provide a toll-free telephone number through which specific information about the reimbursement plan can be requested from Ford. This general reimbursement plan will be incorporated into notifications pursuant to Part 573.6 by reference. Information specific to an individual recall also may be incorporated into the Part 573.6 notification.