

Dealer Notification

Recall Campaign 300: Driver Airbag (DAB) Module Inflator Inspect & Replace (Remedy Available)

August 05, 2026

Document Topic	Date
• Technical Service Bulletin (TSB) 26-01-067H posted on Hyundai Tech Info – Remedy Available	08/05/2026

IMPORTANT: As required by federal law, dealers must not deliver new vehicles for sale or for lease to customers until all open recalls have been performed. Dealers must perform all open recalls on used vehicles, demo, and rental vehicles prior to placing them into customer use and whenever an affected vehicle is in the shop for any maintenance or repair.

To check vehicle specific recall applicability, access the “Vehicle Information” screen via WebDCS.

Recall Description

Certain Elantra (MD, UD) and Elantra GT (GD) vehicles may be equipped with hybrid airbag inflators that contain propellant outside of density specifications. Lower-density propellant can cause increased internal inflator pressures, potentially leading to rupture of the inflator during airbag deployment. An airbag inflator rupture increases the risk of severe injury or fatality to the driver, passengers, or both.

Applicable Vehicles (Certain)

- 2016MY Elantra GT (GD) produced 04/18/2015 – 08/24/2015
 - Built by Hyundai Motor Company (“HMC”) – VIN prefix “KMH”
- 2016MY Elantra (MD) produced 04/21/2015 – 08/21/2015
 - Built by HMC – VIN prefix “KMH”
- 2015-16MY Elantra (UD) produced 10/14/2014 – 05/13/2015
 - Built by Hyundai Motor Manufacturing Alabama (“HMMA”) – VIN prefix “5NP”

Remedy Information

Follow the service procedure outlined in **TSB 26-01-067H** to inspect the Driver Airbag (DAB) module inflator and if necessary, replace it.

- Recommended Technician Certification/Requirements: Hyundai Specialist (or higher)

Recommended Alternative Transportation

A Service Rental Car (SRC) is recommended for customers when their vehicle is required to remain at the dealership for an extended period of time. An SRC may also be necessary when the duration of the repair procedure, or any additional work identified during a service visit, extends the customer’s visit. In the event an SRC is unavailable, alternative transportation options—such as a third-party rental or rideshare—may be offered.

Parts Information

Please refer to **TSB 26-01-067H** for the latest parts information.

- Inventory Management: **Part number 3Y569-30010QQH**
 - An applicable Recall 300 VIN will be required to order this part number.

PARTS RETURN

- Please refer to **TSB 26-01-067H** for the latest information regarding parts return.
- Once the part is replaced, please HOLD the part and do not discard it until an HMA authorized third party arrives to pickup and transport the part.
- Please ensure the original part is packaged with the original hazmat packaging/labels.

- For any questions regarding parts return/pickup, please contact the Warranty Technical Center (WTC) at wtc@hmausa.com.

Warranty Information

Per TSB 26-01-067H, this service procedure includes:

- Labor
 - 0.6 M/H – DAB Module Inflator Inspection & Replacement
 - 0.6 M/H – DAB Module Inflator Inspection (if non-OEM part is identified)
- Parts
 - Driver Air Bag Inflator
- **Digital Documentation:**
 - This TSB includes a repair validation photo. Op times include VIN, mileage, and repair validation photo(s) as outlined in the Digital Documentation Policy. A photo of the non-OEM (not original) DAB module inflator if the part is identified as non-OEM or a photo of the original inflator next to the new, installed inflator if the original part is identified as OEM.

Sample Customer Talk Tracks

1. For Customers on the phone:

*"I reviewed your vehicle for any open campaigns or recalls and found that there is an open recall 300 for which a remedy is available. This recall involves the driver airbag inflators that might contain propellant outside of density specifications, which may cause increased internal inflator pressures and lead to rupture of the inflator during airbag deployment, increasing the risk of severe injury or fatality. This recall provides instructions to inspect the driver airbag (DAB) module inflator and if necessary, replace it. This service will be provided **at NO cost to you**. If you do not feel comfortable operating your vehicle until the remedy is completed, we can offer you a loaner vehicle or other alternative transportation options **at NO cost to you**. Please let me know if I can assist you in scheduling an appointment for this recall to be completed."*

2. For Customers at a dealership in the service lane:

*"During your visit today, I found there is an open recall 300 for which a remedy is available. This recall involves the driver airbag inflators that might contain propellant outside of density specifications, which may cause increased internal inflator pressures and lead to rupture of the inflator during airbag deployment, increasing the risk of severe injury or fatality. This recall provides instructions to inspect the driver airbag (DAB) module inflator and if necessary, replace it. This service will be provided **at NO cost to you**. If you do not feel comfortable operating your vehicle until the remedy is completed, we can offer you a loaner vehicle or other alternative transportation options **at NO cost to you**."*

3. For Customers concerned with the performance of their vehicle:

"If you experience any concern(s) related to the performance of your vehicle, reach out to your nearest Hyundai dealer for assistance. If you do not feel comfortable operating your vehicle while until the remedy is completed, we can offer alternative transportation."

Best Practice Checklist

- **Reservation:**
 - Has WebDCS been referenced for additional open campaigns or recalls?
 - ☐ Yes
 - ☐ **No** – Please ensure all open campaign(s)/recall(s) are identified and addressed.
- **Readiness:**
 - Are the applicable parts, tools, and equipment on-hand and ready to perform the service procedure?
 - ☐ Yes
 - ☐ **No** – Please ensure any necessary parts, tools, and equipment are on hand before any repair work.
- **Reception:**

Has the customer provided their authorization to perform repairs?

- ☐ Yes
- ☐ **No** – Customers must be consulted and provide approval before proceeding with any repairs on their vehicle.

Has the customer been offered alternative transportation?

- ☐ Yes
- ☐ **No** – Please provide the customer a loaner vehicle (if available) and if necessary, alternative transportation, while the remedy is being implemented.

Has the customer been informed of the expected repair duration and a timeframe for status updates?

- ☐ Yes
- ☐ **No** – Customers are to be informed of estimated repair duration and pick-up times after repairs are completed.

- **Repair:**

Does the Technician meet the recommended training requirements to complete this campaign?

- ☐ Yes
- ☐ **No** – Please reference the “Remedy Information” section on this document and ensure a qualified technician performs the service procedure.

- **Return:**

Ensure the customer’s contact information is up-to-date for follow-up conversations regarding their vehicle’s status.

- ☐ Yes
- ☐ **No** – Please ensure the customer’s latest information is accurately recorded in order to provide future updates.

Anticipated FAQs

Q1: What is the issue?

A1: The subject dual-stage hybrid airbag inflators provided in specific production lot(s) by the supplier might contain propellant outside of density specifications. Lower-density propellant can cause increased internal inflator pressures, potentially leading to rupture of the inflator during airbag deployment. Hyundai has not confirmed a rupture, but given the increased inflator pressures, Hyundai is conducting this recall out of an abundance of caution and to recover parts for continued investigation.

Q2: What are the affected vehicles?

A2: Affected vehicles include the following:

- Certain 2016MY Elantra GT (GD) produced 04/18/2015 – 08/24/2015
 - Built by Hyundai Motor Company (“HMC”)
- Certain 2016MY Elantra (MD) produced 04/21/2015 – 08/21/2015
 - Built by HMC
- Certain 2015-16MY Elantra (UD) produced 10/14/2014 – 05/13/2015
 - Built by Hyundai Motor Manufacturing Alabama (“HMMA”)

Q3: What is the safety concern?

A3: An airbag inflator rupture increases the risk of severe injury or fatality to the driver, passengers, or both.

Q4: Have there been any accidents or injuries?

A4: As of the date of the decision to conduct this recall (05/14/2026), there are no incidents, crashes, fires, or injuries related to this condition in the U.S. market.

Q5: Will a Dealer or Port Stop Sale be issued?

Dealer: No, as the vehicles being recalled or no longer in production or offered for sale in the U.S.

Port: No. All vehicles are past the port.

Q6: What will be done during the recall service once the remedy is available?

A6: All owners of the subject vehicles will be notified by first class mail with instructions to bring their vehicle to a Hyundai dealer for inspection of the inflator serial number and replacement, if necessary. This remedy will be offered at no cost to owners for all affected vehicles, regardless of whether the affected vehicles are still covered under Hyundai's New Vehicle Limited Warranty. Additionally, Hyundai will provide owners of affected vehicles reimbursement for out-of-pocket expenses incurred to obtain a remedy for the recall condition in accordance with the reimbursement plan submitted to NHTSA on March 2, 2026.

Q7: When will owners be notified?

A7: Owners are planned to be notified in August 2026 of a remedy available. Owners were previously notified of a remedy not available in mid-July 2026.

Contact Reference

Please see the list below for commonly referred to contacts. Thank you for your prompt attention to this important safety matter and continued commitment to Hyundai customers.

Key Contact Information		
Dealer Support	Contact Information	Description
Parts	HyundaiPartsHotline@MobisUSA.com 1-800-545-4515	Parts ordering hotline
Special Service Tools	hyundaistools@hmausa.com 1-855-763-9199	For ordering SST parts
Techline	1-800-325-6604	Vehicle Technical Support for Hyundai Dealer Technicians
Warranty HELP Line	1-877-446-2922	Warranty Claim questions for Hyundai Dealers
Warranty Prior Approval (PA) Center	PA@hmausa.com	Warranty Prior Approval (PA) Center for Hyundai Dealers
Xtime Technical Support	Support@xtime.com 1-866-984-6355	Assistance with Car Care Scheduling: Appointment / Shop Capacity Management / Campaign Integration / Operation Codes
AutoLoop Technical Support	Support@autoloop.com 1-877-850-2010	Assistance with Car Care Scheduling: Appointment / Shop Capacity Management / Campaign Integration / Operation Codes
CDK Technical Support	https://serviceconnect.support.cdk.com/	Assistance with Car Care Scheduling: Appointment / Shop Capacity Management / Campaign Integration / Operation Codes
Customer Support	Contact Information	Description
Hyundai Customer Care Center (Recall / Campaign Questions)	1-855-671-3059	Customer questions or concerns related to recall or service campaigns
Hyundai Recall / Campaign Website	www.hyundaiusa.com/recall	Updated information related to the specific recall or service campaign
Hyundai Customer Care Center	1-800-633-5151	Customers general questions, non-campaign related
Hyundai Roadside Assistance	1-800-243-7766	Hyundai Roadside Assistance
Key Reference Information		
Name	Source	
Car Care Scheduling (Xtime) - Tutorials	www.HyundaiDealer.com > Service > Dealer Resources > DocumentsLibrary > Car Care Scheduling	
Car Care Scheduling (Xtime) - Recall Appointment Notification	1. Log into Xtime 2. Under the menu at the top left, select "Configure" 3. Under the dealership tab, select "Email Communication" 4. Slide the toggle to "Advanced" 5. Populate as many emails as desired in the "Parts Desk Email Field"	
Parts – Campaign Parts Management (CPM) Procedure	As applicable; www.HyundaiDealer.com > Parts > Documents Library > Campaign Parts Management	
Service Rental Car (SRC) Program	SRC Documentation: www.HyundaiDealer.com > Service tab > Documents Library > Service Rental Car TSD: www.HyundaiDealer.com > Service tab > SRC Fleet Mgmt Software Insurance: www.HyundaiDealer.com > Service tab > SRC Insurance	
Technical Service Bulletin (TSB)	www.HyundaiDealer.com > Service tab > Hyundai Tech Info	
Uncompleted Campaign VIN Listing	A listing of vehicles is located on WEBDCS > SERVICE tab > select UNCOMPLETED CAMPAIGN VIN LISTING – Dealer Stock (New, SRC, CPO, etc.) and Retailed.	
Recall Campaign Website	www.hyundaiusa.com/recall	
NHTSA Website	www.safercar.gov	

Appendix

Document Topic	Date
• Technical Service Bulletin (TSB) 26-01-067H posted on Hyundai Tech Info – Remedy Available	08/05/2026
• Remedy Not Available	05/15/2026