

[📎 Recall 300 - ARC Driver Airbag - Dealer Notification \(No Remedy\) \(posted 05.15.26\).pdf](#)

Hyundai Motor America (HMA) has launched **Remedy Not Available** for Recall 300: Driver's Side Airbag Inflator Replacement.

A. Recall Description:

The subject dual-stage hybrid airbag inflators provided in specific production lot(s) by the supplier might contain propellant outside of density specifications. Lower-density propellant can cause increased internal inflator pressures, potentially leading to rupture of the inflator during airbag deployment.

An airbag inflator rupture increases the risk of severe injury or fatality to the driver, passengers, or both.

B. Affected Vehicles:

- **VIN Identification:** Use the 'Vehicle Information' screen in WebDCS under the 'Campaign Not Performed' section to determine recall applicability.

- 2015-2016MY Elantra (UD) produced 10/14/2014 – 05/13/2015
 - Built by Hyundai Motor Manufacturing Alabama ("HMMA")
- 2016MY Elantra (MD) produced 04/21/2015 – 08/21/2015
 - Built by Hyundai Motor Company ("HMC")
- 2016MY Elantra GT (GD) produced 04/18/2015 - 08/24/2015
 - Built by Hyundai Motor Company ("HMC")

C. Campaign Document(s):

1. Dealer Notification

- a. Available on HyundaiDealerUSA.com > Service > HMA Tech Info > Service News

D. Action Required:

1. The remedy is currently in development. An update will be provided once additional information is available.
2. **NOTE:** HMA recommends that impacted customers be provided with a Service Rental Car until a remedy for this recall becomes available. If an SRC is unavailable, alternative transportation options—such as a third-party rental or rideshare—may be provided.

We appreciate your continued partnership and commitment to our Hyundai customers.

Thank you for your patience and understanding.

Warranty Campaign Team

Hyundai Motor America