

- [26-01-047H - HPCU Software Update \(Recall 301\).\(posted on 05.15.26\).pdf](#)
- [Recall 301 - HPCU Update - Dealer Notification \(Remedy Available\).\(posted 05.15.26\).pdf](#)

**Hyundai Motor America (HMA) has launched Remedy Available for Recall 301: Hybrid Power Control Unit (HPCU).**

**A "stop sale" has been issued on affected new vehicles in dealer's inventory. As required by federal law, dealers must not deliver new vehicles for sale or for lease to customers until all open recalls have been performed. Dealers must perform all open recalls on used vehicles, demo, and rental vehicles prior to placing them into customer use and whenever an affected vehicle is in the shop for any maintenance or repair.**

**A. Recall Description:**

Certain Elantra Hybrid (CN7 HEV) vehicles may have a Hybrid Power Control Unit (HPCU) that may overheat under high electrical loads. In most cases, a "no start" condition or reduced power "Limp Mode" with the malfunction indicator lamp (MIL) illuminated may occur while driving. In limited cases, the HPCU may overheat, resulting in localized thermal damage to the HPCU assembly and internal components. Overheating of the HPCU could increase the risk of a fire.

**Technical Service Bulletin (TSB) 26-01-047H** provides a service procedure to update the HPCU software.

**B. Affected Vehicles:**

- **VIN Identification:** Use the 'Vehicle Information' screen in WebDCS under the 'Campaign Not Performed' section to determine recall applicability.

- 2024-26MY Elantra Hybrid (CN7 HEV) produced 10/31/2023 – 12/31/2025
- Built by Hyundai Motor Company ("HMC")

**C. New Stock Vehicles at Dealers:**

- 1,993 – Divide by region as noted below – 1,992 currently at dealers & 1 vehicle in-transit.

Recall 301 Dealer Stock	
Region	ELANTRA HYBRID
CE	332
EA	302
MA	303
MS	192
SC	343
SO	241
WE	280
<b>Total</b>	<b>1993</b>

**D. Parts Information:**

**1. Hyundai Emissions Label**

- a. Order through normal WebDCS process.
- b. Please note this applies to all vehicles.

**2. Vehicle Emission Proof of Correction Card**

- a. Order through normal WebDCS process.
- b. Please note this card only applies to certain states. See TSB for details.

**E. Campaign Document(s):**

**1. TSB 26-01-047H**

- a. Available on HyundaiDealerUSA.com > Service > HMA Tech Info > Campaign

**2. Dealer Notification**

- a. Available on HyundaiDealerUSA.com > Service > HMA Tech Info > Service News

**F. Action Required:**

1. Confirm VIN eligibility via WebDCS. Review if any vehicles are currently at dealer's location in dealer stock. Do not sell any vehicles identified with an open recall until remedy has been applied.
2. **Follow the TSB** for the service procedure to update the HPCU software.
3. **Submit campaign claim** once the service procedure is completed.

We appreciate your continued partnership and commitment to our Hyundai customers.

Thank you for your patience and understanding.

Warranty Campaign Team

Hyundai Motor America