

Subarunet Announcement

To: All Subaru Retailers

From: Subaru of America, Inc.

Date: May 28, 2026

New Safety Recall and Stop Sale: WRF-26 Forester Power Moonroof Glass Adhesion

Subaru of America, Inc. (Subaru) has initiated a safety recall for certain 2026 model year Forester vehicles equipped with a power moonroof assembly.

Description of the Defect and Safety Risk

The affected vehicles may have been manufactured with power moonroof assemblies in which the glass panel has been improperly bonded to the sliding frame. Over time, the bonding adhesion between the glass panel and the sliding frame may deteriorate and the moonroof glass may become detached during usage of the vehicle.

If the glass panel were to separate from the vehicle, a displaced panel could increase the risk of a potential crash or injury for other road users.

Remedy

For all potentially affected vehicles, Subaru dealers will inspect the power moonroof glass panel for proper adhesion and, if necessary, replace the glass panel assembly at no cost to the customer.

Affected Vehicles

A total of 69,663 U.S. vehicles will be affected by this recall, as listed below.

Model Year	Carline	Production Date Range
2026	Forester	June 19, 2025 – March 17, 2026

Not all vehicles in the production range listed are affected by this recall. Coverage must be confirmed by using the Vehicle Coverage Inquiry function on subarunet.com prior to repair.

Retailer Responsibility

Please be advised that it is a violation of Federal law for a dealer to deliver a new motor vehicle covered by a recall under a sale or lease until the defect is remedied. Therefore, any Authorized Subaru Retailer failing to perform the applicable service procedures to correct all affected vehicles in their inventory prior to the vehicle being placed in service may be subject to civil penalties of up to \$27,874 per violation (i.e., for each vehicle), as provided in 49 CFR §578.6 and will also be in breach of the Subaru Dealer Agreement.

Any vehicles listed in any recall/campaign that are in retailer stock must be:

- Immediately identified
- Tagged or otherwise marked to prevent their delivery or use prior to repair
- Repaired in accordance with the repair procedures outlined in the Product Campaign Bulletin

Retailers are to promptly perform the applicable service procedures, to correct all affected vehicles in their inventory (used, demo & SSLP). Whenever a vehicle subject to this recall is taken into retailer inventory necessary steps should be taken to ensure the recall correction has been made before selling or releasing the vehicle.

Service, Parts, and Claim Instructions

For detailed service and claim instructions, please refer to the WRF-26 Product Campaign Bulletin which will be available today on STIS.

Owner Notification

Subaru will notify affected vehicle owners by first class mail within 60 days. Retailers will be advised when owner notification is scheduled.