



Retailer Notification

Safety Recall 034G: Ignition Coil Ground Bolt Retightening (Remedy Available)

August 27, 2026

Document Topic	Date
• Technical Service Bulletin (TSB) 26-01-066G-1 published on GMA Tech Info; • TSB Supersession: Adding Emissions Labels & Proof of Correction Card under the Parts Information Section • This Retailer Notification document (see yellow highlights) • Other Key Notes & Parts Information (page 2) • Warranty Information (page 3) • Q8 & A8 (page 5)	08/27/2026



IMPORTANT: As required by federal law, retailers must not deliver new vehicles for sale or for lease to guests until all open recalls have been performed. Retailers must also perform all open recalls on used vehicles, demo, and rental vehicles prior to placing them into guest use and whenever an affected vehicle is in the shop for any maintenance or repair.

To check vehicle specific recall applicability, access the “Vehicle Information” screen via WebDCS.

Recall Description

Certain 2027MY G80 (RG3) vehicles may have an ignition coil ground bolt (GC101) that was not sufficiently tightened during vehicle assembly. A loose ground bolt could cause an engine misfire with illumination of multiple warning light(s), or in limited instances, an engine stall.

Applicable Vehicles (Certain)

- 2027MY G80 (RG3) equipped with 2.5T engines produced 06/02/2026 – 06/05/2026
 - Built by Hyundai Motor Company (“HMC”) – VIN prefix “KMT”

Remedy Information

Follow the service procedure outlined in **TSB 26-01-066G-1** to retighten the GC101 ground bolt. Some steps will require a technician and a second helper; these are clearly marked in the TSB where applicable.

- **Recommended Service Technician Level and/or Requirements:** Genesis Specialist (or above)

Recommended Alternative Transportation:

A Service Valet or CVP 4.0 vehicle may be required based on the repair procedure duration/wait and any other additional work on the vehicle that may need to be addressed during the guest’s visit.

- ❖ A Courtesy Vehicle Program (CVP) 4.0 vehicle or Service Valet is expected to be provided to guests.
 - a. Please note that Service Valet is available to the original/subsequent owner for 3 years/36,000 miles ONLY.
A CVP 4.0 Vehicle can be offered with the opportunity for Daily Reimbursement (Please refer to



CVP 4.0 Warranty/Campaign Rental Guidelines).

Other Key Notes

- **Every vehicle must have an emission sticker installed under the hood once repairs are completed.**
- **A Proof of Correction card must also be provided to affected guests in applicable states. Please refer to the TSB for the list of required states.**
- All vehicles will require torquing of the bolt.
- If an owner arrives at the retailer without an appointment, it is recommended that the retailer offer alternative transportation, if possible.

Parts Information

- Please refer to **TSB 26-01-066G-1** (or latest version) for the latest parts information.
- **Genesis Emissions Label (P/N NP001-GENEM)** – Retailer may order from its facing PDC.
- **Vehicle Emission – Proof of Correction Card (NP050-09006):** Retailers from certain states referred to in the 'Remarks' section are required to provide a card to guests as proof the vehicle has completed the campaign.

Model	Part Name	Part Number	Figure	Remarks
G80 (RG3)	Emissions Label	NP001-GENEM		Apply to all vehicles regardless of state.
	Vehicle Emission Recall - Proof of Correction Card	NP050-09006		Order only for states: CA, CO, CT, DE, ME, MD, MA, MN, NJ, NV, NY, OR, PA, RI, VA, VT, WA

Required Equipment/Supplies

- Refer to **TSB 26-01-066G-1** for the latest information regarding necessary tools/supplies.

Name	Figure	Remarks
Prybar		Used to move the transmission to create more workspace
1/4-Inch Drive Torque Wrench		Used to retighten the ignition coil ground bolt
10 millimeter Deep Socket		Approximately 50 millimeters or 2 inches is the required length of the socket
Flashlight		Used to locate the ignition coil ground bolt
Transmission Support Jack		Used to secure the transmission prior to retightening the coil ground bolt



Warranty Information

Per **TSB 26-01-066G-1** (or latest version), this service procedure includes:

- 0.9 M/H for ignition coil ground bolt retightening & emissions sticker application
 - NOTE: Emission sticker only required for retailed vehicles (non-dealer stock)
- **Digital Documentation:**
 - This TSB includes repair validation photos. Op times include VIN, mileage, and repair validation photo(s) as outlined in the Digital Documentation Policy. Please ensure: 1) a picture of the torque wrench with the torque set to the proper specification, 2) a picture of the technician applying the final torque, and 3) a picture of the emissions label attached under the hood is attached.

Guest Talk Tracks:

1. For Guests on the phone:

*"I reviewed your vehicle for any open campaigns or recalls and found that there is an open recall for which a remedy is available. This recall involves the ignition coil ground bolt which might not have been sufficiently tightened during vehicle assembly. An unsecured ground bolt could cause an engine misfire with illumination of multiple warning lights, or in limited instance, an engine stall. A vehicle stall while driving may increase the risk of a crash. This service, of course, will be provided **at no cost to you**. Alternative transportation can also be arranged for you while the service is completed. Please let me know if I can assist you scheduling an appointment for this recall to be completed."*

2. For Guests at a retailer in the service lane:

*"During your visit today, I reviewed your vehicle for any open campaigns or recalls and found there is an open recall for which a remedy is available. This recall involves the ignition coil ground bolt which might not have been sufficiently tightened during vehicle assembly. An unsecured ground bolt could cause an engine misfire with illumination of multiple warning lights, or in limited instance, an engine stall. This service, of course, will be provided **at no cost to you**. Alternative transportation can also be arranged for you while the service is completed. Please let me know if I can assist with getting this recall completed on your vehicle recall."*

3. Guest concern with performance of vehicle:

"If you experience any concern(s) related to the performance of your vehicle or the Malfunction Indicator Lamp (MIL) appears, reach out to your nearest Genesis retailer for assistance. If you do not feel comfortable operating your vehicle until the remedy is completed, we can offer alternative transportation."

Best Practice Checklist:

- **Reservation:** Has WebDCS been referenced for additional open campaigns or recalls?
 - ☐ Yes
 - ☐ **No** – Please ensure all open campaign(s)/recall(s) are identified and addressed.
- **Readiness:** Are all parts, tools, and equipment on-hand (as necessary) and ready to perform the repair procedure?
 - ☐ Yes
 - ☐ **No** – Please ensure the necessary parts, tools, and equipment are on-hand before any repair work.
- **Reception:** Has the guest provided their authorization to perform repairs?
 - ☐ Yes
 - ☐ **No** – Guest must be consulted and provide approval before proceeding with any repairs on their vehicle.
 - Has the guest been informed of the expected repair duration and a timeframe for status updates?



- ☐ Yes
- ☐ **No** – Guest is to be informed of estimated repair duration and pick-up times after repairs are completed.
- Has the guest been offered alternative transportation?
 - ☐ Yes
 - ☐ **No** - If guests do not feel comfortable operating their vehicle until the remedy is completed, alternative transportation should be offered. Guests should also be offered alternative transportation if their vehicle needs to be kept overnight. In addition, a CVP may be required based on the repair procedure duration and any other additional work on the vehicle that may need to be addressed during the visit.
- **Repair:** Does the Technician meet the recommended training requirements to complete this campaign?
 - ☐ Yes
 - ☐ **No** – Please reference the “Remedy Information” section on page 1 and ensure a qualified technician performs the service procedure.
- **Return:** Ensure the guest’s contact information is up-to-date for follow-up conversations regarding their vehicle’s status.
 - ☐ Yes
 - ☐ **No** – Please ensure the guest’s latest information is accurately recorded in order to provide future updates.

Anticipated FAQs:

Q1: What is the issue?

A1: The ignition coil ground bolt used in the subject vehicles might not have been sufficiently tightened during vehicle assembly. An unsecured ground bolt could cause an engine misfire with illumination of multiple warning lights, or in limited instances, an engine stall.

Q2: What are the affected vehicles?

A2: Affected vehicles include certain 2027MY G80 (RG3) equipped with 2.5T engines produced 06/02/2026 – 06/05/2026

Q3: What is the safety concern?

A3: A vehicle stall while driving may increase the risk of a crash.

Q4: Have there been any accidents or injuries?

A4: As of the date of the decision to conduct this recall (07/29/26), there are no confirmed incidents, crashes, fires, or injuries alleging this condition involving the subject vehicles in the U.S. market.

Q5: Will a Retailer Stop Sale or Port Hold be issued?

A5: Retailer: A Retailer “stop sale” has been issued in accordance with federal regulation for involved vehicles unsold at retailers.

Port: A “Port Hold” has been issued for all involved vehicles located at ports and vehicle processing centers.

Q6: What will be done during the recall service at the retailer?

A6: All owners of the subject vehicles will be notified via first class mail with instructions to bring their vehicles to a Genesis retailer, where technicians will tighten the ignition coil ground bolt securing the wire harness ground. This remedy will be offered at no cost to owners for all affected vehicles, regardless of whether the



affected vehicles are still covered under Genesis New Vehicle Limited Warranty. Additionally, Genesis will provide owners of affected vehicles reimbursement for out-of-pocket expenses incurred to obtain a remedy for the recall condition in accordance with the reimbursement plan submitted to NHTSA on March 2, 2026.

Q7: When will owners be notified?

A7: Owners are planned to be notified via First Class Mail no later than September 27, 2026.

Q8: If a vehicle is registered in California, Colorado, Connecticut, Delaware, Maine, Maryland, Massachusetts, Minnesota, New Jersey, Nevada, New York, Oregon, Pennsylvania, Rhode Island, Vermont, Virginia or Washington, what is additionally required?

A8: Due to those states adopting California emissions regulations, Genesis retailers will provide guests with a "Proof of Correction" certificate as verification that this repair has been completed. It is critical that this remains with the vehicle's records and is presented when registering, if requested.

Contact Reference:

Please see the following page for commonly referred to contacts. Thank you for your prompt attention to this important safety matter and continued commitment to our Genesis guests.



Key Contact Information		
Retailer Support	Contact Information	Description
Parts	1-844-436-6455 www.GenesisDealerUSA.com Parts > Mobis Parts Portal	Parts ordering hotline for retailers
Genesis Special Service Tools (SSTs) Support	GenesisTools@gma.com	Questions or feedback on SSTs
Special Service Tools Ordering	1-855-763-6630 GenesisTools@snapon.com	Ordering tools/equipment
Techline	1-800-325-6604	Vehicle Technical Support for Genesis
Warranty HELPLine	1-877-446-2922 warranty@gma.com	Warranty Claim questions for Genesis Retailers
Warranty Prior Approval (PA) Center	1-844-371-3808 pa@gma.com	Warranty Prior Approval (PA) Center for Genesis Retailers
Service Lane Technology (SLT) Xtime / AutoLoop / CDK	Support@xtime.com / 1-866-984-6355 support@autoloop.com / 1-877-850-2010	Assistance with SLT Appointment: • Appointment / Shop Capacity Management / Campaign Integration / OperationCodes
Customer Support	Contact Information	Description
Genesis Customer Care	1-844-340-9741 customer care@genesis motorsusa.com	For Genesis Customer Care, Connected Services and Roadside Assistance
Genesis Recall / Campaign Website	www.genesis.com/us/recall	Updated information for customers related to recall and service campaigns
Genesis Roadside Assistance	1-844-340-9742	Genesis Roadside Assistance
Key Reference Information		
Name	Source	
Service Valet Appointment Scheduling	www.GenesisdealerUSA.com > Resources > Document Library > Services > Service Valet > Xtime Service Valet Settings Guide	
Car Care Scheduling (Xtime) - Recall Appointment Notification	1. Log into Xtime 2. Under the menu at the top left, select 'CONFIGURE' 3. Under the dealership tab, click "EMAIL COMMUNICATION" 4. Slide the toggle to "ADVANCED" 5. Populate as many e-mails as desired in the "PARTS DESK"	
Parts – Campaign Parts Management (CPM) Procedure	As applicable; www.GenesisdealerUSA.com > Resources > Documents Library > Parts > Campaign Parts Management	
Courtesy Vehicle (CVP) Program	www.GenesisdealerUSA.com > Service tab > CVP Fleet Management	
Technical Service Bulletin (TSB)	www.GenesisdealerUSA.com > Service tab > Tech Info	
Uncompleted Campaign VIN Listing	A listing of vehicles is located on WEBDCS > SERVICE tab > select UNCOMPLETED CAMPAIGN VIN LISTING – Dealer Stock (New, SRC, CPO, etc.) and Retailed.	
Recall / Campaign Website	www.genesis.com/us/recall	
NHTSA Website	www.safercar.gov	



Appendix

Document Topic	Date
• Technical Service Bulletin (TSB) 26-01-066G-1 published on GMA Tech Info; • TSB Supersession: Adding Emissions Labels & Proof of Correction Card under the Parts Information Section • This Retailer Notification document (see yellow highlights) • Other Key Notes & Parts Information (page 2) • Warranty Information (page 3) • Q8 & A8 (page 5)	08/27/2026
• Technical Service Bulletin (TSB) 26-01-066G published on GMA Tech Info	07/31/2026
• Remedy Not Available	07/30/2026