

Stop Sale Important - Re-launching Recall Campaign 034G: Ignition Coil Ground Bolt - Remedy Available (Revision)

Posted Date:
08/27/2026

-  26-01-066G-1 - Ignition Coil Ground Bolt Retightening (Recall 034G) (posted 08.27.26).pdf
-  Recall 034G - Ignition Coil Bolt - Retailer Notification (Remedy Available) (posted 08.27.26).pdf

Genesis Motor America (GMA) has re-launched Remedy Available for Recall 034G: Ignition Coil Ground Bolt Retightening.

A “stop sale” has been issued on affected new vehicles in retailer's inventory. As required by federal law, retailers must not deliver new vehicles for sale or for lease to customers until all open recalls have been performed. Retailer must perform all open recalls on used vehicles, demo, and rental vehicles prior to placing them into guest use and whenever an affected vehicle is in the shop for any maintenance or repair.

Revisions to Technical Service Bulletin (TSB):

1. **Add Parts Information table reflecting emissions labels & proof of correction card (page 2)**
2. **Updated service procedure applying emissions labels & proof of correction cards (pages 11 & 12)**

A. Recall Description:

Certain 2027MY G80 (RG3) vehicles may have an ignition coil ground bolt (GC101) that was not sufficiently tightened during vehicle assembly. A loose ground bolt could cause an engine misfire with illumination of multiple warning light(s), or in limited instances, an engine stall.

Technical Service Bulletin (TSB) 26-01-066G-1 provides instructions to retighten the GC101 ground bolt.

-

B. Affected Vehicles:

1. **VIN Identification:** Use the 'Vehicle Information' screen in WebDCS under the 'Campaign Not Performed' section to determine recall applicability.
 - a. Certain 2027MY G80 (RG3) produced 06/02/2026 – 06/05/2026
 1. Built by Hyundai Motor Company (“HMC”)

C. Uncompleted New Stock Vehicles at Retailers - Impacted by Recall 034G Stop Sale

- 15 – Divide by region as noted below – 14 currently at retailers; 1 en-route.

Recall 034G Dealer Stock	
Region	G80 (RG3)
CE	2
EA	3
MA	0
MS	2

SC	3
SO	0
WE	5
Total	15

E. Campaign Documents:

1. **TSB 26-01-066G-1; supersedes 26-01-066G**

1. GenesisDealerUSA.com > Service > Service Resources > Tech Info > Campaign

2. **Retailer Notification; supersedes existing document**

1. GenesisDealerUSA.com > Service > Service Resources > Tech Info > Service News

F. Action Required:

1. Confirm VIN eligibility via WebDCS. Review if any vehicles are currently at retailer's location in stock. Do not sell any vehicles identified with an open recall until the remedy has been applied.
2. **Follow TSB 26-01-066G-1** for the service procedure to retighten the designated ground bolt and apply the emissions label. Provide customer proof of correction card as well, if necessary based on the states listed in the TSB.
3. **Submit campaign claim** once the service procedure is completed.

We appreciate your continued partnership and commitment to our Genesis guests.

Thank you for your patience and understanding.

GMA Warranty Campaigns