

Stop Sale Important - Recall Campaign 034G: Ignition Coil Ground Bolt - Posted Date: Remedy Available

07/31/2026

- 📎 26-01-066G - Ignition Coil Ground Bolt Retightening (Recall 034G) (posted 07.31.26).pdf
- 📎 Recall 034G - Ignition Coil Ground Bolt - Retailer Notification (Remedy Available) (posted 07.31.26).pdf

Genesis Motor America (GMA) has launched Remedy Available for Recall 034G: Ignition Coil Ground Bolt Retightening.

A “stop sale” has been issued on affected new vehicles in retailer's inventory. As required by federal law, retailers must not deliver new vehicles for sale or for lease to customers until all open recalls have been performed. Retailer must perform all open recalls on used vehicles, demo, and rental vehicles prior to placing them into guest use and whenever an affected vehicle is in the shop for any maintenance or repair.

A. Affected Vehicles:

1. **VIN Identification:** Use the 'Vehicle Information' screen in WebDCS under the 'Campaign Not Performed' section to determine recall applicability.
 - a. Certain 2027MY G80 (RG3) produced 06/02/2026 – 06/05/2026
 1. Built by Hyundai Motor Company (“HMC”)

B. New Stock Vehicles at Retailers - Impacted by Recall 034G Stop Sale

- 35 – Divide by region as noted below – 29 currently at retailers; 6 en-route.

Recall 306 Retailer Stock	
Region	G80 (RG3)
CE	10
EA	5
MA	0
MS	5
SC	6
SO	0
WE	9
Total	35

C. Recall Description:

Certain 2027MY G80 (RG3) vehicles may have an ignition coil ground bolt (GC101) that was not sufficiently tightened during vehicle assembly. A loose ground bolt could cause an engine misfire with illumination of multiple warning light(s), or in limited instances, an engine stall.

Technical Service Bulletin (TSB) 26-01-066G provides instructions to retighten the GC101 ground bolt.

D. Campaign Document:

1. **TSB 26-01-066G**
 1. GenesisDealerUSA.com > Service > Service Resources > Tech Info > Campaign
2. **Retailer Notification**
 1. GenesisDealerUSA.com > Service > Service Resources > Tech Info > Service News

E. Action Required:

1. Confirm VIN eligibility via WebDCS. Review if any vehicles are currently at retailer's location in stock. Do not sell any vehicles identified with an open recall until the remedy has been applied.
2. **Follow TSB 26-01-066G** for the service procedure to retighten the designated ground bolt.
3. **Submit campaign claim** once the service procedure is completed.

We appreciate your continued partnership and commitment to our Genesis guests.

Thank you for your patience and understanding.



A black background with a black square Description automatically generated with medium confidence

GMA Warranty Campaigns