

**SAFETY RELATED RECALL**Global Recall Action
Number: D113v2

Changes are highlighted in blue

Subject: Defender 110 Third Row Seatbelt Mounting Bracket - Incorrect Specification	Publication No.: D113v2
	Model: Defender (LE)
	Model Year: 2026
	Date of Issue: 12 May 2026

To:	All National Sales Companies (NSCs), importers, retailers and authorized repairers.
For the Attention of:	The approved JLR retailer / authorized repairer.
Important:	Rest of World: Quarantine in JLR retailer / authorized repairer or applicable NSC location. NOTE: The information in this campaign is intended for use by professional technicians. If you are not a JLR retailer / authorized repairer, do not assume that a condition described affects a specific vehicle. Contact an authorized JLR retailer / authorized repairer to determine if this campaign applies to a specific vehicle. This bulletin supersedes Update Prior to Sale (UPS) UPS0926 with immediate effect. The blue highlighted text relates only to the date information. All text in this bulletin should be read and understood in full. The D113 Safety Recall has been updated to amend the Service Instructions.

FOR THE ATTENTION OF ALL:**DESCRIPTION OF ISSUE AND THE EFFECT ON VEHICLE OPERATION**

A concern has been identified on certain 2026 model year Defender vehicles, where the third-row lower seatbelt anchorage bracket may contain a weld stud of insufficient International Organization for Standardization (ISO) strength, due to material contamination at the supplier.

An insufficiently strong weld stud in this position could result in the safety restraint system not functioning correctly in the event of a crash, increasing the risk of occupant injury.

JLR advise not to use the third-row seats until the repair has been completed.

ACTION TO BE TAKEN

JLR has taken the decision to recall affected vehicles to repair the vehicle.

Following procedures appropriate to your market and as required by local legislation, owners of affected vehicles must be contacted requesting that the owner contact their nearest JLR retailer / authorized repairer as soon as possible to arrange for the repair to be completed. The National Sales Company (NSC), Importer, Regional Office or Government agency will contact the customers. If you have any questions about this process, contact your NSC / Importer or Regional Office for more information.

Check the JLR Warranty Portal to make sure affected vehicles are correctly identified prior to starting this campaign. The Warranty Portal will be updated to reflect only those vehicles affected.

JLR retailers / authorized repairers are reminded that they must not sell vehicles identified as affected by this campaign until such time as the repair has been successfully completed.

An owner may indicate that a repair has already been completed for this concern, in which case the full cost of the repair should be reimbursed. Refer to the warranty section of this campaign for details of the Customer Reimbursement and Related Damage Process. At the time of confirming a booking for a vehicle repair, make sure you check the Warranty Portal to confirm if there are any other outstanding campaigns, to make sure the correct parts are available and adequate workshop time is allocated for repairs to be completed in one visit.

For information purposes, a Technical Question and Answer document is attached.

FOR THE ATTENTION OF NORTH AMERICAN TERRITORIES ONLY:

National Highway Traffic Safety Administration (NHTSA) reference number: 26V-163

Transport Canada (TC) reference number: 2026-126

Visit the British Brands Sales Suite (BBSS) website for a list of affected vehicles at your JLR retailer / authorized repairer. Unsold vehicles must be repaired prior to handover of the vehicle for retail sale.



The following applies to:
[NORTH AMERICA]

REGULATORY INFORMATION



The following applies to:
[NORTH AMERICA]

Jaguar Land Rover North America, LLC and Jaguar Land Rover Canada ULC have informed the National Highway Traffic Safety Administration (NHTSA) and Transport Canada (TC) of their intent to perform a Safety Recall on certain 2026 model year Defender vehicles imported into the United States and Canadian markets. Information relating to this Safety Recall will be posted on the NHTSA and TC websites. United States Federal regulations require that JLR retailers / authorized repairers must be notified within a reasonable time after the manufacturer decides that a defect that relates to motor vehicle safety or a non-compliance exists. United States Federal Law requires JLR retailers / authorized repairers to complete any outstanding Safety Recall before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a JLR retailer / authorized repairer, in the USA only, could

result in a maximum civil penalty of up to the equivalent of \$27,874.00 USD per violation and the equivalent of \$139,356,994.00 USD for a related series of violations. This Safety Recall serves as notification to all JLR retailers / authorized repairers in the United States and Federalized Territories and Canada that any affected new vehicles may not be sold and delivered for customer use until the Safety Recall repair is completed.



The following applies to:
[NORTH AMERICA]

Jaguar Land Rover North America, LLC and Jaguar Land Rover Canada ULC recommends that affected sales demonstrator and loaner vehicles are repaired before use, and that used vehicles are repaired before sale. JLR retailers / authorized repairers who proceed against this recommendation, where legally permitted, must clearly and conspicuously disclose the open Safety Recall notice to the applicable customers.

Yours faithfully

Steve Oldham

Global Customer Care Quality Director

SERVICE INSTRUCTION - D113V2

Changes are highlighted in blue

Parts Information

The parts below must be ordered through JLR in the normal manner.

Description	Part Number	Qty
Bolt	LR074133	2
Foam Noise, Vibration and Harshness (NVH) pad	LR079995	1
Third row seatbelt anchor bracket - Right	522123473	1
Third row seatbelt anchor bracket - Left	522123474	1
Anti-abrasive tape	*ZZZ999	£1

NOTE:

*An allowance equivalent to £1.00 Sterling has been allocated to locally source anti-abrasion tape.

Service Repair Operation (SRO)

Description	SRO	Time
Third row seatbelt anchor bracket - Renew - Pair	05.11.15	1.5
Drive in / drive out	02.02.02	0.2

NOTE:

Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.

Warranty Information

Warranty claims must be submitted quoting program code D113v2 with the relevant option code from the table below. As option codes are used there is no requirement for you to enter [SROs](#) or parts, these are included for information only.

Program	Option	Description	SRO	Time	Part Number / Sundry	Quantity / Cost (£)
D113	C	Third row seatbelt anchor bracket - Renew - Pair	05.11.15	1.5	LR074133 LR079995 522123473	2 1 1

Program	Option	Description		Time	Part Number / Sundry	Quantity / Cost (£)
					522123474 *ZZZ999	1 £1
D113	D	Third row seatbelt anchor bracket - Renew - Pair Drive in / drive out	05.11.15 02.02.02	1.5 0.2	LR074133 LR079995 522123473 522123474 *ZZZ999	2 1 1 1 £1

NOTE:

The option that contains the drive in / drive out allowance may only be claimed when the vehicle has been brought back into the workshop for this action alone to be undertaken.

Warranty claims must be submitted in accordance with the current JLR Global Warranty Manual, and its amendments, unless stated otherwise in this campaign.

Customer Reimbursement and Related Damage Process**NOTE:**

If there is a requirement to claim for related / consequential damage or customer reimbursement, refer to the related instruction that can be found in TOPlx (in the Search box, search for 'Related Damage Claim' and open the related bulletin link).

Table of Contents
[REMOVAL AND INSTALLATION: SERVICE INFORMATION](#)
[REMOVAL AND INSTALLATION: SERVICE INSTRUCTION](#)
SERVICE INFORMATION

SERVICE INSTRUCTION

1. Part numbers 522123473 and 522123474 **MUST** have the sticker stating '**Campaign Use Only**' as shown in the illustration.



SERVICE INSTRUCTION

1. Remove the third row seat (see TOPlx Workshop Manual section 501-10C: Seating - Third Row Seats - Removal and Installation - Third Row Seat - 110).

SERVICE INSTRUCTION

2.

NOTE:

The left loadspace trim is removed for access only.

Remove the left loadspace trim panel (see TOPlx Workshop Manual section 501-05: Interior Trim and Ornamentation - Removal and Installation - Left Loadspace Trim - 110, Vehicles With: Third Row Seats).

3.


NOTE:

The right loadspace trim is removed for access only.


Remove the right loadspace trim panel (see TOPlx Workshop Manual section 501-05: Interior Trim and Ornamentation - Removal and Installation - Right Loadspace Trim - 110, Vehicles With: Third Row Seats).

4. Remove the left side and right side third row seatbelt anchor nuts.

- Move both third row seatbelt anchors to one side.




E410575



5. Remove the left side third row seatbelt anchor bracket.


- Remove the 4 nuts.
- Remove the bolt.
- Discard the third row seatbelt anchor bracket.



E410578

6. Remove the right side third row seatbelt anchor bracket.

- Remove the 4 nuts.
- Remove the bolt.
- Discard the third row seatbelt anchor bracket.



7.

NOTES:

- The new bolt must be inserted from the rear of new third row seatbelt anchor bracket.
- Repeat this step for both new third row seatbelt anchor brackets.
- The head of the new bolt **MUST** be flush against the matting surface.

Insert the new bolt through the hole in the new third row seatbelt anchor bracket as shown in the illustration.




8.

NOTE:

Do not fully tighten the fixings at this stage.


Install the **new** left side and right side third row seatbelt anchor brackets.

- Install the 8 nuts.
- Install the 2 bolts.





9. Tighten the 6 nuts as shown in the illustration.

- Torque: **45Nm**



10. Tighten the 2 nuts and 2 bolts as shown in the illustration.

- Tighten the nuts.
 - Torque: **10Nm**
- Tighten the bolts.
 - Torque: **48Nm**



11. Install the left side and right side third row seatbelt anchors.

- Reposition the third row seatbelt anchor over the new bolt.
- Install the nut.

NOTE:

The head of the bolt must be flat against the rear surface of the bracket when torqued.

Hold the bolt using a suitable spanner and torque the nut.

- Torque: **40Nm**



12.

CAUTION:

The adhesive foam [NVH](#) pad is required to prevent any contact between the head of the bolt and any components within the surrounding area.

NOTE:

Right third row seatbelt bracket only.

Install the adhesive foam [NVH](#) pad.

- Remove the backing from the adhesive foam [NVH](#) pad.
- Install the adhesive foam [NVH](#) pad onto the air suspension pipe, as shown in the illustration.
- Apply a suitable anti-abrasion tape to the foam [NVH](#) pad.



SERVICE INSTRUCTION

- 13.** Install the right loadspace trim panel (see TOPlx Workshop Manual section 501-05: Interior Trim and Ornamentation - Removal and Installation - Right Loadspace Trim - 110, Vehicles With: Third Row Seats).
- 14.** Install the left loadspace trim panel (see TOPlx Workshop Manual section 501-05: Interior Trim and Ornamentation - Removal and Installation - Left Loadspace Trim - 110, Vehicles With: Third Row Seats).
- 15.** Install the third row seat (see TOPlx Workshop Manual section 501-10C: Seating - Third Row Seats - Removal and Installation - Third Row Seat - 110).

SAMPLE CUSTOMER LETTER - FOR INFORMATION ONLY

Name
Address line 1
Address line 2
Address line 3
Post Code

Vehicle Identification Number (VIN):
Registration Number:
Program Number: D113

Date: month/year

SAFETY RELATED RECALL - Defender - Defender 110 Third Row Seatbelt Mounting Bracket - Incorrect Specification

Dear

JLR would like to advise you that during ongoing quality assessment of our product it has been identified that a possible safety related problem may occur on certain JLR vehicles within a specific production range. Read the information below, explaining the actions that we intend to take and what you are required to do.

Why are we contacting you?

A concern has been identified on certain 2026 model year Defender vehicles, where the third-row lower seatbelt anchorage bracket may contain a weld stud of insufficient International Organization for Standardization (ISO) strength, due to material contamination at the supplier.

An insufficiently strong weld stud in this position could result in the safety restraint system not functioning correctly in the event of a crash, increasing the risk of occupant injury.

JLR advise not to use the third-row seats until the repair has been completed.

What will your JLR retailer / authorized repairer do?

At your visit, your preferred JLR retailer / authorized repairer will have the third-row lower seatbelt anchorage bracket replaced, or the weld-stud on the bracket replaced with an equivalent standalone bolt.

How long will it take?

The work on your vehicle will be completed as quickly and efficiently as possible in order to minimize inconvenience to you. Your JLR retailer / authorized repairer will be able to advise how long your vehicle will be required for when a booking is made.

What we are asking you to do

Contact your preferred JLR retailer / authorized repairer without delay. To book your vehicle in for this action, you must provide your JLR retailer / authorized repairer with the following details, which are at the beginning of this letter:

- The VIN for your vehicle
- Vehicle registration number of your vehicle.

- The Program Number for the action.

If you do not have a JLR retailer / authorized repairer, access, www.landrover.co.uk or www.landrover.com for contact details.

If you no longer own the vehicle, could you complete the 'Change of Ownership' slip attached to this letter, returning the slip to JLR immediately in the enclosed Freepost envelope. This will enable us to make contact and share this information with the new owner.

If you have concerns

If you experience any concerns relating to this Recall, contact the Service Manager at the JLR retailer / authorized repairer for assistance or contact the JLR Customer Experience Center on 0345 303 2303 or (enter phone number).

This bulletin is being issued in accordance with the legislative or industry requirements concerning vehicle defects. The authorities will closely monitor the response rate of this bulletin.

Treat this matter with the urgency it requires, JLR apologize for any inconvenience this bulletin may cause and thank you, in advance, for your co-operation.

Yours sincerely

Head of Business

Technical Questions And Answers	
FOR USE ON ENQUIRY	
JLR Recall D113	
Defender 110 Third Row Seatbelt Mounting Bracket - Incorrect Specification	

A concern has been identified on certain Land Rover Defender 7-seat models where the third-row lower seatbelt anchorage bracket may contain a weld stud of insufficient ISO strength due to material contamination at the supplier.

Question 1

Why is JLR recalling certain models?

Answer

JLR is conducting a voluntary safety recall involving certain 2026 MY Land Rover Defender 7-seat vehicles. Customers will be asked to take their vehicles to an approved repairer to have third-row seatbelt anchorage brackets replaced.

Question 2

Can you tell me more about what is wrong with the vehicles?

Answer

Material analysis of the weld studs on the third-row seatbelt anchorage bracket has identified a risk of lower specification material being present. This could increase the risk of injury in the event of a crash.

Question 3

How would the customer become aware of potentially having this concern?

Answer

The issue is invisible to the customer, but in the event of a crash the risk to occupant injury for users of the third-row seats may be increased.

Question 4

Does this concern affect vehicle safety?

Answer

Yes.

Question 5

Has JLR received many complaints?

Answer

JLR has not received any complaints related to this concern.

Question 6

Have there been any accidents, injuries or fires?

Answer

There have been no reported accidents, injuries or fires as a result of this concern.

Question 7

Are there any precautions that can be taken to minimize the risk until the corrective measures are implemented?

Answer

Affected customers will be contacted directly by JLR and are advised to book their vehicles in for repair as soon as possible. Customers are advised to not use the third-row seats until the repair has been completed.

Question 8

How was the concern discovered?

Answer

The concern was identified through JLR's internal reporting process.

Question 9

How long has JLR known about this problem?

Answer

The presence of the potential defect in customer vehicles was known to JLR from March 2026.

Question 10

Is the concern leading you to any concerns regarding the reliability of the vehicle?

Answer

JLR has no concerns with the overall reliability of the vehicle. JLR carefully monitors field data to make sure that any matters relating to safety and compliance are rigorously investigated.

Question 11

What has JLR done in production?

Answer

The supplier quality processes have been improved to make sure material specification is met for the seatbelt anchorage bracket before shipping to JLR.

Question 12

What will JLR retailers / authorized repairers do to the vehicles?

Answer

Vehicles will have the third-row lower seatbelt anchorage bracket replaced, or the weld-stud on the bracket replaced with an equivalent standalone bolt.

There will be no charge to the owners for this permanent repair.

Question 13

Which vehicles are affected by this concern?

Answer

Certain 2026 model year Defender 7-seat vehicles may be affected.

Question 14

Are other JLR models affected by this concern?

Answer

No other JLR models are known to be affected by this concern.

Question 15

Are parts available to rework vehicles?

Answer

Parts are available for JLR retailers / authorized repairers to conduct this repair.

Question 16

How much will the recall cost JLR?

Answer

Cost was not a factor in deciding to recall these vehicles.

Question 17

How do I know if my vehicle is affected?

Answer

All owners of potentially affected vehicles will shortly be contacted and invited to make an appointment with a JLR retailer / authorized repairer for the work to be completed.

In some countries, recall information is available online through the brand's web site.

Customers can use the Recall Search at <https://TOPIx.landrover.jlrext.com/TOPIx/vehicle/lookupForm>

Question 18

How long does it take for the vehicle to be inspected and repaired?

Answer

The work will be completed out as quickly and efficiently as possible in order to minimize inconvenience to customers and is expected to take no longer than 2 hours 30 minutes to complete. Naturally, due to JLR retailer / authorized repairer schedules, vehicles may be required for longer.

Note:

Press enquiries must be referred to the JLR Corporate Media office on +44-(0)2475-361000 or jlrmmedia@jaguarlandrover.com