



## Repair Procedure

1. Verify that the vehicle is included in Recall 0193. Refer to Vehicle Recall Verification.
2. Verify that the vehicle is equipped with the Original Equipment (OE) Airbox Assembly (Part No. 29000373).
  - a. If the vehicle has been equipped with a Parts and Accessories (P&A) or aftermarket air cleaner, file the appropriate claim for Inspection Only per Credit Procedure. Refer to Credit Procedure.
3. Remove outer cover of air cleaner.
4. Remove breather hose from transmission breather.
5. See Figure 1. Gently apply air to breather hose in the direction of the air cleaner backing plate, using an air gun with a rubber tip with a rubber tip to ensure proper sealing.
  - a. Applying too much air pressure in bursts could push the hose off the backing plate and falsely indicate a blockage.




Figure 1. Breather Hose

6. Verify that air flows through the hose and into air box backing plate.
  - a. Make sure that the hose did not blow off the backing plate when applying air. If the hose does come off, the backing plate could indicate a blockage.
  - b. If no blockage is found, file the appropriate claim for Inspection Only per Credit Procedure. Refer to Credit Procedure.
7. If initial testing indicates the air box **IS NOT** flowing air, see the service manual to remove the air box backing plate.
8. See Figure 2. With the air box removed, apply air to the backing plate directly. A blockage will be indicated by no air flow.




Figure 2. Backing Plate

9. If the air box backing plate port is blocked, rework the breather passage:
  - a. See Figure 2. Using a 3/16-inch drill bit, from the backside of the backing plate, drill the port open.

### NOTE

See Figure 3. Drill bit should only proceed far enough to open the port up from flash blockage (2). Do not drill into the elbow (1) of the backing plate.



**Figure 3. Drilling Breather Port**

- b. Make sure any material from drilling is cleaned and removed from the part.

10. Install backing plate per service manual.

### Dealer Inventory Instructions

1. Locate any dealer inventory of Airbox Assembly (Part No. 29000373).
2. If inventory is located and found to be blocked, file Defective Stock (DFS) for the inventory service part.

### Credit Procedure

**NOTE**

Enter bulletin number into comment section of claim.

For each vehicle involved in this recall (involvement of VIN has been verified on H-Dnet.com ), submit a recall claim per Table 4.

**Table 4. Credit Procedure: Talon/h-dnet.com Warranty Claim System Users-INSPECTION ONLY OR NON-OE PART INSTALLED**

ITEM	DATA
Claim Type	SRC
Problem Part Number	29000373
Quantity	Leave Blank
Primary Labor Code <sup>(1)</sup>	2749
Labor Time	0.1 hours
Customer Concern Code	0193
Condition Code	9981
<i>(1) Download may be required</i>	

**Table 5. Credit Procedure: GDP/SAP System Users-INSPECTION ONLY OR NON-OE PART INSTALLED**

ITEM	DATA
Claim Type	Recall Claim
Fix ID-Found in Recall Number	C
Problem Part Number	29000373
Customer Concern Code	0193
Condition Code	9981

Upon submission of the properly completed claim, you will be credited for 0.1 hours of labor time for performing the procedure, plus appropriate administrative time. Submit campaign events

on their own warranty claim. Do not mix them with other warranty events.

For each vehicle involved in this recall (involvement of VIN has been verified on H-Dnet.com ), submit a recall claim per Table 6.

**Table 6. Credit Procedure: Talon/H-Dnet.com Warranty Claim System Users-REPAIR**

ITEM	DATA
Claim Type	SRC
Problem Part Number	29000373
Quantity	Leave Blank
Primary Labor Code <sup>(1)</sup>	2783
Labor Time	0.2 hours
Customer Concern Code	0193
Condition Code	9982
<i>(1) Download may be required</i>	

**Table 7. Credit Procedure: GDP/SAP System Users-REPAIR**

ITEM	DATA
Claim Type	Recall Claim
Fix ID-Found in Recall Number	R
Problem Part Number	29000373
Customer Concern Code	0193
Condition Code	9982

Upon submission of the properly completed claim, you will be credited for 0.2 hours of labor time for performing the procedure, plus appropriate administrative time. Submit campaign events on their own warranty claim. Do not mix them with other warranty events.

For parts in dealer inventory, submit a claim per Table 8.

**Table 8. Credit Procedure: Kits in Dealer Inventory**

ITEM	DATA
Claim Type	DFS/PAM Stock
Problem Part Number	29000373
Quantity	Could Vary
Customer Concern Code	9203
Condition Code	9109