

SAFETY RECALL

NORTH AMERICA

Incorrect Speed Calibration



Reference: 43D / NHTSA 26V-288

FCA US LLC



RAM

Remedy available for

2023-2026 (DJ) RAM 2500

Template Version 1.0

Revision	Edition	Detail
0	May 2026	Initial Version.

SYMPTOM DESCRIPTION

The vehicle speed calibration on about 16,063 of the above vehicles may exceed the maximum tire speed rating. A vehicle that can exceed the tire speed rating can reduce tire integrity which can result in compromised vehicle control. Compromised control of the vehicle can cause a vehicle crash without prior warning.

SCOPE

This recall applies only to 2023 through 2026 Model Year (DJ) Ram 2500 Rebel and Warlock pickups equipped with a 6.7L diesel engine (sales codes ETL and ETM) and tire sales code TKN. Also 2026 Model Year (DJ) Ram 2500 Warlock pickups equipped with 6.4L gasoline engine (sales code ESL) and tire sales code TKN.

NOTE: Some vehicles above may have been identified as not involved in this recall and therefore have been excluded from this recall.

IMPORTANT:

- Some of the involved vehicles may be in dealer new vehicle inventory. Federal law requires you to complete this recall service on these vehicles before retail delivery. Violation of this requirement by a dealer could result in a civil penalty of up to \$27,874 per vehicle.
- Some of the involved vehicles may be in dealer used vehicle inventory. Dealers should complete this recall service on these vehicles before retail delivery.
- Dealers should also perform this recall on vehicles in for service.

Involved vehicles can be determined by using the VIP inquiry process.

REPAIR TO BE PERFORMED

Reprogram the Powertrain Control Module (PCM) for gas engine vehicles.

Perform the PCM Configuration routine in wiTECH for diesel engine vehicles.

ALTERNATE TRANSPORTATION

Dealers should proactively minimize customer inconvenience while the recall repair is being performed. Reference the Goodwill Alternate Transportation Guidelines warranty bulletin link within Recall Central on DealerCONNECT for options to support the customer while their vehicle is in service.

COMPLETION REPORTING / REIMBURSEMENT

Claims for vehicles that have been serviced must be submitted on the DealerCONNECT Claim Entry Screen located on the Service tab. Claims paid will be used by FCA to record recall service completions and provide dealer payments.

Use the following labor operation numbers and time allowances:

Labor Description	Number	Hrs
Inspect Powertrain Control Module (PCM) Software Level	18-43-D1-81	0.2
Inspect and Reprogram Powertrain Control Module (PCM) Software (Gas Engines Only)	18-43-D1-82	0.3
Perform PCM Configuration Routine (Diesel Engines Only)	18-43-D1-83	0.2

NOTE: See the Warranty Administration Manual, Recall Claim Processing Section, for complete recall claim processing instructions.

SAFETY RECALL

NORTH AMERICA

Incorrect Speed Calibration



Reference: 43D / NHTSA 26V-288

FCA US LLC

For Mobile Service Reimbursement, dealer to include standard dealer entry and mark-up for parts, standard dealer entry and labor rate for service, as well as the special services code for mobile allowance. The special services LOP will only be paid once per VIN and may NOT be used in coordination with any Alternate Transportation claims.

For additional details, reference the Mobile Service Warranty Bulletin - for convenience, a copy has been linked within Recall Central on DealerCONNECT.

PARTS INFORMATION

No parts are required to perform this service procedure.

PARTS RETURN

No parts return required for this campaign.

SPECIAL TOOLS

Number	Description
NPN	wiTECH MicroPod II / MDP
NPN	Laptop Computer
NPN	wiTECH Software

DEALER NOTIFICATION

To view this notification on DealerCONNECT, select "Global Recall System" on the Service tab, then click on the description of this notification.

OWNER NOTIFICATION / SERVICE SCHEDULING

All involved vehicle owners known to FCA are being notified of the service requirement by first class mail. They are requested to schedule appointments for this service with their dealers. A generic copy of the owner letter is attached.

Dealers are encouraged to consider alternative scheduling and servicing approaches for this recall. This repair does not require hoists or other full service facility special equipment and is a Chrysler Mobile Service approved repair.

VEHICLE LISTS, GLOBAL RECALL SYSTEM, VIP AND DEALER FOLLOW UP

All involved vehicles have been entered into the DealerCONNECT Global Recall System (GRS) and Vehicle Information Plus (VIP) for dealer inquiry as needed.

GRS provides involved dealers with an updated VIN list of their incomplete vehicles. The owner's name, address and phone number are listed if known. Completed vehicles are removed from GRS within several days of repair claim submission.

To use this system, click on the "Service" tab and then click on "Global Recall System." Your dealer's VIN list for each recall displayed can be sorted by: those vehicles that were unsold at recall launch, those with a phone number, city, zip code, or VIN sequence.

Dealers must perform this repair on all unsold vehicles before retail delivery. Dealers should also use the VIN list to follow up with all owners to schedule appointments for this repair.

Recall VIN lists may contain confidential, restricted owner name and address information that was obtained from the Department of Motor Vehicles of various states. Use of this information is permitted for this recall only and is strictly prohibited from all other use.

ADDITIONAL INFORMATION

If you have any questions or need assistance in completing this action, please contact your Service and Parts District Manager.

Customer Services / Field Operations
FCA US LLC.

SERVICE PROCEDURE

A. PCM Flash (Gasoline Engines Only)

NOTE: The wiTECH scan tool must be used to perform this recall. If the reprogramming flash for the PCM is aborted or interrupted, repeat the procedure.

1. Open the hood. Install a battery charger and verify that the charging rate provides 13.0 to 13.5 volts. Do not allow the charger to time out during the flash process. Set the battery charger timer (if so equipped) to continuous charge.

NOTE: Use an accurate stand-alone voltmeter. The battery charger volt meter may not be sufficiently accurate. Voltages outside of the specified range will cause an unsuccessful flash. If voltage reading is too high, apply an electrical load by activating the park or headlamps and/or HVAC blower motor to lower the voltage.

2. Connect the wiTECH MDP to the vehicle data link connector.
3. Place the ignition in the **"RUN"** position.
4. Open the wiTECH 2.0 website.
5. Enter your **"User id"** and **"Password"** and your **"Dealer Code"**, then select **"Sign In"** at the bottom of the screen. Click **"Accept"**.
6. From the **"Vehicle Selection"** screen, select the vehicle to be updated.
7. From the **"Action Items"** screen, select the **"Topology"** tab.

NOTE: The PCM must be at the latest software calibration level after completing this recall.

8. From the **"Topology"** tab, select the **"Powertrain Control Module (PCM)"** module icon.
9. From the **"Flash"** tab, compare the **"Current Electronic Control Unit (ECU) Part Number"** with the **"New ECU Part Number"** listed.
 - If the **"Current ECU part Number"** is the same as the **"New Part Number"**, proceed to **Step 15**.
 - If the **"Current ECU part Number"** is NOT the same as the **"New Part Number"**, continue with **Step 10**.

SAFETY RECALL
NORTH AMERICA
Incorrect Speed Calibration



Reference: 43D / NHTSA 26V-288

FCA US LLC

-
10. From the PCM tab, select the PCM flash part number. Read the flash special instructions page. Select **"OK"** to continue.
 11. From the flash ECU agreement page, agree to terms by checking the box.
 12. Select **"Flash ECU"** and then follow the wiTECH screen instructions to complete the flash.
 13. Confirm the software is at the latest available calibration level.
 14. Click **"View DTCs"**, select **"Clear All DTCs"**, click **"Continue"** and then click **"Close"**.
 15. Place the ignition in the **"OFF"** position and then remove the wiTECH MDP device from the vehicle.
 16. Remove the battery charger from the vehicle.

SERVICE PROCEDURE

B. PCM wiTECH Routine (Diesel Engines Only)

NOTE: The wiTECH scan tool must be used to perform this recall. If the reprogramming flash for the PCM is aborted or interrupted, repeat the procedure.

1. Open the hood. Install a battery charger and verify that the charging rate provides 13.0 to 13.5 volts. Do not allow the charger to time out during the flash process. Set the battery charger timer (if so equipped) to continuous charge.

NOTE: Use an accurate stand-alone voltmeter. The battery charger volt meter may not be sufficiently accurate. Voltages outside of the specified range will cause an unsuccessful flash. If voltage reading is too high, apply an electrical load by activating the park or headlamps and/or HVAC blower motor to lower the voltage.

2. Connect the wiTECH MDP to the vehicle data link connector.
3. Place the ignition in the **“RUN”** position.
4. Open the wiTECH 2.0 website.
5. Enter your **“User id”** and **“Password”** and your **“Dealer Code”**, then select **“Sign In”** at the bottom of the screen. Click **“Accept”**.
6. From the **“Vehicle Selection”** screen, select the vehicle to be updated.
7. From the **“Action Items”** screen, **“Topology”** tab, select the **“PCM”**.
8. From the **“PCM”** screen, select the **“Miscellaneous Functions”** tab.
9. From the list, select **“PCM Configuration”** and follow on-screen prompts.
10. When completed, the **“PCM Configured Successfully”** message will appear.



Figure 1 – PCM Configured Successfully

11. Click **“View DTCs”**, select **“Clear All DTCs”**, click **“Continue”** and then click **“Close”**.
12. Place the ignition in the **“OFF”** position and then remove the wiTECH MDP device from the vehicle.
13. Remove the battery charger from the vehicle.