

ATTENTION:

GENERAL MANAGER ☐

PARTS MANAGER ☐

CLAIMS PERSONNEL ☐

SERVICE MANAGER ☐

IMPORTANT - All Service Personnel Should Read and Initial in the boxes provided, right.

© 2026 Subaru of America, Inc. All rights reserved.



SUBARU

QUALITY DRIVEN® SERVICE

PRODUCT CAMPAIGN BULLETIN

APPLICABILITY: 2026MY Forester

NUMBER: WRF-26

SUBJECT: Safety Recall and Stop Sale: Forester
Power Moonroof Glass Adhesion

DATE: 05/28/26

NHTSA ID: TBD

Subaru of America, Inc. (Subaru) has initiated a safety recall for certain 2026 model year Forester vehicles equipped with a power moonroof assembly.

DESCRIPTION OF THE DEFECT AND SAFETY RISK:

The affected vehicles may have been manufactured with power moonroof assemblies in which the glass panel has been improperly bonded to the sliding frame. Over time, the bonding adhesion between the glass panel and the sliding frame may deteriorate and the moonroof glass may become detached during usage of the vehicle.

If the glass panel were to separate from the vehicle, a displaced panel could increase the risk of a potential crash or injury for other road users.

REMEDY

For all potentially affected vehicles, Subaru dealers will inspect the power moonroof glass panel for proper adhesion and, if necessary, replace the glass panel assembly at no cost to the customer.

AFFECTED VEHICLES

A total of 69,663 U.S. vehicles will be included in this safety recall as listed below. Not all vehicles in the production range listed are affected by this recall. Coverage must be confirmed by using the Vehicle Coverage Inquiry function on subarunet.com prior to repair.

Model Year	Carline	Production Date Range
2026	Forester	June 19, 2025 – March 17, 2026

CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

Subaru of America, Inc. is ISO 14001 Compliant

ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.

Continued...

RETAILER RESPONSIBILITY

Please be advised that it is a violation of Federal law for a dealer to deliver a new motor vehicle covered by a recall under a sale or lease until the defect is remedied. Therefore, any Authorized Subaru Retailer failing to perform the applicable service procedures to correct all affected vehicles in their inventory prior to the vehicle being placed in service may be subject to civil penalties of up to \$27,874 per violation (i.e., for each vehicle), as provided in 49 CFR §578.6 and will also be in breach of the Subaru Dealer Agreement.

Any vehicles listed in any recall/campaign that are in retailer stock must be:

- Immediately identified
- Tagged or otherwise marked to prevent their delivery or use prior to repair
- Repaired in accordance with the repair procedures outlined in the Product Campaign Bulletin

Retailers are to promptly perform the applicable service procedures, to correct all affected vehicles in their inventory (used, demo & SSLP). Whenever a vehicle subject to this recall is taken into retailer inventory necessary steps should be taken to ensure the recall correction has been made before selling or releasing the vehicle.

OWNER NOTIFICATION


Subaru will notify affected vehicle owners by first class mail within 60 days. Retailers will be advised when owner notification is scheduled.

PART INFORMATION:

Part Description	Part Number	Qty	Image
LID ASSY (Lid Assembly-Sunroof)	65430SL00A	1	
Screw	65482SL00A	6	




Continued...

SERVICE PROCEDURE FLOW CHART:




Continued...

REQUIRED TOOLS & MATERIALS:

Description	Image	Details
General Tools		
Torque wrench		Check Tightening Torque
Protective Tape		For Protecting Roof Panels
L-Shaped Pick Tool		For Removing the Lid Covers
T25 Torx Bit Socket		Removal and reinstallation of the Lid Assembly-Sunroof hardware
Flashlight		For Visual Inspection of Primer
Clean Shop Towel		Used as a Spacer for Height Adjustment of the Lid Assembly-Sunroof

Continued...

COMPONENT CONFIGURATION:



Continued...

SERVICE PROCEDURE / INFORMATION:


Step 1: Sunroof Assembly – Inspection

IMPORTANT NOTE: This document refers to “GLASS FRITS.” Glass Frits are the baked-on, ceramic-based black enamel bands and fading dot-matrix patterns found around the edges of the sunroof glass.

1.1 Fully close the sunroof assembly, open the sunshade.




1.2 Remove both right- and left-hand lower portions of the lid covers by inserting a L-shaped pick tool and pulling horizontally toward the inside of the vehicle. The upper portion of the lid cover can remain attached.



Continued...

1.3 Temporarily secure the lid covers to the glass with protective tape.



1.4 Visually inspect all six mounting brackets shown in the diagram below. Inspect to ensure all brackets have black primer and grey glass frit. If only grey frits are found on any of the brackets, proceed to step 2, sunroof assembly replacement. If primer and grey frits are found on all 6 brackets, reinstall the lower lid covers, and the procedure is complete.

JUDGEMENT CRITERIA	
Is primer applied at all six inspection locations?	
OK (Primer Applied)	NG (No Primer Applied)
①Example: Primer Applied ②Example: Primer Applied Gray area = Glass frit Black area = Primer Gray area = Glass frit Black area = Primer (Example where primer is visible at the glass edge)	Example: No Primer Applied All gray areas = Glass frit only
Results	
OK	Since the lid assembly-sunroof is acceptable, reinstall the lid covers. This completes the procedure.
NG	If primer is not applied to one or more of the six inspection locations, the part is considered defective. Proceed to step 2.

Continued...

Step 2: Sunroof Lid Assembly Replacement


2.1 Apply protective tape to the body of the vehicle to prevent scratches while handling the sunroof lid assembly.




2.2 Insert an L-shaped pick tool into the upper portion of both lid covers as shown below. Pull down diagonally.

Caution:

DO NOT pull on the pleated portion of the lid cover. Doing so will damage the covers; always disengage the covers at the mounting point.



2.3 Remove all six T25 bolts and discard.




Continued...

2.4 Remove sunroof lid assembly.

Caution:


The sunroof lid assembly is VERY HEAVY. To prevent injury or damage to the vehicle, always handle and carry sunroof lid assembly carefully.



2.5 Install NEW sunroof lid assembly.

Caution:

- DO NOT handle the sunroof lid assembly from the rear section. Grabbing or bending the rear section will cause deformation and/or separation from the glass.
- Handle the assembly with care.




Continued...



2.6 Adjust the height of the sunroof lid assembly by inserting **CLEAN** shop towels as shown in the diagram below. Adjust the towels until the glass is within **1.3mm +/- 1mm (0.05 +/- 0.04in)** of the roof line.




Continued...



2.7 Install six NEW T25 bolts and torque to: **4.5 N·m (3.3 ft-lbs)**



2.8 Confirm sunroof lid assembly is still within **1.3mm +/- 1mm (0.05 +/- 0.04in)** of the roof line. Remove the towels supporting the sunroof lid assembly. Check to ensure the sunroof opens and closes without binding.



Continued...

2.9 Install lid covers, press in until the cover has fully engaged support.

Caution:

It is possible to install lid covers upside down. Confirm orientation with the image below.



Step 3: Perform Sunroof Initialization

Note: Ensure that position learning is performed first. Sliding position learning cannot be performed unless the position learning is complete.

3.1 Close the sunroof completely. Press and hold the close switch until you hear the glass reach its mechanical lock position (approximately 10 seconds), then release the switch.

3.2 Within 6 seconds of completing Step 3.1, press and hold the close switch again. Continue holding until the sunroof moves to the fully open position, and finally back to the fully closed position. Once it returns fully closed, release the switch.

3.3 Turn the ignition switch off to complete initialization. Then turn the ignition back on and test the sunroof operation.

Note: When opening the sunroof, it will open and then stop slightly before reaching the fully open position. This feature is designed to reduce wind noise. Press the open button again to fully open the sunroof. For more details, see page 166 of the owner's manual.

SERVICE PROGRAM IDENTIFICATION LABEL:

Type or print the necessary information on a Campaign Identification Label. The completed label should be attached to the vehicle's upper radiator support. Additional labels are available through normal parts ordering channels. The part number is MSA6P1302, which comes as one sheet of 20 labels.

Part Number	Applicability	Description	Order Quantity
MSA6P1302	All Models	Campaign Identification Label (contains one sheet of 20 labels)	1

Continued...

CLAIM REIMBURSEMENT AND ENTRY PROCEDURES:

Credit to perform this recall will be based on properly completed repair order information. Retailers may submit claims through Subarunet.com.

An NQR with fail code WRF, accompanied by photographic evidence demonstrating the absence of primer, must be submitted to support each recall claim in which a Technician determines that sunroof replacement is necessary. Failure to comply with this NQR requirement may result in rejection of the claim.

Claim Type	Labor Description	Labor Operation #	Labor Time	Fail Code
RC	Inspection of the Lid Assembly-Sunroof	A100900	.2	WRF-26
	Inspection and Replacement of the Lid Assembly*-Sunroof	A100918	.5	

*For this recall, Lid Assembly replacement is only covered in the case of missing primer as outlined in the procedures. Any other concerns identified as a result of inspection must be addressed outside of this recall.

IMPORTANT REMINDERS:

- SOA strongly discourages the printing and/or local storage of service information as previously released information and electronic publications may be updated at any time.
- Always check for any open recalls or campaigns anytime a vehicle is in for servicing.
- Always refer to STIS for the latest service information before performing any repairs.