

Recall:	26V-446 NHTSA / 2026-336 TC	Product:	Airxcel MaxxAir Roof Ventilation Fan
Companion Recall:	Airxcel (RV Products) 26E-036	Repair Time:	0.30 h insp. / 0.50 h insp.+ repl.

Purpose

This document accompanies **NHTSA Safety Recall 26V-446/TC safety recall 2026-336**, a companion to Airxcel (RV Products) Equipment Recall 26E-036. The repair procedure for this recall is the attached Airxcel document, “RV Products Recall 26E-036 Inspection and Repair Procedure.” Perform the repair exactly as described in that document. This claim preparation document provides the GDRV-specific claim coding, pre-authorization requirements, and supplementary references for the repair.

Safety

This document provides general instructions. Many variables can change the circumstances of any procedure, including the degree of difficulty involved and the ability level of the individual performing the operation. If the skill level required is too advanced or the procedure too difficult, a certified technician should be consulted before performing the operation. Failure to correctly install, remove, or service the system may result in voiding the warranty, inflicting injury, or even death.

WARNING

The “WARNING” symbol indicates a procedure has a safety risk involved and may cause death, serious personal injury, or severe product and/or property damage if not performed safely and within the parameters set forth in this document.

CAUTION

The “CAUTION” symbol indicates a procedure that has a safety risk involved and may cause personal injury or product and/or property damage if not performed safely and within the parameters set forth in this document.

WARNING

Electric shock hazard. Before working on any installed fan, disconnect all power or turn off the associated breaker.

CAUTION

Ensure task-appropriate personal protective equipment (PPE) is worn at all times during this procedure.

Affected Units

This procedure applies to Grand Design RV units within the NHTSA Safety Recall **26V-446/TC safety recall 2026-336** population that were factory-equipped with an Airxcel (RV Products) MaxxAir roof ventilation fan containing an affected control board.

Affected models: 2026-2027 Grand Design Lineage

Affected component build dates: Control boards built December 15, 2025 – June 17, 2026; installed in fans built January 5, 2026 – June 26, 2026.

Affected Airxcel part numbers: 00-08950N, 00-08900N (MaxxFan DLX)

Affected VIN/SN:

Identifying configuration: Fan serial number (beneath the intake screen) in the format #####-#####N-#### or #####-#####NX-####, with a PCB date code within the affected range.

Mercedes – Benz (25FW/25TK) 1/13/26 – 6/25/26

Start Vin/Serial	End VIN/Serial
W1X9N33Y3SN343418	W1X9N33Y1TT600167
MM2613TFF01167	MM2613VFF01576

Ford Transit (LVT1/LVT2) 1/23/26 – 6/26/26

Start Vin/Serial	End VIN/Serial
1FDBF6XG3RKB74462	1FDBF6XG4SKB31464
TV213BTÉE00243	TV213BTÉE00249

Ford (29AN/30DC/31ZW/31ZW5) 1/14/26 – 6/24/26

Start Vin/Serial	End VIN/Serial
1FDFF6LTXSDA17591	1FDFF6LTXSDA17476
FF3428TFF01244	MM2613VFF01576

Ram (LVP1/LVP2) 3/11/26 – 6/23/26

Start Vin/Serial	End VIN/Serial
3C6MRVSG9TE167197	3C6MRVSG0TE181067
DV214CTÉE00262	DV214CVÉE00393
3C6MRVSG0TE184213	3C6MRVSG0TE181070
AV214CVÉE00396	AV214CVÉE00417

Claim Information

Submit a warranty claim pre-authorization request using the following codes and labor times.

Operation Code	M910063	Fault Code	Recall
----------------	---------	------------	--------

Approved Time	0.30 h (inspection) / 0.20 h (PCB replacement)
Pre-Auth Required	Yes — Inspection only claim: the following photos are required, photo of serial number tag, photo of PCB with approved date code showing. Photo of “QUAL INSP” sticker installed by SN tag on fan. PCB replacement photos required: Inspection photos plus photo of new boards date code, photo of replace board destroyed (physical damage must be present in photo).

Promptly submit all pre-authorizations and claims through the Dealer Portal. For assistance, contact the Dealer Relations Team at 888-825-2820.

Resources Required

Refer to the attached Airxcel 26E-036 procedure for full detail. Key tools and materials include:

- Phillips screwdriver
- Side cutters (to remove the wiring zip tie)
- Camera / phone for required documentation photos
- Validated replacement control board (in-range units only)
- Provided “QUAL INSP” verification stickers
- Task-appropriate personal protective equipment (PPE)

Required Components

Callout	Part #	Qty	Description
PCB	810930	1	Validated MaxxFan control board – in-range units only; obtain from Airxcel (RV Products) – will come with required stickers

**Replacement control boards and verification stickers are supplied by Airxcel (RV Products).*

Pre-Authorization Documentation

The following documentation must be submitted with the pre-authorization or claim for payment:

- Photo of the PCB date code.
- Photo of a legible serial-number label.
- Photo of the unit VIN tag.

Instructions

NOTE

The repair procedure is contained in the attached Airxcel document “RV Products Recall 26E-036 Inspection and Repair Procedure” (dated June 25, 2026). Perform the repair exactly as described in that document. Do not deviate from the Airxcel procedure.

Key parameters from the Airxcel procedure are reproduced below for quick reference. The attached Airxcel document governs in all cases.

- Disconnect power (or turn off the breaker) and wear PPE before working on the fan.
- Remove the intake screen (four lock-in tabs); record the fan serial number located beneath the screen.
- Remove the four fan-face screws and the one handle screw; remove the fan face.
- **Photograph the PCB with the date code visible** and record the date code.
- Decision point — if the date code is outside the affected range, or in range but bearing a “QC Pass” sticker: reassemble, apply a “QUAL INSP” sticker to the fan control plate, photograph, and stop (inspection only). If within the affected range, replace the board.
- To replace: remove the two PCB screws, disconnect wiring at all three points, cut the zip tie, **destroy and photograph the removed board**, then install the validated board with the same screws, reattach wiring, and replace the zip tie.
- Reassemble the fan; apply a “QUAL INSP” sticker to the right of the rain-sensor sticker.
- **Photograph the reassembled fan showing the sticker and a legible serial label**; run the fan to validate all connections.

Required for Claim Payment

Photos required:

- Photo of serial number tag on MaxxFan
- Photo of Qual inspection sticker as indicated on Airxcel’s instructions
- If PCB is replaced, photo of date code on NEW board is required
- If PCB is destroyed, photo of destroyed board is required
- Photo of VIN tag on motorhome

Lack of photos may delay or prevent payment of claim.

June 25, 2026

RV Products Recall 26E-036

Inspection and Repair Procedure

Flat Rate Charges

- Inspection only – 0.25 of an hour
- Inspection and Repair – 0.50 of an hour

Inspection Instructions

- Record vehicle identification number (VIN)
- Prior to working on any installed fan, make sure that all power is disconnected or the associated breaker is turned off to avoid potential electric shock.
- Additionally, ensure that proper PPE is worn at all times during the process.
- Remove screen on fan by twisting four lock-in tabs:



- Record the fan serial number. The location of this is underneath the screen and will contain the format #####-#####N-##### or #####-#####NX-#####.
 - Example: 2601-4900N-1234

- Remove 4 screws in fan face and 1 in handle:



- Remove fan face
- Photograph PC board with date code visible:



- Record the date code from the PCB which is in the location circled in the above image.
- If the date code is outside of the identified recall range or the date code is in range but contains a “QC Pass” sticker:
 - Re-assemble fan following the prior steps in reverse.
 - Place provided “QUAL INSP” sticker in the corner of the fan control plate (placement shown below with green arrow)



- Photograph reassembled fan with sticker in place
- If the PCB date code is within the recall range, continue to the following steps

Repair Instructions

- Remove two screws from PCB



- Disconnect wiring, (3) places



- Carefully cut and remove zip tie on wiring
- Destroy then photograph the destroyed PCB.
- Replace the PCB by securing the new validated PCB to the control panel using the same screws that were removed before.
 - Reattach wires and replace zip tie

- Re-assemble the fan
 - Place provided “QUAL INSP” sticker to the right of rain the sensor sticker (placement shown below with green arrow)



- Photograph reassembled fan with sticker in place and the serial number label visible and clear enough to read.
- Run a test on the fan to validate connections are made properly.

Service

For any questions, please reach out to the RVP service department using the contact information below:

RVP, A division of Airxcel
Service Department
3050 North Saint Francis Street
Wichita, Kansas 67219
574-247-9235 (Option 1)