

CSC-10026086-7590



CHRYSLER

**CUSTOMER SATISFACTION NOTIFICATION H20
RECONFIGURE FRONT CONTROL MODULE**

Dear: (Name)

Customer satisfaction is very important to Chrysler. Accordingly, we are recommending the following service on some **2008 and 2009 model year Dodge Dakota trucks that are not equipped with the Trailer Tow Group option.**

The problem is... The 4-way electrical connector for trailer lights on your truck (VIN: xxxxxxxxxxxxxxxxxxxx) may not function properly due to an improperly configured Front Control Module (FCM).

What your dealer will do... Chrysler will repair your vehicle free of charge (parts and labor). To do this, your dealer will reconfigure your vehicle's FCM. The work will take about ½ hour to complete. However, additional time may be necessary depending on service schedules.

What you must do... Simply **contact your dealer** right away to schedule a service appointment. **Remember to bring this letter with you to your dealer.**

If you need help... If you have questions or concerns which your dealer is unable to resolve, please contact Chrysler at 1-800-853-1403.

Please help us update our records, by filling out the attached prepaid postcard, if any of the conditions listed on the card apply to you or your vehicle.

If you have already experienced this condition and have paid to have it repaired, you may send your original receipts and/or other adequate proof of payment to the following address for reimbursement: Chrysler Customer Assistance, P.O. Box 21-8007, Auburn Hills, MI 48321-8007, Attention: Reimbursement.

We're sorry for any inconvenience, but we believe that this service will help to ensure your continuing satisfaction with your vehicle. Thank you for your attention to this important matter.

Customer Services Field Operations
Chrysler
Notification Code H20
(Revised)

*Buckle up
for Safety!*