

#### Service **Technical Information** 29/12 ENU WC23

### WC23 - Replacing Vacuum Pump (Workshop Campaign)

Vehicle Type: Panamera/Panamera 4

Model Year: As of 2011 up to 2012

Concerns: Vacuum pump

Information: This is to inform you of a voluntary Workshop Campaign on the above-mentioned vehicles.

There is a possibility that the elastomer check valve in the additional outlet on the vacuum

pump can become damaged over the service life of the vehicle.

As a result, the vacuum supplied to the secondary loads may not be sufficient.

This can cause malfunctions in the variable intake system. The lack of vacuum can also result in a fault entry during tank leakage diagnosis in the DME and can cause the Check Engine light to come on.

Action Replace vacuum pump.

Required: Also check the area on the vacuum unit for the intake-air distributor switching mechanism for traces of oil.

If there are traces of oil on the vacuum unit or on the intake-air distributor switching mechanism, the

seals for the coolant regulator housing must also be replaced in addition to the vacuum pump.

Affected

The VIN(s) can be checked by using PIWIS Vehicle Information link to verify if the campaign affects the Vehicles: vehicle. This campaign is scope specific to the VIN! Failure to verify in PIWIS may result in an improper

repair. This campaign affects 3,036 vehicles in North America.

**NOTE:** All parts for Scope 2 and all parts for Scope 3 will be automatically allocated to your dealership Parts Info:

with the exception of the following, which should be readily available at your dealership:

000.043.301.47 Antifreeze 000.043.301.19 Engine Oil

000.043.205.93 Klüberplus S06 - 100 grease

000.043.204.68 Grease WC23000001 Engine oil

Scope 1: Not valid for your market.

Scope 2: Replacing vacuum pump:

1		Service			
4	WC23	ENU 29/12			

# **Technical Information**

000.043.207.89	⇒ Vacuum pump	1
000.043.301.47	⇒ Antifreeze	1-liter container (As much as required, approx. 200 ml per vehicle)
000.043.301.19	⇒ Engine oil	1-liter container (As much as required, approx. 100 ml per vehicle)

## Scope 3: Replacing vacuum pump and seals on coolant regulator housing:

000.043.207.89	$\Rightarrow$ Vacuum pump	1
000.043.301.47	⇒ Antifreeze	1-liter container (As much as required, approx. 200 ml per vehicle)
In addition:		
948.106.124.01	⇒ Seal for coolant regulator housing	2
948.107.437.20	⇒ Seal for oil separator	1
948.107.438.20	⇒ Seal for oil separator	1
946.110.146.02	⇒ Seal for intake-air distributor	6
948.106.533.00	⇒ Seal for coolant pump	1
999.707.477.40	$\Rightarrow$ 0-ring, 19 x 3 for coolant pipe	2
999.701.825.40	$\Rightarrow$ 0-ring, 19.6 x 3.53 for coolant pipe	1
999.707.586.40	$\Rightarrow$ 0-ring, 11 x 2.5 for vent line	2
948.106.707.00	$\Rightarrow$ 0-ring, 62.86 x 5.33 for thermostat insert	2
000.043.205.93	⇒ Klüberplus S06–100 grease	100g tube (As much as required, approx. 1 gram per vehicle)
000.043.204.68	⇒Grease	50g tube (As much as required, approx. 1 gram per vehicle)

# **Technical Information**

Service

29/12 ENU WC23

4

WC230000001

 $\Rightarrow$  Engine oil

1 unit

Corresponds to a maximum quantity of 1.25 liters – for warranty invoicing only\*. The actual quantity required depends on the engine-oil refill quantity determined using the PIWIS Tester.

Special Tools: Nr.90 Pos.3 - Torque wrench

9818 - PIWIS Tester II

Work

See Attachment "A".

Procedure:

Claim See Attachment "B".

Submission:

#### Attachment "A": Work Procedure

1 Remove vacuum pump ⇒ Workshop Manual '477619 Removing and installing vacuum pump'



#### Information

If a vacuum pump is damaged, engine oil can leak out of the vacuum pump through an adjacent duct and get into the vacuum unit for the intake-air distributor switching mechanism and can then leak out of the vacuum unit via the linkage.

The oil can move forward towards the coolant regulator housing on the underside of the intake-air distributor or via various lines routed in this area on the engine and can then be deposited heavily in this area.

The build-up of oil can cause the seals on the coolant regulator housing to swell and coolant can then start leaking out.

<sup>\*</sup> The WWS Warranty system will automatically add into the "Miscellaneous item" section (sublet) of the claim after the claim has been submitted.

2 Check the area on the vacuum unit ⇒ Figure 1-1for the intake-air distributor switching mechanism next to the vacuum pump ⇒ Figure 1-2- for traces of leaking engine oil ⇒ Figure 1-arrow-.



Figure 1

3 If the vacuum unit ⇒ Figure 2-1- or intake-air distributor switching mechanism ⇒ Figure 2-item 2- as shown in ⇒ Figure 2-arrow- has visible traces of oil, ⇒ continue with Step 4 and first replace both seals on the coolant regulator housing (Scope 3).

If there are no traces of oil on the vacuum unit and on the intake-air distributor switching mechanism, ⇒ continue with Step 5 and install a new vacuum pump (Scope 2).



#### Information

If there are **traces of oil** on the vacuum unit or on the intake-air distributor switching mechanism, in addition to replacing the seals on the coolant regulator housing, **all** components of the vacuum system for the secondary loads (vacuum lines, connections, switching valves) must be checked for **oil leaks**. Vacuum system components that are contaminated with oil must be **replaced**.

The working time and spare parts needed are to be invoiced using a **separate warranty claim**.



Figure 2

- The additional warranty claim must be processed by specifying ⇒ damage code 4776 97 000, repair code 1.
- Document the work in the PQIS job by entering 4776 (brake booster vacuum pump) under "Location" and 9735 (Repair in accordance with PAG instructions) as the "Symptom".
- Specify that the repairs were carried out due to campaign WC23 under "Further Information" on the PQIS job.
- 4 Replace seals on the coolant regulator housing.

- 4.1 Remove coolant regulator housing ⇒ Workshop Manual '195519 Removing and installing coolant regulator housing'
- 4.2 Carefully **clean** components and lines soiled with engine oil.
- 4.3 **Both seals**  $\Rightarrow$  *Figure 3-4-* on the coolant regulator housing  $\Rightarrow$  *Figure 3-1-* must be replaced.




Figure 3

- 4.4 Install coolant regulator housing ⇒ Workshop Manual '195519 Removing and installing coolant regulator housing'.
- Install new vacuum pump  $\Rightarrow$  Workshop Manual '477619 Removing and installing vacuum pump'.
- 6 Check engine-oil level and correct it if necessary ⇒ Workshop Manual '170101 Checking engine-oil level'.
- 7 Enter the workshop campaign in the Warranty and Maintenance booklet.

#### Attachment "B": Claim Submission - Workshop Campaign WC23

Warranty claims should be submitted via WWS/PQIS.

Open campaigns may be checked by using either the PIWIS Vehicle Information system or through PQIS Job Creation.

Labor, parts, and sublet will be automatically inserted when Technician is selected in WWS/PQIS. If necessary, the required part numbers will need to be manually entered into warranty system by the dealer administrator.

Scope 1: Not valid for the North American market.

Scope 2: Replacing vacuum pump and checking intake-air distributor for oil leaks.

# 4

## Service

WC23 ENU 29/12

# **Technical Information**



#### Information

Scope 2 must be invoiced if there are **no traces of oil** on the vacuum unit and on the intake-air distributor switching mechanism and as a result, **only the vacuum pump must be replaced**.

#### Working time:

Replacing vacuum pump Labor time: 209 TU

Includes: Removing and installing cowl panel cover

Removing and installing plenum panel cover Removing and installing wiper linkage Removing and installing cross panel

Checking intake-air distributor for traces of oil

#### Parts required:

000.043.207.89 Vacuum pump 1

 000.043.301.47
 Antifreeze, 1-liter container
 0.2 ea.

 000.043.301.19
 Engine oil, 1-liter container
 0.1 ea.

⇒ Damage code WC23 066 000 2

#### Scope 3:

#### Replacing vacuum pump and seals on coolant regulator housing.



#### Information

Scope 3 must be invoiced if there are **traces of oil** on the vacuum unit and/or on the intake-air distributor switching mechanism and as a result, **the seals on the coolant regulator housing must also be replaced in addition to the vacuum pump**.

#### Working time:

Replacing vacuum pump and seals on coolant regulator housing

Includes: Removing and installing cowl panel cover

Removing and installing plenum panel cover Removing and installing wiper linkage Removing and installing cross panel Checking intake-air distributor for traces of oil

Removing and installing intake-air distributor
Removing and installing coolant regulator housing

#### Parts required:

000.043.207.89 Vacuum pump 1

000.043.301.47 Antifreeze, 1-liter container 0.2 ea.

948.106.124.01 Seal 2

Labor time: 442 TU

Technical Information	Service	1
	29/12 ENU WC23	4

948.107.437.20	Seal	1
948.107.438.20	Seal	1
946.110.146.02	Seal	6
948.106.533.00	Seal	1
999.707.477.40	O-ring, 19 x 3	2
999.701.825.40	O-ring, 19.6 x 3.53	1
999.707.586.40	O-ring, 11 x 2.5	2
948.106.707.00	O-ring, 62.86 x 5.33	2
000.043.205.93	Klüberplus S06–100 grease	0.01 ea.
000.043.204.68	Grease	0.02 ea.
WC23000001	Engine oil	1 unit Corresponds to a maximum quantity of 1.25 liters – for warranty invoicing only*. The actual quantity required depends on the engine-oil refill quantity determined using the PIWIS Tester.

<sup>\*</sup> The WWS Warranty system will automatically add into the "Miscellaneous item" section (sublet) of the claim after the claim has been submitted.

#### ⇒ Damage code WC23 066 000 2

#### References:

- ⇒ Workshop Manual '477619 Removing and installing vacuum pump'
- ⇒ Workshop Manual '195519 Removing and installing coolant regulator housing'
- ⇒ Workshop Manual '195819 Removing and installing coolant regulator (thermostat insert)'
- ⇒ Workshop Manual '170101 Checking engine-oil level'

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. If a particular condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your authorized Porsche Dealer for the latest information about whether a particular technical bulletin applies to your vehicle. Part numbers listed in these bulletins are for reference only. Always check with your authorized Porsche dealer to verify the current and correct part numbers. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

Dealership	Service Manager	 Shop Foreman	 Service Technician	 	 
Distribution		14/ 1 4 1 1	C . T		
Routing	Asst. Manager	 Warranty Admin.	 Service Technician	 	 

Dr. Ing. h.c. F. Porsche AG is the owner of numerous trademarks, both registered and unregistered, including without limitation the Porsche Crest®, Porsche®, Boxster®, Carrera®, Cayenne®, Cayenne®, Porsche®, Boxster®, Cayenne®, Cayenne®, Porsche®, Porsche®, Boxster®, Cayenne®, Porsche®, Porsche®